



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001



No F 6 / DFS / MS / 2023 /Hospital/ 495

Dated 18/10/2023

FIRE SAFETY CERTIFICATE

Certified that the **Gupta Multi Specialty Hospital** located at **Dhandhu Ram Market, Near Main Bus Stand, Bawana, Delhi-110039** comprised of **Ground+ Three upper floors** owned/ occupied by **Gupta Multi Specialty Hospital** have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on **29.09.2023** in the presence of **Dr. D.P. Gupta** and found that the building/ premises is fit for occupancy class **Institutional "Group C"** with effect from **18/10/2023** for a period of **03 (Three) years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on **18/10/2023**..... at New Delhi by

(Atul Gang)
Director

Ph- 011-23414000

Copy to:-

1. M/s Gupta Multi Specialty Hospital, Dhandhu Ram Market, Near Main Bus Stand, Bawana, Delhi-39.
2. The Director General of Health Services, Nursing Homes Cell, 3rd Floor, DGD Building, S-1, School Block, Shakarpur, Delhi-92.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in
8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

INSPECTION REPORT

1. Name & address of the building : Gupta Multi-Speciality Hospital, Dhandu Ram Market, Near Bus Stand Bawana, Delhi-110039.
2. Type of Occupancy : Institutional-C (i)
3. Building Composition : Ground+ 03 upper floors.
4. Type of Case : New Case
5. Details of Previous NOC : Nil
6. Fire Safety directives letter No : NBC Part IV
7. Date of inspection : 29/09/2023
8. Name of Inspecting Officer : ADO (BW)
9. Name and designation of officers from the building side : Dr. D.P. Gupta
10. Year of Construction : 2011 & 2014-15
11. Applicant's Letter No. : Diary No. 5968 Dated 12/09/2023

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/UBBL	Provided at site	Remarks MR/NMR
1.	Access to building			
	• Road width	Accessible	Accessible	MR
	• Gate width	Directly accessible	Directly accessible	MR
	• Width of internal road	NA	NA	NA
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	02	03	MR
	• Basements	NA	NA	NA
	b. Width of staircases			
	• Upper Floor	2 m & 1.5 m	2 m, 1 m & 1.5 m (iron staircase)	MR
	• Basements	NA	NA	NA
	c. Protection of exits			
	• Fire check door	NA	NA	NA
	• Pressurization	NA	NA	NA
	d. No. of continuous staircases to terrace	01	Provided	MR
	e. Width of Corridor	2.40 m	Provided	MR
	f. Door Size	Patient room doors size 2 m & 1.25 m, Staircase door size 2 m & 1.5 m	Provided	MR
3.	Compartmentation			
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4.	Smoke Management System			
	• Basements	NA	NA	NA
	• Upper floors	Required	Provided	MR
5.	Fire Extinguishers			
	• Total numbers	15 nos	20 nos	MR
	• Types	ABC/Co2	Provided	MR
	• IS marking	Required	Provided	MR
6.	First-Aid Hose Reels			
	• Total numbers on each floor	01	Provided	MR
	• Length of hose reel hose	30 m	Provided	MR
	• Nozzle diameter	05 mm	Provided	MR

7.	Automatic fire detection and alarming system			MR
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power 	Required	Provided	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
	<ul style="list-style-type: none"> Hooters' Location 	Required	Provided	MR
8.	MOEFA	NA	NA	NA
9.	Public Address System			
10.	Automatic Sprinkler System			
		NA	NA	NA
	<ul style="list-style-type: none"> Basement Ground Floor Sprinkler above false ceiling 	NA	NA	NA
		NA	NA	NA
11.	Internal Hydrants			
		100 mm	Provided	MR
	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants per floor Hose Box 	01	Provided	MR
		Required	Provided	MR
12.	Yard Hydrants			
		NA	NA	NA
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	NA	NA	NA
13.	Pumping Arrangements			
	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/Manual Stopping Pump House Access 	1620 lpm	Provided	MR
		40 m	Provided	MR
		01	Provided	MR
		180 lpm	Provided	MR
		40 m	Provided	MR
		1620 lpm	Provided	MR
		40 m	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
	<ul style="list-style-type: none"> Terrace level <ul style="list-style-type: none"> Discharge of pump Head of the pump Power Supply Auto Starting of pump 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
14.	Captive Water Storage for fire fighting			
	<ul style="list-style-type: none"> Underground tank capacity <ul style="list-style-type: none"> Draw-off connection Fire service inlet Access to tank Overhead Tank capacity 	50,000 ltrs	Provided	MR
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		5000 ltrs	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	<ul style="list-style-type: none"> Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	NA	NA	NA
		NA	NA	NA
		Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area.	Required	Provided	MR
	<ul style="list-style-type: none"> Total Area 	NA	NA	NA

19.	Fire Control Room			
	• Detector System Panel	NA	NA	NA
	• Flow Switch Panel	NA	NA	NA
	• PA System Panel	NA	NA	NA
	• Battery backup	NA	NA	NA
	• Building Floor Plans	NA	NA	NA
20.	Special Fire Protection System for Protection of special Risks, if any:	NA	NA	NA

Accordingly, the fire protection systems provided in the building were tested/ checked and found functional at the time of inspection. The management had rectified the shortcomings issued vide letter number F6/DFS/MS/Hospital/2023/WZ/1497 dated 18/07/2023.

Keeping in view of substantial compliance of the minimum standards on fire prevention and fire safety requirements under the rules it is recommended to grant Fire Safety Certificate under rule 33 of Delhi Fire Service Rules 2010.

ADO (BW)
5/10/23

~~DCFO (WZ)~~

Signature of Inspecting Officer
Name : Rajeev Kumar Sinha
Designation : ADO (BW)

181
Dated: 9/10/2023

~~9/10~~

~~cfp 10/10/2022~~

~~Director~~

~~11/10/23
DLFO/WZ~~

~~Asst Dir~~ Sir, F.T letter is put up direct please

ADO (BW)
13/10/23

~~Director (DB)~~
10/10/23

n