



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/EH/SZ/2023/ 317

Dated: 26/10 /2023

## FIRE SAFETY CERTIFICATE

Certified that M/s OPHELIA (A unit of Ayesha Hospitality Pvt. Limited) located at 50-B, Ground Floor, The Ashoka Hotel, Diplomatic Enclave, Chanakyapuri, New Delhi-110021, comprised of Ground plus 07 upper floors but the restaurant running at ground floor only, owned/occupied by M/s OPHELIA (A unit of Ayesha Hospitality Pvt. Limited) was granted Fire Safety Certificate by this department vide letter No. No. F.6/DFS/MS/ED/SZ/2020/151 dated 04/11/2020. The premise was re-inspected by the officer concerned of this department on 17/10/2023 in the presence of Mr. Raj and found that the said eating house at ground floor only have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class "Group-D Assembly Building" as above with effect from 26/16/2023 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS Rules, 2010.

Issued on 26/10/2027 at New Delhi by

DÎNGCTOR DELHI FIRE SERVICE

## Copy to:-

- The Medical Officer of Health, New Delhi Municipal Council, Palika Kendra, New Delhi (W.r.t. MHA ID No. 2023101017065 dated 10.10.2023)
- 2. Authorized Signatory, M/s OPHELIA (A unit of Ayesha Hospitality Pvt. Ltd), 50-B, Ground Floor, The Ashoka Hotel, Diplomatic Enclave, Chanakyapuri, New Delhi-110021

## Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangement provided therein shall be maintained in good working conditions
  at all times. Any loss of life or property due to non-functional fire safety measures shall be at
  the responsibility of the management.
- 3. All the staff members must know correct method of operation of fire fighting system.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on <a href="www.dfs.Delhigovt.nic.in">www.dfs.Delhigovt.nic.in</a>
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

	INSPECT	TION REPORT			
	Name & Address of the Building	M/s Ophelia (A unit of Ayesha Hospitality Pvt. Ltd), 50-B, Ground Floor, The Ashoka Hotel, Diplomatic Enclave, Chanakyapuri, New Delhi-110021			
	Type of Occupancy	Group-D, "Assembly" (Restaurant) Ground + 07 upper floors (But restaurant is at ground			
	Building Comprised of				
	Building Comprised of				
	T	floor only). Renewal			
	Type of Case	Renewal	20/SZ/151 dated 04/11/	2020	
	Details of Previous NOC		120/32/131 dated 04/11/		
•	Fire Safety Directives Letter No	Nil			
1	Date of Inspection	17/10/2023			
8	Name of the Inspecting Officers	ADO (SJ) Santosh	Kumar	_	
9	Name & Designation of Officers	Mr. Raj			
	from the building side	10 10			
10	Year of construction	1956	1.40/10/2023	/	
11	Applicant letter / MHA Portal ID No.	ID No. 2023101017	7065 dated 10/10/2023	Remark	
\$.	Minimum standards on Fire	Existing Fire	Provided at Site	MR/NM	
No.	Prevention and Fire Safety U/R 33	Protection System		IVALUTATION	
1	Access to Building.		and the same of th	MR	
-	Road width	Required	15m	MR	
	Gate width	Required	6m	N/A	
-	Width of internal road	N/A	N/A	14/21	
	Number, width, type & arrangement	ent of exits.			
2	Number, width, type & arrangem			1	
	a) Number of Staircase	N/A	Restt. at GF only	N/A	
	> Upper floors.	N/A	N/A	N/A	
	Basement floor.	NA			
	b) Width of Staircase	N/A	Restt. at GF only	N/A	
1	> Upper floors		N/A	N/A	
1	> Basement floor	N/A	10/21		
1	c) Protection of exits		N/A	N/A	
	> Fire check door	1.07.2	27 (accycle)	N/A	
	> Pressurization	N/A	N/A	MR	
1	timens staircase to terrac	e Required	03 Nos	N/A	
	- comider	N/A	N/A	MR	
1		2m x 1.5m	2m & 1.70m (2 exits)	MIK	
1	f) Door size			N/A	
3	Compartmentation.  • Fire check door.	N/A	N/A	MR	
	Sealing of electrical shafts.	Required	Provided	N/A	
1	• Scaling of clouds	N/A	N/A	N/A	
	Fire rating of shaft door.				
	Fire rating of shaft door.  Water curtain	N/A	N/A	_	
	<ul> <li>Water curtain</li> </ul>	N/A Required	Provided Provided	MR	
	Water curtain     Fire dampers.	Required	Provided	MR	
4.	Water curtain     Fire dampers.  Smoke Management system.	Required 30 ACPH	Provided N/A	MR N/A	
4.	Water curtain     Fire dampers.  Smoke Management system.  Basement	Required	Provided	MR N/A	
	Water curtain     Fire dampers.      Smoke Management system.      Basement     Ground floor	Required 30 ACPH	N/A Exhaust fans provided	MR N/A MR	
4.	Water curtain     Fire dampers.      Smoke Management system.     Basement     Ground floor  Fire Extinguishers.	Required  30 ACPH 12 ACPH  04 Nos	N/A Exhaust fans provided  04 Nos	MR N/A MR	
	Water curtain     Fire dampers.      Smoke Management system.     Basement     Ground floor      Fire Extinguishers.     Total numbers	Required  30 ACPH 12 ACPH  04 Nos ABC/CO <sub>2</sub> /WCO <sub>2</sub>	N/A Exhaust fans provided  04 Nos ABC & WCO2	MR N/A MR MR	
	Water curtain     Fire dampers.      Smoke Management system.     Basement     Ground floor      Fire Extinguishers.     Total numbers     Types	Required  30 ACPH 12 ACPH  04 Nos ABC/CO <sub>2</sub> /WCO <sub>2</sub>	N/A Exhaust fans provided  04 Nos ABC & WCO <sub>2</sub> Provided	MR N/A MR MR MR MR	
5.	Water curtain     Fire dampers.      Smoke Management system.     Basement     Ground floor     Fire Extinguishers.     Total numbers     Types     ISI Marking	Required  30 ACPH 12 ACPH  04 Nos ABC/CO <sub>2</sub> /WCO <sub>2</sub> ISI marked Common fire-	N/A Exhaust fans provided  04 Nos ABC & WCO <sub>2</sub> Provided  fighting system for entir	MR N/A MR MR MR MR MR building	
	Water curtain     Fire dampers.      Smoke Management system.     Basement     Ground floor      Fire Extinguishers.     Total numbers     Types     ISI Marking  First Aid Hose Reels.	Required  30 ACPH 12 ACPH  04 Nos ABC/CO <sub>2</sub> /WCO <sub>2</sub> ISI marked Common fire-	N/A Exhaust fans provided  04 Nos ABC & WCO <sub>2</sub> Provided  fighting system for entire Provided	MR N/A MR MR MR MR MR MR MR MR	
5.	Water curtain     Fire dampers.      Smoke Management system.     Basement     Ground floor     Fire Extinguishers.     Total numbers     Types     ISI Marking	Required  30 ACPH 12 ACPH  04 Nos ABC/CO <sub>2</sub> /WCO <sub>2</sub> ISI marked Common fire-	N/A Exhaust fans provided  04 Nos ABC & WCO <sub>2</sub> Provided  fighting system for entir	MR N/A MR MR MR MR MR building	



7	Automatic fire detection & alarming	system.		
	Type of detectors	Smoke & Heat	Smoke & Heat	MR
	<ul> <li>Location of Main Panel</li> </ul>	Required	Ground floor	MR
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/A
	Alternate source of power	Required	Battery backup	MR
	Hooter's location	Required	Provided	MR
8	MOEFA	Required	Provided	MR MR
9	Public Address System	Required	Provided	
10	Automatic Sprinkler System	Common fire-fighting system for ent		e building
	Basement	N/A	N/A	N/A
	Ground floor.	Required	Provided	MR
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.	Common fire-fi	ghting system for entire	e building
	Size of Riser/Down-comer	200mm	Provided	MK
	Number of Hydrant per floor	01 near Restt.	Provided	MR
	Hose box.	01 near Restt.	Provided	MR
12	Yard Hydrants.	Common fire-fi	ghting system for entire	e building
14	Total number of hydrants.	Required 1	0 Nos + 19 monitors	MR
			0 Nos	MR
	Hose box.	Common fire-fi	ighting system for entire	building
13	Pumping arrangements.	Common the 1	Burne of arrest	
	Ground Level	2850 LPM	2850 LPM	MR
	> Discharge of main pump.	80m	80m	MR
	> Head of main pump.	Two	Two	MR
	<ul><li>Number of main pumps.</li><li>Jockey Pump output.</li></ul>	225 LPM	225 LPM	MR
	> Jockey Pump bead.	80m	80m	MR
	Standby Pump output.	2850 LPM	2850 LPM	MR
	Standby Pump head.	80m	80m	MR
	> Auto Starting/Manual Stopping.	Required	Provided	MR
	> Pump house access.	Required	Provided	MR
		Common fire-f	ighting system for entir	
	Terrace Level	900 LPM	900 LPM	MR
	➤ Discharge of pump.			MR
	➤ Head of pump.	40m	40m	
	➤ Power supply.	Required	Provided	MR
	> Auto starting of pump.	Required	Provided	MR
11	Captive water storage for fire fighting.	Common fire-fighting system for en		re building
14	Underground tank capacity.	4,00,000 Ltrs	Provided	MR
		Required	Provided	MR
	> Draw-off connection.	Required	Provided	MR
	➤ Fire Service Inlet.	Sec to section where of provide was the		MR
	Access to tank.	Required	Provided	
	<ul> <li>Overhead tank capacity.</li> </ul>	25,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
15 16	Provision of Lifts.		Not required	
10	The state of the s	N/A	N/A	N/A
		N/A	N/A	N/A
	<ul> <li>Pressurization of lift lobby.</li> </ul>		20027415345	N/A
	<ul> <li>Communication in lift car.</li> </ul>	N/A	N/A	
	Fireman's switch.	N/A	N/A	N/A
	7.0.	N/A	N/A	N/A
	The state of the s	Required	Provided	MR
17	Standby Power Supply	Acquires	Not required	2007/20
18	Refuge Area	NI/A	N/A	N/A
	Total area	N/A	N/A	N/A
	<ul> <li>Location</li> </ul>	N/A	I IV/A	I IN/A

Y

0	Fire Control Room.	Provided and Maintained by Hotel		Nigm
19		Required	Provided	MIK
	Detector system panel.	N/A	Provided	N/A
	Flow switch panel.	Required	Provided Provided	MR MR
	<ul> <li>PA system panel.</li> </ul>	Required		
1	Ballety Dackup.			MR
Building floor	Building floor plan.	Required	a di-michar	MR
20	Special Fire Protection System for the Protection of special Risk, if any.	Required	provided near electrical panel	

The fire protection systems provided in the building/premises were checked, tested at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F6/DFS/MS/EH/SZ/2020/151 dated 04/11/2020, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Santosh Kumar

Designation: ADO (SJ)

DO (SD)

And for your Signature Pl