



No.F6/DFS/MS/School/NDZ/2023/ 762

Dated: 26/10/2023

FIRE SAFETY CERTIFICATE

Certified that the **The Neev School**, located at **B-07 Mandawali, I.P. Extn., Patparganj, Delhi-110092**, now comprised of **Ground + 03 upper floors only** (Earlier it Ground + 01 upper floor only for which Fire Safety Certificate was issued by this department vide letter No. F6/DFS/MS/School/2016/NDZ/253 dated 12.12.2016), have complied with fire prevention & fire safety requirements in accordance with 33 of the Delhi Fire Service Rules, 2010/ NBC Part - IV and verified by the officer concerned of Fire Service on 10.10.2023 in presence of Mrs. Anshu Goel (Principal) and that the building /premises is fit for occupancy class **“Educational” (Group-B)** with effect from 26/10/2023 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 26/10/2023 at New Delhi by.


(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE
o/c (u)

Copy to:-

1. Director of Education, Udyod Sadan, Plot no.419, FIE, Patparganj Industrial Area, Delhi-110092.
2. The Principal, The Neev School, located at B-07 Mandawali, I.P. Extn., Patparganj, Delhi-110092.

Conditions for the validity of Fire Safety Certificate

1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form 'J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
2. All the means of escape shall be kept free of all the type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

19/11

INSPECTION REPORT

1	Name & address of the building	The Neev School, located at B - 07 Mandawali, I.P. Extn., Patparganj, Delhi-110092.		
2	Building is comprised of	Ground + 03 upper floors only.		
3	Type of occupancy	Educational Building		
4	Type of case	New (Alteration Of 02 + 03 floor on existing Ground + 03 upper floor)		
5	Details of previous FSC	F6/DFS/MS/School/2016/NDZ/253 dated 12.12.2016 Ground + 01 Upper Floor		
6	Fire safety directives letter no.	NBC Part -VI		
7	Date of inspection	10.10.2023		
8	Name of the inspecting officers	Yashwant Singh Meena ADO (L.N)		
9	Name of the designation of officer from the building side	Mrs. Anshu Goel (Principal)		
10	Year of construction	1996 & 2014		
11	Applicant's letter no.	Outdoor Diary No. 6107 dated -15.07.2023		
S.No	Minimum standard of fire prevention and fire safety U/R 33	NBC Part -IV requirement	Provided at site	Remarks MR/NMR
1	Access to Building:			
A	Road width	6.0 mtrs.	6.0 mtrs.	MR
B	Gate width	N/A	N/A	N/A
C	Width of internal road	N/A	N/A	N/A
2	Number, Width, Type and Arrangement of Exits:			
A	Number of staircases			
a	Upper floor	02 no.	02 nos.	MR
b	Basement	N/A	N/A	N/A
B	Width of staircases			
a	Upper floor	1.50 mtrs.	1.04 mtrs. & 1.07 mtrs	MR (Old Case)
b	Basement	N/A	N/A	N/A
C	Protection of exits			
a	Fire check door	N/A	N/A	N/A
b	Pressurization	N/A	N/A	N/A
D	No. of continuous staircases to terrace	01 no.	01 no.	MR
E	Width of corridor	1.50 mtrs.	2.50 mtrs.	MR
F	Door size	1.0 mtrs.	1.0 mtrs.	MR
3	Compartmentation:			
A	Fire check door	NA	NA	NA
B	Sealing of electrical shafts	N/A	N/A	N/A
C	Fire rating of shaft door	N/A	N/A	N/A
D	Water curtain	N/A	N/A	N/A
E	Fire dampers	N/A	N/A	N/A
4	Smoke Management System:			
A	Basement	N/A	N/A	N/A
B	Upper floor	N/A	N/A	N/A

(W) A

-N/12-

5.	Fire Extinguisher:			
A	Total numbers	08 nos.	10 nos.	MR
B	Types	CO ₂ & ABC	CO ₂ & ABC	MR
C	ISI marking	ISI Marked	Provided	MR
6	First-Aid-Hose Reel:			
A	Total numbers of each floor	01 no.	Provided	MR
B	Length of hose reel hose	30 mtrs.	Provided	MR
C	Nozzle diameter	05 mm	Provided	MR
7	Automatic Fire Detection and Alarming System:			
A	Type of detectors	N/A	N/A	N/A
B	Location of main panel	N/A	N/A	N/A
C	Location of repeater panel	N/A	N/A	N/A
D	Alternate source of power	N/A	N/A	N/A
E	Hooters	N/A	N/A	N/A
8	MOEFA:	N/A	N/A	N/A
9	Public Address System:	N/A	N/A	N/A
10	Automatic Sprinkler System:			
A	Basement	N/A	N/A	N/A
B	Upper floor	N/A	N/A	N/A
C	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants:			
A	Size of riser/down-comer	100 mm	100 mm	MR
B	Number of hydrants per floor	01 no.	01 no.	MR
C	Hose box	01 no.	01 no.	MR
12	Yard Hydrants:			
A	Total number of hydrants	N/A	N/A	N/A
B	Hose box	N/A	N/A	N/A
13	Pumping Arrangements:			
1	Ground level			
A	Discharge of main pump	N/A	N/A	N/A
B	Head of main pump	N/A	N/A	N/A
C	Number of main pumps	N/A	N/A	N/A
D	Jockey pump out put	N/A	N/A	N/A
E	Jockey pump head	N/A	N/A	N/A
F	Standby pump out put	N/A	N/A	N/A
G	Standby pump head	N/A	N/A	N/A
H	Auto starting /manual stopping	N/A	N/A	N/A
I	Pump house access	N/A	N/A	N/A
2	Terrace Level			
A	Discharge of pump	450 LPM	450 LPM	MR
B	Head of the pump	40 mtrs.	40 mtrs.	MR
C	Power supply	Required	Provided	MR
D	Auto starting of pump	Auto	Provided	MR

The Neev School, located at B-07 Mandawali, I.P. Extn., Patparganj, Delhi-110092


④ X

50/

14	Captive Water Storage for Fire Fighting:		
A	Underground tank capacity	N/A	N/A
B	Draw-off connection	N/A	N/A
C	Fire service inlet	Required	Provided
D	Access to tank	N/A	N/A
E	Overhead tank capacity	10,000 ltrs	10,000 ltrs.
		Required	Provided
15	Exit Signage:		
16	Provision of Lifts:		
A	Pressurization of lift shaft	N/A	N/A
B	Pressurization of lift lobby	N/A	N/A
C	Communication in lift car	N/A	N/A
D	Firemen's grounding switch	N/A	N/A
E	Lift signage	N/A	N/A
		Required	Provided
17	Standby Power Supply:		
18	Refuge Area:		
A	Total area	N/A	N/A
B	Location	N/A	N/A
19	Fire Control Room:		
A	Detector system panel	N/A	N/A
B	Flow switch panel	N/A	N/A
C	PA system panel	N/A	N/A
D	Battery backup	N/A	N/A
E	Building floor plans	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:		

The fire protection system was randomly checked and tested and was found functional at the time of inspection. The shortcomings issued vide letter no. F6/DFS/MS/School/2019/7683 dated 20.12.2019 by this department have been rectified by the management.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, it is recommended to grant Fire Safety Certificate under Rules 37 of Delhi Fire Service Rules 2010.


 Signature of the Inspecting Officer
 Name- Yashwant Singh Meena
 Designation- ADO (L.N)

DO (E.D)

By: C.F.O. (N&Z)

C.F.O.

19/10/23