



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

F.6/DFS/MS/EH/2023/SZ/323

Dated: 31/10 /2023

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s Dominos Pizza, located at Ground floor, 05, Nehru Place, New Delhi-110019 in the building comprised of Basement, Ground, Mezzanine plus Three upper floors owned/ occupied by Jubilant Foodworks Limited Dominos Pizza have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 17/10/2023 in the presence of Mr. Ankur (Manager) and that the premise is fit for occupancy class Group-D Assembly Building (Restaurant at Ground floor only) and validly upto 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 31 / 10 /2023 at New Delhi by

DELHI FIRE SERVICE 911

Copy to: -

1. The DHO, MCD, Public Health Department, Central Zone, Jal Vihar Lajpat Nagar, New Delhi-110024. (Ref. MHA Portal ID 2023100616885 dated 06/10/2023)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire-fighting

system.

4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-

2016), if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."



Cabo Duilding					
Name & Address of the Building	ON REPORT M/s Dominos Pizza, (Jubilant Foodworks Limited located at Ground floor, 05, Paras Cinema Nehro				
30	Place, New Delhi-110019				
Type of Occupancy	Assembly Building Restaurant at GF only				
	Basement, Ground, Mezzanine plus Three Upper Floor				
	New case				
Details of Previous NOC	Nil	and the state of t			
	UBBL-2016				
The state of the s	17/10/2023	9 65 54 D 1			
	7,000	of the first well of			
	2005	office of more than			
7 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -		2023100616885 dated 06	5/10/2023		
			Remarks		
		1 Tovided at Site	MR/NMR		
	C No F.6/DFS/M	S/Assembly/2022/SZ/Ciner	na/132 Date		
Access to Building.	022 Paras Cinem	a District Centre Nehru P	lace, Kalka		
		Provided*	MR		
	- Constants	Provided*	MR		
ALAN TARREST AND			MR		
	AT STATE OF THE ST	Tioriaca			
	exits.	Maintained by Doros	Cinama		
a. Number of Staircase		Namiained by Faras	MR		
Upper floors			MR		
Basement floor			VALUE OF THE PARTY		
b. Width of Staircase	And the second particular to the second				
Upper floors	Required		MR		
The state of the s	Required		MR		
L Sand to the Association of the	Provided &	& Maintained by Paras	Cinema		
	Required	Provided*	MR		
	N/A	As above	N/A		
	Required	Provided*	MR		
			N/A		
	5.7 = 000 V/H	5018001120	MR		
			ARRESTOR		
			MR		
		The second secon	N/A		
			N/A		
Fire rating of shaft door.					
Water curtain	2020000		N/A		
Fire dampers.	1	122WCQ51402C	N/A		
Smoke Management system.	Provided &	& Maintained by Paras			
	N/A	N/A	N/A		
	Required	Exhaust fans provided	MR		
		Political Partition 1 0:			
	06 Nos	06 Nos.	MR		
187 SEE SEEDS AND		A STATE OF THE STA	MR		
	ISI marked		MR		
			7		
First Aid Hose Reels.	Provided o	Company of the Compan			
Total numbers on each floor.	Hose Reel	One in Restaurant	MR		
		30m	MR		
 Length of hose-reel hose. 					
Length of hose-reel hose. Nozzle Diameter		5mm	MR		
Nozzle Diameter	vstem Provid	graph in the part of the	I. Salaman		
	ystem. Provid Required	5mm ed & Maintained by Pa Smoke & Heat	I. Salaman		
	Protection of exits Fire check door Width of corridor Monday existence Width of staircase Upper floors Basement floor Width of Staircase Upper floors Basement floor C. Protection of exits Fire check door Pressurization M. No. of continuous staircase to terrace Width of corridor Fire check door. Sealing of electrical shafts. Fire rating of shaft door. Water curtain	Building Comprised of Type of Case Details of Previous NOC Nil Fire Safety Directives Letter No Date of Inspection Name of the Inspecting Officers Name & Designation of Officers Name & Required & Name	Basement, Ground, Mezzanine plus Three Type of Case New c		



			27/4			
7.	Location of Main Panel	N/A	N/A Provided*	N/A		
Con les I	Location of Repeater Panel	Required	Provided*	MR		
	Alternate source of power Hooter's location	Required	Provided	MR		
8. M	OEFA	Required	Provided*	MR		
9. Pu	iblic Address System	Required	Provided*	MR		
	utomatic Sprinkler System					
	Basement	Required	Provided*	MR		
-	Upper floors	Required	Provided in Restt.	MR		
- 1	Sprinkler above false ceiling	N/A	N/A	N/A		
11. In	iternal Hydrants.	15-10-5-5	Maintained by Paras			
	Size of Riser/Down-comer	Required	Provided*	MR		
	Number of Hydrant per floor	Required	Provided*	MR		
in a las	Hose box.	Required	Provided*	MR		
12. Y	ard Hydrants.	1.071.000.000.000.000.000	Maintained by Paras	12/4/10/0		
V13437	Total number of hydrants.	Required	Provided*	MR		
0.7177	2. Hose box.	Required	Provided*	MR		
13. P	umping arrangements.	(ku)	TOVIDE	IVIK		
100	Ground Level	Provided &	Maintained by Paras	Cinema.		
nz	Discharge of main pump.	2280 LPM	Provided*			
B2	Head of main pump.	60 mtr	Provided*	MR		
	> Number of main pumps.	Two	Provided*	MR		
norter (> Jockey Pump output.	180 LPM	Provided*	MR		
10.6	> Jockey Pump head.	60 mtr	Provided*	MR		
Siphy 1	> Standby Pump output.	2280 LPM	Provided*	MR		
const.97	> Standby Pump head.	60 mtr	Provided*	MR		
(1),	Auto Starting / Manual Stopping.	Required	Provided*	MR MR		
B/	Access to pump house	Required	Provided*	MR		
mirrord 9	Terrace Level		Maintained by Paras			
Tyr	Discharge of pump.	N/A	N/A	N/A		
100	➤ Head of pump.	N/A	N/A	N/A N/A		
NA.	> Power supply.	N/A	N/A	00.000.000		
	> Auto starting of pump.	N/A	N/A	N/A		
14.	Captive water storage for Fire Fighting.		Maintained by Paras	N/A		
15/L m 2	Underground tank capacity.	75,000 Ltrs	1,00,000 ltr			
ORY D	Draw-off connection.	Required	Provided*	MR		
100	Fire Service Inlet.	Required	Provided*	MR MR		
Alie 1	Access to tank.	Required	Provided*	MR		
F 12	Overhead tank capacity.	10,000 Ltrs	Provided*			
15.	Exit Signage.	Required	Provided	MR		
	Provision of Lifts.		& Maintained by Paras	Cinama		
10	Pressurization of lift shaft.	N/A	N/A	N/A		
RB	Pressurization of lift lobby.	N/A	N/A	N/A N/A		
	Communication in lift car.	N/A	N/A	N/A N/A		
140	• Fireman's switch.	N/A	N/A	N/A		
312	Lift signage.	N/A	N/A	N/A N/A		
17	Standby Power Supply	Required	Provided (DG Set)	100000		
18.	Refuge Area	roquito	Trovided (DG Set)	MR		
nid	Total area	N/A	N/A	N/A		
Man	• Location	N/A	N/A	N/A		
19.	Fire Control Room.	Provided				
THE THE	Detector System Panel.	Required	Provided*	MR		
710	Flow Switch Panel.	Required	Provided*	MR		
71677	 PA system Panel. 	Required	Provided*	MR		





		Provided*	MR
Building floor plan 20. Special Fire Protection System for the Protection of special Risk, if any: Note: * Fire safety arrangements.	Required	Provided*	MR
	Required	Provided*	MR
	n of special Risk, if any :	n of special Risk, if any :	

Note:- * Fire safety arrangements provided and maintained by Paras Cinema Complex, Nehru place

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 650 dated 07/11/2022.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

on cont

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

1,500/11

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

сто (но)

26 07 (2023)

Directa

800 K10

As approved, F.T. letter is forthe for your

signature &

1/4

Directory My (4)

My

38/10/33 1/4/04/1