

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No: F6/DFS/MS/Hospital/WZ/2023/ 135

Dated: 09 03 9023

## FIRE SAFETY CERTIFICATE

Certified that the MGS Super Speciality Hospital, located at 35/37, Rohtak Road, West Punjabi Bagh, New Delhi - 110026, comprised of Basement + Ground + 3 Upper Floors was issued **FSC** this by department vide Letter F6/DFS/MS/HOSPITAL/2020/WZ/116 dated 26/02/2020 (for Basement + Ground + 02 upper floors only). Now the hospital management have added 3<sup>rd</sup> Floor and extended fire fighting arrangements. The premises was re inspected by the officers concerned of this department on 24/02/2022 in the presence of Sh. Dilip Singh and found that the Fire prevention and fire safety arrangements provided in the premises, found in good working condition. The premises have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class Group C (Institutional) (for basement, ground plus three upper floors) with 03 2023 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 09 03 2023 at New Delhi.

Copy to:-

 The Medical Superintendent, MGS Super Specialty Hospital, located at 35/37 Rohtak Road, West Punjabi Bagh, New Delhi – 110026.

## Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The basement shall be used as per building bye laws.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8 The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the

## INSPECTION REPORT

1. Name & address of the building : MGS Super Speciality Hospital, 35/37, Rohtak Road, West

Punjabi Bagh, New Delhi- 110026.

: Institutional (Hospital) 2. Type of Occupancy

: New (Addition of 3rd floor) Basement + Ground + 3 Upper Floors 3. Type of Case

: F6/DFS/MS/HOSPITAL/2020/WZ/116 dated 26/02/2020 4. Details of previous NOC (for Basement + Ground + 02 upper floors only)

: F6/DFS/MS/BP/93/Hospital/2006 dated 09/12/1993 for 5. Fire Safety directives letter No Basement + Ground + 02 upper floors & F6/DFS/MS/BP/2022/Hospital/605 dated 16/03/2022 for Basement + Ground + 03 upper floors.

: 24/02/2023 6. Date of inspection

7. Name of the Inspecting Officers: DO (W) & ADO (MN)

8. Name and designation of officers

: Sh. Dilip Singh from the building side

: 1991 (As Per Prev. Insp. dated 11/02/2020) 9. Year of Construction

: nil dated 03.02.2023 10. Applicant's letter No.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	BBI As	/NBC Require Per guideline d 16/03/2021	me	nt/ d	Provided at s	site	Rema MR/N	
1	Access to building		The state of the s			n '1.1	-	M	D.
	<ul><li>Road width</li><li>Gate width</li><li>Width of internal road</li></ul>		12 mts		Provided		A STORY CAN		
			5 mts		Provided		MR MR (being		
			Required		Provided		old case)		
2	Number, Width, Type & Arra	ngem	ent of Exits			21-15-16	11		
71	a. Number of staircases								
	• Upper Floors		05 stairs		Provided		MR		
	Basements	Basements		03 + 01 (ramp)		Provided		MR	
	Opper Proofs		02 mts, 1.82 mts 0.97 mts	2. 3. 4. 5.	) 2 m ) 1.8 n ) 0.97 ) 1.05 Prov Ran	ron made (G to 3 <sup>rd</sup> f ron made (G to Terr nts to 2.0 mts to 1.09 mts (GF to 3 vided 2.5, 0.97 & 1 p 1.72 mts	ok	MR MR	
				N/A Provided		MR			
			GF to 2 <sup>nd</sup> F- old case, 3 <sup>rd</sup> Floor- 2.4 mts			Provided MR (being		(being o	ng old case
	g. Door Size	15	3 <sup>rd</sup> Floor- 1.25, 1			Provided	MR (	being o	ld case
	Compartmentation.		Spinor AU			ND		N	P
	Fire check door Sealing of electrical shafts		NR		NR Provided		NR MR		
		S	Required		NR		NR		
	<ul><li>Fire Rating of shaft door</li><li>Water Curtain</li><li>Fire Dampers</li></ul>		NR		NR NR		NR NR		
			NR		NR		NR		
			NR		IVIX		INIC		

4	Smoke Management System.						
	Basements	Required	Exhaust fan Provided	MI			
	Upper floors	Required	Exhaust fan Provided	MI			
5	Fire Extinguishers	Required					
	<ul> <li>Total numbers</li> </ul>	25 nos.	Provided	MF			
	Types	CO <sub>2</sub> , ABC type	Provided	MF			
	IS marking	ISI marked	Provided	MF			
6	First-Aid Hose Reels.						
	Total numbers on each floor	02	Provided	MR			
	<ul> <li>Length of hose reel hose</li> </ul>	30 mts	Provided	MR			
	Nozzle diameter	5 mm	Provided	MR			
7	Automatic fire detection and alarming system.						
	Type of detectors	Smoke & Heat	Provided	MR			
	Location of Main Panel     Location of Main Panel	G. Floor	Provided	MR			
	Location of Repeater Panel	NA	NA	NA			
	Alternate source of power	Required	Provided	MR			
22.5	Hooters' Location	Suitable location	Provided	MR			
8	MOEFA	Required	Provided	MR			
9	Public Address System.	Required	Provided	MR			
10	Automatic Sprinkler System.		The result of	1 1			
	Basement	Required	Provided	MR			
	Upper Floor	Required	Provided	MR			
	Sprinkler above false ceiling	NR	NR	NR			
11	Internal Hydrants	a. L. magazaran d	KENNY MAJESA AN	1			
	Size of riser/down-comer	100 mm	Provided	MR			
	<ul> <li>Number of hydrants per floor</li> <li>Hose Box</li> </ul>	02	Provided	MR			
10		02	Provided	MR			
12	Yard Hydrants.	T 04 T	Mark Mark Later Comment	AND PARK OF			
	Total number of hydrants	04	Provided	MR			
7039	Hose Box	04	Provided	MR			
13							
	Ground Level	(Day)		este contraction and			
	Discharge of main Pump	1620 LPM	Provided	MR			
	> Head of Main pump	45 mts	Provided	MR			
	Number of main pumps	01	Provided	MR			
	> Jockey Pump out put	180 LPM	Provided	MR;			
	> Jockey pump head	45 mts	Provided	MR			
	Standby Pump out put	1620 mts	Provided	MR			
	> Standby Pump Head	45 mts	Provided	MR			
	> Auto Starting/ Manual stopping	Required	Provided	MR			
	> Pump House Access	Required	Provided	MR			
	Terrace level						
	Discharge of pump	NA	NA	NA			
	➢ Head of the pump	NA	NA NA	NA NA			
	> Power Supply	NA	NA NA	NA NA			
	Auto Starting of pump	NA	NA	NA			

	Captive Water Storage for fire fightin	g. 1741 (d	CONTRACTORS OF	ult.			
19	Underground tank capacity	1,50,000 ltr	Provided	MR			
	> Draw-off connection	Required	Provided	MR			
	Fire service inlet	Required	Provided	MR			
	> Access to tank	Required	Provided	MR			
	Overhead Tank capacity	10,000 ltr	Provided	MR			
5	Exit Signage.	Required	Provided	MR			
6	Provision of Lifts						
	Pressurization of Lift Shaft	NA	NA NA	NA			
	Pressurization of Lift lobby	NA ( a)	NA NA	NA			
	Communication In lift Car	Required	Provided	MR			
	Fireman's Grounding Switch	Required	Provided	MR			
	• Lift Signage	Required	Provided	MR			
17	Standby power supply	Required	D.G. Set Provided	MR			
18	Refuge Area.						
	<ul><li>Total Area</li><li>Location</li></ul>	NA NA	NA NA	NA NA			
19	Fire Control Room						
	Detector System Panel	Required	Provided	MR			
	Flow Switch Panel	NA	NA	NA			
	PA System Panel	Required	Provided	MR			
	Batter backup	Required	Provided	MR			
	Building Floor Plans	NA	\ NA	- NA			
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	Provided	MR			

The fire Protection systems provided in the building were checked and found functional at the time of inspection. The shortcomings issued this deptt. vide letter No. F6/DFS/MS/Hospital/2022/WD/864 dated 21/04/2022 as been complied the by hospital management.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules & as directed, it is recommended to grant fire safety certificate under Delhi Fire Service Act- 2007 & Rules- 2010.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer Name: - M. K. Chattopadhyay

Designation: - DO (West)

Signature of the Inspecting Officer

Name: - Sarabjeet Singh Designation: - ADO (MN)

Sto (DPA)

is agulant as 1.25 m 2 2.00m.

DATED. 2/2/22