



No. F6 /DFS/MS/Hospital/NDZ/2023/ 527

Dated: 07/11/2023

Certified that the **National Society for the Prevention of Blindness India** located at **Plot No. 8-B, Institutional Area Karkardooma, Delhi -110092**, comprised of basement, ground plus three upper floors only owned/occupied by **National Society for the Prevention of Blindness India** was issued FSC vide letter No. F6/DFS/MS/Hospital/2016/NDZ/940 dated 07/06/2016. The Premises was re-inspected by the officer concerned of this department of 27/10/2023 in the presence of Mr. R.S. Negi and found that the premises have deemed complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules, 2010 and found that the Banquet is fit for occupancy class C **“(Institutional building)”** with effect from 07/11/2023 for a period of **three years** in accordance with Rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rule 2010, subject to conditions printed below.

Issued 07/11/2023 at New Delhi by.


(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE
o/c (w)

Copy to: -

Mr. R. S. Negi,
National Society for the Prevention of Blindness India
Plot No.8-B, Institutional Area Karkardooma, Delhi -110092

Conditions for the validity of Fire Safety Certificate

1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form 'J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
2. All the means of escape shall be kept free of all the type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

N/19

INSPECTION REPORT

1	Name & address of the building	National Society for the Prevention of Blindness India located at ,Plot No.8-B, Institutional Area Karkardooma, Delhi -110092		
2	Building is comprised of	Basement, Ground + 03 Upper floors only		
3	Type of occupancy	Institutional (Non Bedded)		
4	Type of case	Renewal		
5	Details of previous FSC	F6/DFS/MS/Hospital/2016/NDZ/940 Dated:07/06/2016		
6	Fire safety directives letter no.	Delhi Fire Service Act,2007 and Rules 2010		
7	Date of inspection	27.10.2023		
8	Name of the inspecting officers	Yashwant Singh Meena ADO (L.N)		
9	Name of the designation of officer from the building side	Mr. R.S.Negi (Representative)		
10	Year of construction	2013		
11	Applicant's letter no.	Email dated- 29.09.2023		
S.No	Minimum standard of fire prevention and fire safety U/R 33	Circular requirement	Provided at site	Remarks MR/NMR
1	Access to Building:			
A	Road width	6.0 mtrs.	23 mtrs. ✓	MR
B	Gate width	4.5mtrs	5mtrs ✓	MR
C	Width of internal road	N/A	N/A	N/A
2	Number, Width, Type and Arrangement of Exits:			
A	Number of staircases			
a	Upper floor	01 nos.	02 nos.	MR
c	Basement	01 nos.	02 nos.	MR
B	Width of staircases			
a	Upper floor	02mtrs.	02mtrs & 01 mtrs. ✓	MR
b	Basement	02mtrs.	02mtrs & 01 mtrs.	MR
C	Protection of exits			
a	Fire check door	N/A	N/A	N/A
b	Pressurization	N/A	N/A	N/A
D	No. of continuous staircases to terrace	01 no.	01 no. ✓	MR
E	Width of corridor	N/A	N/A	N/A
F	Door size	01 mtrs.	01 mtrs. ✓	MR
3	Compartmentation:			
A	Fire check door	NA	NA	NA
B	Sealing of electrical shafts	N/A	N/A	N/A
C	Fire rating of shaft door	N/A	N/A	N/A
D	Water curtain	N/A	N/A	N/A
E	Fire dampers	N/A	N/A	N/A
4	Smoke Management System:			
A	Basement	30 a/c per hours	Exhaust	MR
B	Upper floor	12 a/c per hours	Ventilated	MR

W

5. Fire Extinguisher:				
A	Total numbers	10 Nos.	10 Nos.	MR
B	Types	CO ₂ & ABC	CO ₂ & ABC	MR
C	ISI marking	ISI Marked	Provided	MR
6 First-Aid-Hose Reel:				
A	Total numbers of each floor	01 no.	01 no.	MR
B	Length of hose reel hose	30 mtrs.	30 mtrs.	MR
C	Nozzle diameter	05 mm	05 mm	MR
7 Automatic Fire Detection and Alarming System:				
A	Type of detectors	Smoke	Provided	MR
B	Location of main panel	N/A	N/A	N/A
C	Location of repeater panel	N/A	N/A	N/A
D	Alternate source of power	N/A	N/A	N/A
E	Hooters	N/A	N/A	N/A
8	MOEFA:	Required	Provided	MR
9	Public Address System:	N/A	N/A	N/A
10 Automatic Sprinkler System:				
A	Basement	Required	Provided	MR
B	Upper floor	N/A	N/A	N/A
C	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants:		N/A	N/A
A	Size of riser/down-comer	100 mm	100 mm	MR
B	Number of hydrants per floor	01 no.	01 no.	MR
C	Hose box	01 no.	01 no.	MR
12 Yard Hydrants:				
A	Total number of hydrants	N/A	N/A	N/A
B	Hose box	N/A	N/A	N/A
13 Pumping Arrangements:				
1 Ground level				
A	Discharge of main pump	N/A	N/A	N/A
B	Head of main pump	N/A	N/A	N/A
C	Number of main pumps	N/A	N/A	N/A
D	Jockey pump out put	N/A	N/A	N/A
E	Jockey pump head	N/A	N/A	N/A
F	Standby pump out put	N/A	N/A	N/A
G	Standby pump head	N/A	N/A	N/A
H	Auto starting /manual stopping	N/A	N/A	N/A
I	Pump house access	N/A	N/A	N/A
2 Terrace Level				
A	Discharge of pump	450 LPM	450 LPM	MR
B	Head of the pump	40 mtrs.	40 mtrs.	MR
C	Power supply	Required	Provided	MR
D	Auto starting of pump	Required	Provided	MR

W


W

← N/21-

14	Captive Water Storage for Fire Fighting:						
	A	Underground tank capacity	50,000 ltr	50,000 ltr ✓	MR		
	B	Draw-off connection	N/A	N/A	N/A		
	C	Fire service inlet	N/A	N/A	N/A		
	D	Access to tank	N/A	N/A ✓	N/A		
	E	Overhead tank capacity	5,000 ltrs	10,000 ltr	MR		
15	Exit Signage:				Required	Provided	MR
16	Provision of Lifts:				N/A	N/A	N/A
	A	Pressurization of lift shaft	N/A	N/A	N/A		
	B	Pressurization of lift lobby	N/A	N/A	N/A		
	C	Communication in lift car	N/A	N/A	N/A		
	D	Firemen's grounding switch	N/A	N/A	N/A		
	E	Lift signage	N/A	N/A	N/A		
17	Standby Power Supply:				N/A	N/A	N/A
18	Refuge Area:				N/A	N/A	N/A
	A	Total area	N/A	N/A	N/A		
	B	Location	N/A	N/A	N/A		
19	Fire Control Room:				N/A	N/A	N/A
	A	Detector system panel	N/A	N/A	N/A		
	B	Flow switch panel	N/A	N/A	N/A		
	C	PA system panel	N/A	N/A	N/A		
	D	Battery backup	N/A	N/A	N/A		
	E	Building floor plans	N/A	N/A	N/A		
20	Special Fire Protection systems for protection of special Risks, if any:				N/A	N/A	N/A

The fire protection system was randomly checked and tested and was found functional at the time of inspection. The shortcomings issued vide letter no. F6/DFS/MS/2019/hospital//7972 dated 31.12.2019 by this department have been rectified by the management.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Director of Education the FSC issued vide letter no. F6/DFS/MS/Hospital/2016/NDZ/940 dated 07/06/2016 is recommended to be renewed.



31/10/2023

Signature of the Inspecting Officer
Name:- Yashwant Singh Meena
Designation:- ADO (L.N)

Dy. CFO (NDZ)


01/11/23

C.F.O.


3/11/2023