FORM 'H' FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI

No. F6/DFS/MS/SZ/2023/ 52-8

Dated:07 / // /2023

FIRE SAFETY CERTIFICATE

Certified that the Venkateshwar Hospital (A unit of All India Society for Health Aid Education & Research), located at Sector 18A, Dwarka, New Delhi-110075 in a building comprised of three tier Basement + Ground Floors +Ten upper floor owned/occupied by Venkateshwar Hospital was issued Fire Safety Certificate vide letter No. F6/DFS/MS/2020/493, dated 24/11/2020. The premises was re inspected by the officers concerned of this department on 01/11/2023 in the presence of Sh. Kamal Solanki (CEO) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class "Assembly" Group D with effect from O+ 11 2023 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on . 07/11/2023. at New Delhi by.

(Atul Garg) (Director) Delhi/Fire Service

Copy to: -

 M/s. Venkateshwar Hospital (A unit of All India Society for Health Aid Education & Research), Sector 18A, Dwarka, New Delhi-110075.

2. The Directorate General of Health Services, F-17, Arjun Gali, Karkardooma, Anand Vihar, New Delhi – 110032.

Following fire safety directives must be adhered to:-

- All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

3. The trained staff should be available round the clock.

- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

6. Basement shall be used as per building bye laws.

- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expired.

INSPECTION REPORT

1. Name & address of the building: Venkateshwar Hospital (A unit of All INDIA Society for Health Aid Education & Research), Located at Sector 18A, Dwarka, New Delhi-110075

2. Type of Occupancy : Institutional (Hospital) comprised of three tier basement, Tower-A=G+6UF & Tower -B=G+10UF.

Type of Case

: Renewal

4. Details of previous NOC

: F6/DFS/MS/2020/493, dated 24/11/2020

14/35

5. Fire Safety directives L. No.: F6/DFS/MS/BP/Hospital/2014/246 dated

6. Date of inspection

: 01-11-2023

7. Name of the Inspecting Officer: DO/SW & ADO (DWK)

8. Name and designation of Officer:

from the building side

: Sh. Kamal Solanki (CEO)

9. Year of Construction

:2015-16

10. Applicant's letter No

	10. Applicant's letter No.	: Form J dated 17-102023						
S No	Minimum standards on fire prevention and fire safety U/R 33		As per N/30, N/31, N/32 & N/33		Provided at site	1.75	Remarks MR/NMR	
1.	Access of building	1155						
	Road width		12 m		Provided		MR	
	Gate width Width of internal road	5 m			vided vided	MR MR		
2.	Number, width, Type & Arrangemer		1 5		IVIK			
	a. Number of staircases	its of exits						
	Upper floors	04	provi	provided		MR		
	Basements Width of staircases	06	provi		MR			
3.	 Upper floors 	2mtr	2 mt	r Provided		MR		
	Basements Protection of exits	2 m&1.5m	4x	4x2m,2x1.5m & Ramp				
	Fire check door	Required	Pro	Provided		MR		
	Pressurization	Required	-	Provided		MR		
	d. No of continuous staire to terrace	ase	03	Pro	Provided		MR	
	e. Width Of Corridor f. Door Size	2.40mts	Pro	Provided		MR		
	Compartmentation		2.0mts	Pr	Provided		MR	
	 Fire check door Sealing of electrical shafts Fire Rating of shaft door 		Required	Pro	Provided		MR	
			Required	Pro	Provided		MR	
			Required	Pro	vided	_	MR	
	Water Curtain Fire Down		Pseudo compart		Provide			
	Fire Dampers		Required		Provided		MR	
			(Ma)	1				

	Smoke managements System			200/0 1		D.	Provided		MR	
	 Basements 			30a/c per hour		_	4-10-20-30-00-00-00-00-00-00-00-00-00-00-00-00	_	MR	
		pper floors		12a/c per	hour	Pr	ovide	a	IVIK	
5.	Fire Extinguishers			2022			T =			1.00
	 Total numbers 			150 nos.		22020		rided		MR
	Types			DCP &CO2, CO2		02	2 Provided			MR
	IS marking			ISI marked			Provided			MR
6.	First - Aid Hose Reels			m % 8		111-	or I	- Au		
		 Total numbers on each floor 		BF-6, GF to 7 th Floor 8 th to Terrace-3			r-4, Provide		vided	MR
	• L	ength of hose reel hos	se	· 30 m				Provided		MR
	Nozzle diameter		5 mm			7	Provided		MR	
7.		ic fire detection and a	larmin		-	-			1 1/1	
		ype of detectors		Smoke &	Heat	Pro	vided	TM	TD CT	101
		ocation of Main Pane	1							
	72.00	ocation of Repeater P		Basement-		_	rovided rovided		MR	
		lternate source of pov							MR MR	
		looters' Location	WCI	Required			Provided Provided		K	1
	- Hooters Location			required		100000000000000000000000000000000000000	No. of Street,		and the second	MR
8.	MOEFA		VEH C	Paguired		Strategic loc Provided		_		
9.		ddress System		Required			ALCOHOLD STATE	M		and.
10.	Automat	ic Sprinkler System		Required		Prov	vided	M	R	
	• B	asements	Requ	ired	l n					
		pper Floor			_	Provided		M		
								M	MR	
	ceiling Requ					vided N		M	MR	
11.	Internal Hydrants:						3 100	83		
	• S	ize of riser/down- con	150			land.				
	Number of hydrants per floor Hose Box			150mm		Provided		1	MR	
					BF-6, GF to 7 th		Provided			MR
				Floor-4, 8 th to Terrace-3						
						E TOLON THE		May H	-4-2-	
12.	Yard Hydrants			Required Pro			Provi	rovided MR		MR
	• T	otal number of bud-		0.01					-1.	VII.
	Total number of hydrants Hose Box			08Nos. Provided		ded	MR			
13.	Pumping Arrangements:			08 Provide		ded MR		_		
	Ground Level				1		CALCULATE OF THE PARTY OF THE P	1411		
	• D	ischarge of main pum	Muc	ď.		_			1/	
	> H	ead of main pump	p	2280lpm			Provided		_	
	Number of main pumps			110 m			Provided			MR
	Jockey pump out put			2 '						MR
	Jockev numn hand			220 lpm			Provided			MR
	Standby Pump and			110m			Provided			MR
	Statiuty Plimp Used			2280lpm		-	Provided			MR
	Auto Staring/Manual		110m		1	Provided			MR	
	1 30	UDDIng		Required		1	Provided			MR
	 Pump House Access Terrace level Discharge of pump Head of the pump Power supply Auto starting of pump 					1	Provided			MR
				Required Decari						
				FIOVI		rovid	ded		MR	
				NA						
				NA		NA		1	NA	
				NA			NA ⁻			NA
				NA		1 3	NA			171
		r-mp		NA	-					
		rp		NA			NA NA	_	_ 1	NA NA

	11/07								
14.	Captive water Storage for fire fighting:								
	 Under ground tank capacity 	1,50,000 liter	Provided	MR					
	Draw off connection	Required	Provided	MR	-				
	 Fire service inlet 	Required	Provided	MR					
	Access to tank	Accessible	Provided	MR					
	Overhead Tank capacity	Required20,000 Litres	Provided	MR					
15	Exit Signage	Required	Provided	MR					
16.	Provision of Lifts		A Trail of		100				
	 Pressurization of Lift Shaft 	Required	Provided	rovided MR					
1	 Pressurization of lift lobby 	Required	Provided	MR					
	Car	Required	Provided	MR					
	 Fireman's Grounding Switch 	Required	Provided	MR					
	➤ Lift Signage	Required	Provided	MR					
17.	Standby power supply	Required	DG set MR 500KVA						
18.	Refuge Area				1				
	> Total area	Required	sanctioned plan		MR				
	> Location	Required	AT 6TH FLOOR	<u> </u>	MR				
19.	Fire control room								
1	> Detector system panel	Required	Provided MR						
	> Flow Switch Panel	Required	Provided	MR					
	> PA System Panel	Required	Provided	MR					
	> Battery backup	Required	Provided	MR					
	> Building Floor Plans	Required	Provided	MR					
20.	Special Fire Protection Systems for Protection of special Risks, if any;	Required	CO2 flooding system Provided in elect.Panel.	MR					

The fire protection systems provided in the building were test checked and

found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the FSC issued vide letter no. F6/DFS/MS/2020/493, dated 24/11/2020 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Off Name

Designation D.O

Signature of the Inspecting Name Ublas

Designation