



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2023/School/ 813

Dated: 14 / 11 /2023

FIRE SAFETY CERTIFICATE

Certified that Convent of Model Education located at Gali No-9, Near Amina Masjid, Wazirabad, Delhi-110084 comprised of Ground & first floor only owned/ occupied by Convent of Model Education was granted FSC by this department vide letter no. No.F6/DFS/MS/2020/WZ/479 dated 05.11.2020. The premises was re-inspected by the officer concerned of this department on 31.10.2023 in presence of Sh. Manzoor Husain (Admin) and observed that all the fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education vide letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy class "Group B Educational" with effect from [4.] 11.1.2.23. for a period of three years, subject to compliance of the conditions mentioned below:

Issued on ... 14 11 2023 at New Delhi

Director Ph.-011-23414000

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Scett. Delhi - 110054.

2. The Principal, Convent of Model Education located at Gali No-9, Near Amina Masjid, Wazirabad, Delhi-110084.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.

3. Any loss of life or property due to non-functional fire safety measures shall be at the

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first Service Rules http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms. 2010. form is available

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any,

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its

INSPECTION REPORT

Name & address of the building : Convent of Modern Education at Gali No-9, Near Amina Masjid, Wazirabad.

Delhi-110084.

2 Type of Occupancy : Educational

Composition of building : Ground & first floor only

Type of Case : Renewal

5. Details of previous NOC : F6/DFS/MS/2020/WZ/479 Dated: 05.11.2020

: ADO (RN)

Fire Safety directives letter No

Date of inspection : 31.10.2023 Name of the Inspecting Officers

9. Name and designation of officers

from the building side : Mr. Manzor Husain (Admin)

10. Year of Construction : 2004

11. Applicant's letter No. : Letter No. CME/10/2023 Dated- 20.10.2023

	Minimum Standards on fire prevention and fire safety U/R 33	Director of education circular dated 01.03.20 Requirements		Remarks MR/NMR		
1	Access to building					
	Road width	Accessible	Accessible	MR		
	Gate width	Accessible	Accessible	MR		
	Width of internal road	NA	NA	NA		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	 Upper Floors 	01	02	MR		
	Basements	NΛ	NA	NΛ		
	b. Width of staircases					
	Upper Floors	1.50m	1.0m & 75 cm	MR(old case		
	Basements	NA	NA	NA		
	c. Protection of exits					
	Fire check door	NA	NA	NA		
	 Pressurization 	NA	NA	NA		
	d. No. of continuous staircases to terrace	NA	NA	NA		
	e. Width of Corridor f. Door Size	NA	NA	NΛ		
	The state of the s	01m	01m	MR		
	Compartmentation.					
	Fire check door	NA	NA	NA		
	Sealing of electrical shafts	· NA	NA	NA		
	Fire Rating of shaft door	NΛ	NΛ	NA		
	Water Curtain	NΛ	NA	NA		
	Fire Dampers	NA	NA	NA		
	Smoke Management System.					
	Basements	NA	NA	NA		
	• Upper floors	Required	Provided	MR		
	Fire Extinguishers					
	Total numbers	02nos	03nos	MR		
	• Types	ABC/CO2	ABC-03	MR		
	ISI marking	ISI Marked	Yes	MR		
	First-Aid Hose Reels.					

	NIIA			THE REAL PROPERTY.	
_	Total numbers on each floor	NA	NA		
	Length of hose reel hose	NA	NA		
	Nozzle diameter	NA	NΛ	NA	
	Automatic fire detection and alarming system.		NA	NA NA	
	Type of detectors	NA	NA NA	NA	
	Location of Main Panel	NA	NA NA	NA	
	Location of Repeater Panel	NA	PACTORIA CONTRACTOR OF THE PACTOR OF THE PAC	NA	
	Alternate source of power	NA	NA		
	Hooters' Location	NA	NΛ	NA	
	Thoron and the second s	NA	NA	NA NA	
3	MOEFA	NA	NΛ	NA	
)	Public Address System.				
10	Automatic Sprinkler System.	NA	NΛ	NA	
	Basement	NA	NA	NA	
	Upper Floor Glasseiling	NA	NA	NA	
	Sprinkler above false ceiling	NA			
11	Internal Hydrants	NA I	NΛ	NΛ	
	Size of riser/down-comer	NA NA	NA	NA	
	Number of hydrants per floor	NA NA	NA	NA	
	Hose Box	INA			
12	Yard Hydrants.	NA	NA	NA	
	Total number of hydrants	NA	NA	NA	
	Hose Box				
13	Pumping Arrangements.				
	Ground Level	N/A	N/A	N/A	
	➤ Discharge of main Pump		N/A	N/A	
	> Head of Main pump	N/A	-4.75.00	N/A	
	> Number of main pumps	N/A	N/A		
	> Jockey Pump out put	N/A	N/A	N/A	
	> Jockey pump head	N/A	N/A	N/A	
	> Standby Pump out put	N/A	N/A	N/A	
	> Standby Pump Head	N/A	N/A	N/A	
	Auto Starting/ Manual stopping Pump House Access		N/A	N/A	
	Terrace level	N/A	N/A	*****	
	> Discharge of pump			NI/A	
	Head of the pump	N/A	N/A	N/A	
	Power Supply	N/A	N/A	N/A	
	> Auto Starting of pump	N/A	N/A	N/A	
		N/A	N/A	N/A	
14	Captive Water Storage for fire fighting.				
265	Underground tank capacity	NA	NA	NA	
	> Draw-off connection	NA	NA	NA	
	➤ Fire service inlet	NA	NA	NA	
	> Access to tank	NA	NA	NA	
	Overhead Tank capacity	N/A	N/A	N/A	
	100 April 100 Ap				
15	Exit Signage.	N/A	N/A	N/A	

	Pressurization of Lift Shaft	N/A	N/A	N/A	
	 Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
7	Standby power supply	N/A	N/A	N/A	
8	Refuge Area.				
	Y Total Area	N/A	N/A	N/A	
	Location	N/A	N/A	N/A	
9	Fire Control Room				
	Detector System Panel	N/A	N/A	N/A	
	Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel	N/A	N/A	N/A	
	Batter backup Building Floor Plans	N/A	N/A	N/A	
		N/A	N/A	N/A	
0	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. F6/DFS/MS/2020/WZ/479 dated: 05.11 2020.

Signature of the Inspecting Officer
Name:-C.L. Meena

Designation:- ADO/RN

Dy. Chief Fire Officer (WZ)

01/11/2000

CF. Hugh 17 11/2023

CI DI

CEO! 3.41 Level