GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/School/SZ/2023/8/O

Dated- 14 .11.2023

FIRE SAFETY CERTIFICATE

Certified that The Li'l Geniuses School, Plot 'No- 52, Main Goyla Dairy Road, Shivpuri (Part- 2), Near Sec-19, Dwarka, New Delhi, comprised of ground and first floor only, owned/occupied by Mr. Prem Sukh Jakhar, was inspected by the officer concerned of Delhi Fire Service on 08.11.2023 in the presence of Mr. Prem Sukh Jakhar (Owner), and found that the said School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Directorate of Education circular No. F.6/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 and that the school building is fit for occupancy class "Educational" with effect from 14.11.2023 for a period of three years, subject to compliance of the under mentioned conditions.

Issued on 14 .11.2023 at New Delhi by.

(Atul Garg)
Director
Delhi Fire Service

Copy to: -

 Mr. Prem Sukh Jakhar (Owner), The Li'l Geniuses School, Plot No- 52, Main Goyla Dairy Road, Shivpuri (Part- 2), Near Sec-19, Dwarka, New Delhi.

The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Conditions for the Validity of Fire Safety Certificate

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. Basement used only for storage purpose as per BBL.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.
- All the means of escapes /exits shall not be locked/blocked at any time for safe evacuation of the occupants in case of emergency.

INSPECTION REPORT

1. Name & address of the building

: The Li'l Geniuses School, Plot No- 52, Main Goyla Dairy

Road, Shivpuri (Part- 2), Near Sec-19, Dwarka, New

Delhi.

2. Type of Occupancy

: Educational

3. Building Composition

: School building comprised of ground plus one upper floor only.

4. Type of Case

: New Case

5. Details of previous NOC

: N/A

6. Fire Safety directives letter No

: Directorate of Education circular No. F.16/Estate/CC/Fire

Safety/2011/3298 to 3398 dated 01-03-2011.

7. Date of inspection

: 08.11.2023

8. Name of the Inspecting Officers

: Vedpal Chhikara, Divisional Officer (SW)

9. Name and designation of officers

from the building side

: Mr. Prem Sukh Jakhar (Owner)

9. Year of Construction : 2023

10 Applicant's letter No. : Latter No. Nil dated 30.10.2023

| S. No. | Minimum Standards on fire prevention and fire safety U/R 33 | Directorate of Education circular dt. 01.03.2011 | Provided at site | Remarks MR/NMR | | |
|-----------|---|--|---------------------|-------------------|--|--|
| | Access to building | | | | | |
| | Road width | 06 mts 05 mts | Provided Provided | MR MR | | |
| | • Gate width | N/A | N/A | N/A | | |
| | • Width of internal road Number, Width, Type & Arrangement | 24.75.02.49.03 | N/A | IVA | | |
| | | | | 1 | | |
| | a. Number of staircases | 02 | 02 | MR | | |
| | Upper Floors | 02 | 02 | IMIK | | |
| | Basements | N/A | N/A | N/A | | |
| | b. Width of staircases | | 3 <u>22/4-20-</u> 1 | \ | | |
| | • Upper Floors | 1.50 mts each | 1.50 mts each | MR | | |
| 9 | Basements | N/A | N/A | ŊΑ | | |
| | c. Protection of exits | | | 1-1 | | |
| | Fire check door | N/A | N/A | N/A | | |
| | Pressurization | N/A | N/A | N/A | | |
| | e. No. of continuous staircases to terrace | 01 Nos. | 02.Nos. | MR | | |
| | g. Width of Corridor | N/A | N/A | N/A | | |
| | h. Door Size | 1.0 mt | 1.10 mts. | MR | | |
| 7 | Compartmentation. | | | | | |
| 1 | Fire check door | N/A | N/A | N/A | | |
| | Sealing of electrical shafts | N/A | N/A | N/A | | |
| | Fire Rating of shaft door | N/A | N/A | N/A | | |
| | Water Curtain | N/A | N/A | N/A | | |
| | Fire Dampers | N/A | N/A | N/A | | |
| + | Smoke Management System. | | | | | |
| \dashv | Basements | 30 a/c per hour | N/A | N/A | | |
| | Upper floors | 12 a/c per hour | N/A | N/A | | |
| 1 | Fire Extinguishers | | | | | |
| 7 | Total numbers | 06 nos. | Provided | MR | | |
| | Types | ABC type | Provided | MR | | |
| | IS marking | ISI marked | Provided | MR | | |

| | First-Aid Hose Reels. | - | | |
|-----|--|---------------------------------------|------------|------------|
| | Total numbers on each floor | N/A | 01 Nos. | 1377 |
| - 1 | Length of hose reel hose | N/A | 30 mm | N/A |
| | Nozzle diameter | N/A | 5 mm | N/A N/A |
| | Automatic fire detection and alarming | 1000000 | t required | IN/A |
| | Type of detectors | N/A | | 12.00 |
| | Location of Main Panel | N/A | N/A N/A | N/A |
| | Location of Repeater Panel | N/A | 2000.00 | N/A |
| | Alternate source of power | N/A | N/A N/A | N/A |
| | Hooters Location | N/A | N/A | N/A |
| | MOEFA | N/A | N/A | N/A N/A |
| | Public Addres System. | N/A | N/A | |
| 0 | Automatic Sprinkler System | | N/A | N/A |
| | Basenent | | | |
| | Upp r Floor | N/A | N/A | N/A |
| | | N/A | Provided | N/A |
| | Sprakler above false ceiling | N/A | N/A | N/A |
| 1 | Internal Lydrants | | | |
| | See of riser/down-comer | N/A | | |
| | Number of hydrants per floor | 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | N/A | N/A |
| | Hose Box | N/A | N/A | N/A |
| 2 | Yard Lydrants. | N/A | N/A | N/A |
| | | 10 | | IVA |
| | Total number of hydrants | N/A | N/A | N/A |
| | Hose Box | N/A | 20000000 | |
| 3 | Purping Arrangements | 1371 | N/A | N/A |
| | Ground Level | 4 | | |
| | Discharge of main Pump | N/A | N/A | |
| | ➤ Head of Main pump | N/A | | N/A |
| | Number of main pumps | N/A | N/A | N/A |
| | ➢ Jockey Pump out put | N/A | N/A | N/A |
| | > Jockey pump head | 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | N/A | N/A |
| | Standby Pump out put | N/A | N/A | N/A |
| | Standby Pump Head | N/A | N/A | N/A |
| | > Auto Starting/ Manual | N/A | N/A | N/A |
| 1 | stopping | N/A | N/A | N/A |
| / | ➤ Pump House Access | N/A | N/A | N/A |
| | Terrace level | | - W. 1. 1 | IN/A |
| | Discharge of pump | | | |
| | Head of the pump | N/A | 450 LPM | N/A |
| | 10 (10 to 10 | N/A | 40 M | N/A |
| | > Power Supply | N/A | N/A | - N/A |
| 4 | Auto Starting of pump | N/A | N/A | N/A |
| • | Captive Water Storage for fire fight | ting | | N/A |
| | Underground tank capacity | N/A | N/A | NT/A |
| | Draw-off connection | N/A | N/A | N/A |
| | Fire service inlet | N/A | N/A | N/A |
| | Access to tank | N/A | N/A | N/A |
| | Overhead Tank capacity | N/A | 5,000 lts | N/A |
| | | | | N/A |

| 16 | Provision of Lifts. | Not Appl | Not Applicable | | |
|----|---|----------|--|-----|--|
| | Pressurization of Lift Shaft | N/A | N/A | N/A | |
| | Pressurization of Lift lobby | N/A | N/A | N/A | |
| | Communication In lift Car | N/A | N/A | N/A | |
| | Fireman's Grounding Switch Lift Signage | N/A | N/A | N/A | |
| | | N/A | N/A | N/A | |
| 17 | Standby power supply | N/A | N/A | N/A | |
| 18 | Refuge Area. | | | | |
| | ➤ Total Area | N/A | N/A | N/A | |
| | Location | N/A | N/A | N/A | |
| 19 | Fire Control Room | | | | |
| | Detector System Panel | N/A | N/A | N/A | |
| | Flow Switch Panel | N/A | N/A | N/A | |
| | PA System Panel | N/A | N/A | N/A | |
| | Batter backup | N/A | N/A | N/A | |
| | Building Floor Plans | N/A | N/A | N/A | |
| 20 | Special Fire Protection Systems for Protection of special Risks, if any: | Required | The state of the s | | |

The fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the Rules, it is recommended to grant fire safety certificate under The Directorate of Education circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011.

Accordingly, DFA is put up for approval & signature please.

Signature of the Inspecting Officer Name- Vedpal Chhikara Divisional Officer (SW)

CFO (SZ)

9/11/2022

Dinecter

putup forerpm

M/18)11/2