

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001**

No. F.6/DFS/MS/2023/SZ/college/29

Dated: 10/11/2023

FIRE SAFETY CERTIFICATE

Certified that the **JSS Spiritual & Cultural Centre**, Plot no 18 & 19, Sec-VI, Pushp Vihar, Saket, New Delhi-110017 comprised of Basement, Ground + 3 upper floors Owner/Occupied by Jagadguru Sri Veerasimhasana Math was issued FSC by this department vide letter no F6/DFS/MS/2020/SZ/402 dated 05/10/2020. The premises was re-inspected by the officers concerned of this department on 05/11/2023 in the presence of Mr. Giresh (Care Taker) and found that the said building/premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the building/premises is fit for occupancy **Group- D " Assembly Building"** (Spiritual Education cum Residential) as above with effect from 10/11/2023 for a period of **three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 10/11/2023. at New Delhi by.


(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to: -

1. The Manager, JSS Spiritual & Cultural Centre, Plot no 18& 19, Sec-VI, Pushp Vihar, Saket, New Delhi-110017.
2. The Executive Engineer (Bldg Department) MCD, Green Park, Zone, New Delhi - 16

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management. The trained staff should be available round the clock.
3. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
4. The basement shall be used as per the provisions of UBBL 2016 /NBC Part- IV.
5. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

1	Name & Address of the Building	JSS Spiritual & Cultural Centre, Sri Suttur Bhawan, Plot no 18& 19, Sec-VI, Pushp Vihar, Saket, New Delhi-17		
2	Type of Occupancy	Assembly, " (Spiritual Education cum Residential)		
3	Building Comprised of	Basement, Ground + 3 upper floors		
4	Type of Case	Renewal		
5	Details of Previous NOC	F6/DFS/MS/2020/SZ/402 dated 15/10/2020		
6	Fire Safety Directives Letter No	F6/DFS/MS/BP/2007/2869 dated 04/10/2007		
7	Date of Inspection	05/11/2023		
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Giresh (Care Taker)		
10	Year of construction	2012		
11	Applicant letter No.	DFS outdoor diary no nil dated 26/09/2023		
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC Requirements	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	• Road width	12 m	12 m	MR
	• Gate width	Required	5 m	MR
	• Width of internal road	-N/A-	-N/A-	-N/A-
2	Number, width, type & arrangement of exits.			
	a) Number of Staircase			
	➤ Upper floors.	02 nos	02 nos	MR
	➤ Basement floor.	02 nos	02 nos	MR
	b) Width of Staircase			
	➤ Upper floors	Required	1.20 m & 1.08 m	MR(old case)
	➤ Basement floor	Required	1.20 m & 1.08 m	MR(old case)
	c) Protection of exits			
	➤ Fire check door	Required	Provided	MR
	➤ Pressurization	-N/A-	-N/A-	-N/A-
	d) No. of continuous staircase to terrace	Two	Two	MR
	e) Width of corridor	-N/A-	-N/A-	-N/A-
	f) Door size	1.25 m	1.25 m	MR
3	Compartmentation.			
	• Fire check door.	-N/A-	-N/A-	-N/A-
	• Sealing of electrical shafts.	Required	Provided	MR
	• Fire rating of shaft door.	-N/A-	-N/A-	-N/A-
	• Water curtain	-N/A-	-N/A-	-N/A-
	• Fire dampers.	Yes	Provided	MR
4.	Smoke Management system.			
	• Basement	Required	Exhaust fan Provided	MR
	• Upper floors	Required	Exhaust fan Provided	MR
5.	Fire Extinguishers.			
	• Total numbers	Fire Extinguisher ISI marked	25Nos	MR
	• Types		W.CO ₂ -20, CO ₂ -05	MR
	• ISI Marking		Provided	MR
6.	First Aid Hose Reels.			
	• Total numbers on each floor	Hose reel	Two	MR
	• Length of hose-reel hose.		30 m	MR

N/23

	• Nozzle Diameter		5 mm	MR
7	Automatic fire detection & alarming system.			
	• Type of detectors	Required	Smoke	MR
	• Location of Main Panel	Required	Basement	MR
	• Location of Repeater Panel	Required	Basement	MR
	• Alternate source of power	Required	DG Set	MR
	• Hooter's location	Required	Every floor	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	-N/A-	-N/A-	-N/A-
10.	Automatic Sprinkler System			
	• Basement.	Required	Provided	MR
	• Upper floors	-N/A-	-N/A-	-N/A-
	• Sprinkler above false ceiling	-N/A-	-N/A-	-N/A-
11.	Internal Hydrants.			
	• Size of Riser / Down-comer	Required	150 mm	MR
	• Number of Hydrant per floor	Required	02 nos	MR
	• Hose box.	Required	02 nos	MR
12.	Yard Hydrants.			
	• Total number of hydrants.	Required	05 nos	MR
	• Hose box.	Required	05 nos	MR
13.	Pumping arrangements.			
	• Ground Level			
	Discharge of main pump.	2280 LPM	2280 LPM	MR
	➤ Head of main pump.	70 m	70 m	MR
	➤ Number of main pumps.	One	One	MR
	➤ Jockey Pump output.	180 LPM	180 LPM	MR
	➤ Jockey Pump head.	60 m	60 m	MR
	➤ Standby Pump output.	2280 LPM	2280 LPM	MR
	➤ Standby Pump head.	70 m	70 m	MR
	➤ Auto Starting/Manual stopping.	Required	Provided	MR
	➤ Pump house access.	Required	Provided	MR
	• Terrace Level			
	➤ Discharge of pump.	900 LPM	900 LPM	MR
	➤ Head of pump.	40 m	40 m	MR
	➤ Power supply.	Required	Provided	MR
	➤ Auto starting of pump.	-N/A-	-N/A-	-N/A-
14.	Captive water storage for firefighting.			
	• Underground tank capacity.	Required	50000 ltrs	MR
	➤ Draw-off connection.	-N/A-	Provided	MR
	➤ Fire Service Inlet.	Required	Provided	MR
	➤ Access to tank.	-N/A-	Provided	MR
	• Overhead tank capacity.	10,000 ltrs	10,000 ltrs	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	• Pressurization of lift shaft.	-N/A-	-N/A-	-N/A-
	• Pressurization of lift lobby.	-N/A-	-N/A-	-N/A-
	• Communication in lift car.	Required	Provided	MR
	• Fireman's switch.	Required	Provided	MR
	• Lift signage.	Required	Provided	MR
17	Standby Power Supply	Required	DG Set Provided	MR

18.	Refuge Area			
	• Total area	-N/A-	-N/A-	-N/A-
	• Location	-N/A-	-N/A-	-N/A-
19.	Fire Control Room.			
	• Detector System Panel.	Required	Provided	MR
	• Flow Switch Panel.	-N/A-	-N/A-	-N/A-
	• PA system Panel.	-N/A-	-N/A-	-N/A-
	• Battery backup	Required	Provided	MR
	• Building floor plan	-N/A-	-N/A-	-N/A-
20.	Special Fire Protection System for the Protection of special Risk, if any.			-N/A-

The Fire protection systems provided in the premises were checked / operated at random and found functional at the time of inspection.

Keeping in view of the substantial satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no. F6/DFS/MS/2020/SZ/402 dated 15/10/2020, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

msk

Signature of the Inspection Officer
Name: Sh. Manoj Kumar Sharma
Design: DO (South)

Sh. Rajesh Kumar
9/11/23

Signature of the Inspecting Officer
Name: Sh. Rajesh Kumar
Design: ADO (BCP)

CFO (HQ)

Wugh
8/11/2023
Director

[Signature]
9/11/23

[Signature]

As approved, f-y letter is put up
for your signature pl

[Signature]
9/11/2023

Director
[Signature]
10/11/23