

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/2023/E11/338

Dated 15 111 12023

FIRE SAFETY CERTIFICATE

Certified that the M/s Kiiza Café and Lounge (A Unit of Shiv Shambhu Hospitality) located at First Floor, Property No-2648, Hudson Lane Kingsway Camp, Delhi-110009in a building comprised of basement, ground and 03 upper floors owned/ occupied by M/s Kiiza Café and Lounge (A Unit of Shiv Shambhu Hospitality) have complied with the fire prevention andfire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 20.10.2023 in the presence of Sh. Sunil Kumarand that the building/ premise is fit for occupancy Class Assembly (Restaurant) atfirst floor only with effect from 15-11-2023 for a period Upto 31.03.2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 15-11-2023 at New Delhi by

Copy to:-

1. M/s Kiiza Café and Lounge (A Unit of Shiv Shambhu Hospitality) located at First Floor, Property No-2648, Iludson Lane Kingsway Camp, Delhi-110009.

Conditions for the validity of Fire Safety Certificate:

1. This Fire Safety Certificate is valid only for restaurant at first floor for assembly occupancy only. In case of any violation, this FSC will be treated as null & void.

2. All the means of escape/entry/exit shall be kept free from any obstruction.

3. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.

4. Any loss of life or property due to non-functional fire safety measures shall be at the

5. All the staff members must know the correct method of operation of firefighting system.

6. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

7. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if

8. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its

INSPECTION REPORT

Name & address of the building

: M/s Kiiza Cafe and Lounge (A Unit of Shiv Shambhu Hospitality) at

Plot No.2648, First Floor, Hudson Lane, Kingsway Camp, Delhi-110009.

Type of Occupancy

: Assembly (Restaurant)

3. Composition of building

: Basement, Ground & 03 Upper Floorsbut restaurant running at first floor

only basement-vacant, ground floor-shops, 2nd& 3rd floor other restaurant.

4. Type of Case

: New Case

Details of previous NOC

: Nil

6. Fire Safety directives letter No

: Nil

Date of inspection

: 20.10.2023

Name of the Inspecting Officers

: ADO (RN)

Name and designation of officers

from the building side

: Mr. SunilKumar

10. Year of Construction

: 2020

	2. Covered area-110sqm Minimum Standards on fire prevention and fire safety U/R 33	UBBL/NBC-2016 requirements	Provided at site	Remarks MR/NMF				
	Access to building							
	Road width	06	09m approx	MR				
	Gate width	NA	NΛ	NΛ				
	Width of internal road	NΛ	NΛ	NΛ				
?	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases			1				
	Upper Floors	02	02	MR				
	Basements	NΛ	NA	NA				
	b. Width of staircases							
	Upper Floors	1.50m each	1.50m each	MR				
	Basements	NΛ	NA	NA				
	c. Protection of exits							
	Fire check door	Required	Provided	MR				
	Pressurization	NΛ	NΛ	NA				
	d. No. of continuous staircases to terrace	02	02	MR				
	c. Width of Corridor	NΛ	NA	NΛ				
	f. Door Size	1.50m each	Provided	MR				
	Compartmentation.							
	Fire check door	Required	Provided	MR				
	Sealing of electrical shafts	NA	NΛ	NΛ				
	Fire Rating of shaft door	NA	NΛ	NA				
	Water Curtain	NΛ	NΛ	NΛ				
	Fire Dampers	NA	NA	NA				
	Smoke Management System.							
	Basements	NA	NA	NA				
	Upper floors(first floor)	Required	Provided	MR				
	Fire Extinguishers							
	Total numbers	04nos	04nos	MR				
	Types	ABC/Co2	ABC-04	MR				
	ISI marking	Yes	Provided	MR				
		Con		1				

6	First-Aid Hose Reels. Total numbers on each floor	01	Provided	MR		
		30m	30m	MR		
	Length of hose reel hose	5mm	5mm	MR		
	Nozzie diameter					
7	Automatic fire detection and alarming system.	Required	Provided	MR		
	Type of detectors	Required	First floor	MR		
	Location of Main Panel	NA	NΛ	NΛ		
	Location of Repeater Panel	NΛ	NΛ	NA NA		
	Alternate source of power	NΛ	NA	NA		
	Hooters' Location	Required	Provided	MR		
8	MOEFA	NA	NA	NΛ		
9	Public Address System.					
10	Automatic Sprinkler System.	NA	NΛ	NΛ		
	Basement Uses Place	NA	NA	NΛ		
	Upper Floor Upper Floor Upper Floor	NΛ	NA	NΛ		
	Sprinkler above false ceiling	, na				
11	Internal Hydrants	100mm	Provided	MR		
	Size of riser/down-comer	01	01	MR		
	Number of hydrants per floor	01	01	MR		
	Hose Box					
12	Yard Hydrants.	1 314 1	NΛ	NΛ		
	Total number of hydrants	NA	70.00	NΛ		
	Hosc Box	NΛ	NΛ	N/A		
13	Pumping Arrangements.					
	Ground Level		N/A	NΛ		
	Discharge of main Pump	NΛ	- P.O. V. S.			
	> Head of Main pump	NΛ	N/A	NA NA		
	> Number of main pumps	NΛ	N/A	NA N/A		
	> Jockey Pump out put	N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A	N/A		
	> Standby Pump out put	N/A	N/A	N/A		
	> Standby Pump Head	N/A	N/A	N/A		
	> Auto Starting/ Manual stopping	N/A	N/A	N/A		
	Pump House Access					
	Terrace level		450lpm	MR		
	> Discharge of pump	450lpm				
	> Head of the pump	40m	40m	MR		
	> Power Supply	Required	Provided	MR		
	➤ Auto Starting of pump	Required	Provided	MR		
			1			
4	Captive Water Storage for fire fighting.					
	Underground tank capacity	NΛ	NA	NA NA		
	> Draw-off connection	NΛ	NΛ	NA MD		
	40.00000	Required	Provided	MR		
	48.54 Epige-Interes	Required	Provided	MR		
	> Access to tank		Provided	MR		
	Overhead Tank capacity	20,000ltr Required	Provided	MR		
5	Exit Signage.	Required				

	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car Fireman's Grounding Switch Lift Signage	NΛ	NΛ	NΛ		
		NΛ	NΛ	NΛ		
		Required	Provided	MR		
7	Standby power supply	Required	Provided	MR		
18	Refuge Area.					
	> Total Area	N/A	N/A			
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
.,	Detector System Panel	N/A	N/A	1977		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
		NA NA	NA	NΛ		
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA.				

Note:-

(a) The total covered area of the first floor Restaurant is 110sqm (Approx) including scating arca, toilet arca, kitchen arca,

(b) As per the NBC Part IV, the number of occupants comes out to be approx 61 person's i.e.

The fire protection systems provided in the building were tested/ checked and found in working order at the time of inspection. The observations/ shortcomings issued and communicated vide this department letter of even no. F6/DFS/MS/2023/E11/453 dated: 22.08.2023 have been compiled by the

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire management. safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name :- C.I.. Meena

Designation:- Asst. Div. Officer (RN)

Dy. Chief Hire Officer ()