

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/EH/2023/SZ/337

Dated: 14/11/2023

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s **L.R Enterprises** located at 15 & 16, 1st Floor, J-Block Market, Saket, New Delhi-110017 comprised of Ground plus two upper floors was issued FSC by this department vide letter No. F6/DFS/MS/EH/2020/SZ/155 Dt. 05/11/2020. The premise was re-inspected by the officer concerned of this department on 06/11/2023 in the presence of Mr. Rohan Gupta and observed that the said building have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class-D "**Assembly Building**" (Restaurant) and **validity upto 31/03/2026** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 14/11/2023 at New Delhi by


(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to: -

1. The DHO (Green Park Zone), MCD, Health Department, Green Park, New Delhi-110016. (Ref. MHA Portal No. 2023101817431 dated 19/10/2023)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

INSPECTION REPORT

INSPECTION REPORT

1	Name & Address of the Building	M/s L. R Enterprises located at 15 & 16, 1 st Floor, J-Block Market, Saket, New Delhi-110017		
2	Type of Occupancy	Assembly Building "Group-D"(Restaurant)		
3	Building Comprised of	Ground plus two upper floors.		
4	Type of Case	Renewal / Name Change		
5	Details of Previous NOC	F6/DFS/MS/EH/2020/SZ/155 Dt. 05/11/2020		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	06/11/2023		
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Rohan Gupta		
10	Year of construction	1980	Restt. Running at first floor only.	
11	Applicant letter No.	Online No. 2023101817431 dated 19/10/2023		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old FSC Requirement	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	<ul style="list-style-type: none">Road widthGate widthWidth of internal road	Required	6m	MR
		N/A	N/A	N/A
		N/A	N/A	N/A
2	Number, width, type & arrangement of exits.			
	a) Number of Staircase			
	<ul style="list-style-type: none">➤ Upper floors.➤ Basement floor.	Required	01 No.	MR
		N/A	N/A	N/A
	b) Width of Staircase			
	<ul style="list-style-type: none">➤ Upper floors➤ Basement floor	Required	1.25m	MR (old case)
		N/A	N/A	N/A
	c) Protection of exits			
	<ul style="list-style-type: none">➤ Fire check door➤ Pressurization	N/A	N/A	N/A
		N/A	N/A	N/A
	d) No. of continuous staircase to terrace	N/A	N/A	N/A
	e) Width of corridor	N/A	N/A	N/A
	f) Door size	02 Nos	2m Provided	MR (old case)
3	Compartmentation.			
	<ul style="list-style-type: none">Fire check door.Sealing of electrical shafts.Fire rating of shaft door.Water curtainFire dampers.	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
4	Smoke Management system.			
	<ul style="list-style-type: none">BasementUpper floors	30 ACPH	N/A	N/A
		12 ACPH	Exhaust Fans	MR
5	Fire Extinguishers.			
	<ul style="list-style-type: none">Total numbersTypesISI Marking	08 Nos.	08 Nos.	MR
		ABC/W.CO ₂	ABC	MR
		ISI marked	Provided	MR
6	First Aid Hose Reels.			
	<ul style="list-style-type: none">Total numbers on each floor.Length of hose-reel hose.Nozzle Diameter	01 No.	01 No.	MR
		30m	30m	MR
		5mm	5mm	MR

h

7	Automatic fire detection & alarming system.			
	• Type of detectors	N/A	N/A	N/A
	• Location of Main Panel	N/A	N/A	N/A
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooter's location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System	N/A	N/A	N/A
10	Automatic Sprinkler System			
	• Basement	N/A	N/A	N/A
	• Upper floor	Required	Provided	M/R
	• Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.			
	• Size of Riser/Down-comer	100 mm	Provided	MR
	• Number of Hydrant per floor	01 No	Provided	MR
	• Hose box.	01 No	Provided	MR
12	Yard Hydrants.			
	• Total number of hydrants.	N/A	N/A	N/A
	• Hose box.	N/A	N/A	N/A
13	Pumping arrangements.			
	• Ground Level			
	➤ Discharge of main pump.	N/A	N/A	N/A
	➤ Head of main pump.	N/A	N/A	N/A
	➤ Number of main pumps.	N/A	N/A	N/A
	➤ Jockey Pump output.	N/A	N/A	N/A
	➤ Jockey Pump head.	N/A	N/A	N/A
	➤ Standby Pump output.	N/A	N/A	N/A
	➤ Standby Pump head.	N/A	N/A	N/A
	➤ Auto Starting/Manual Stopping.	N/A	N/A	N/A
	➤ Pump house access.	N/A	N/A	N/A
	• Terrace Level			
	➤ Discharge of pump.	450 LPM	450 LPM	MR
	➤ Head of pump.	38m	38m	MR
	➤ Power supply.	Required	Provided	MR
	➤ Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.			
	• Underground tank capacity.	N/A	N/A	N/A
	➤ Draw-off connection.	N/A	N/A	N/A
	➤ Fire Service Inlet.	Required	Provided	MR
	➤ Access to tank.	N/A	N/A	N/A
	• Overhead tank capacity.	5,000 Ltrs	5,000 Ltrs	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	• Pressurization of lift shaft.	N/A	N/A	N/A
	• Pressurization of lift lobby.	N/A	N/A	N/A
	• Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	• Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	• Total area	N/A	N/A	N/A

N/20

	• Location	N/A	N/A	N/A
19	Fire Control Room.			
	• Detector system panel.	N/A	N/A	N/A
	• Flow switch panel.	N/A	N/A	N/A
	• PA system panel.	N/A	N/A	N/A
	• Battery backup.	N/A	N/A	N/A
	• Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2020/SZ/155 Dt. 05/11/2020, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

meish

Signature of the Inspection Officer
Name: Sh. Manoj Kumar Sharma
Design: DO (South)

16/11/23

Signature of the Inspecting Officer
Name: Sh. Rajesh Kumar
Design: ADO (BCP)

CFO
9/11/2022
Director
10/11/23
Approved

As approved, F.T. letter is put up for
your signature pl

Director
13/11/23
my

16/11/23

Uploaded
14/11/23