



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/EH/WZ/2023/ 334

ľ

Dated: 09 / 11 /2023

FIRE SAFETY CERTIFICATE

Certified that the M/s. Sunshine Cuisine located at Shop No.- DE.84, Upper Ground Floor, Tagore Garden, New Delhi- 110027, running at Upper Ground Floor, in a building comprised of Basement + stilt + Upper Ground + 03 Upper Floor. Owned/Occupied by M/s. Sunshine Cuisine, the building/premises was inspected by the officer concerned of this department on 08/11/2023 in the presence of Sh. Manmohan singh and found that the said premises/building have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises/building is fit for occupancy class "Assembly" (Group - D) and validity upto 31/03/2026 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010. Conditions Printed Overleaf.

Issued on ... 9. 11 . 2023. at New Delhi by.

Copy to: -

1. The owner/occupier, M/s. Sunshine Cuisine Located at Shop No. DE.84, UGF, Tagore Garden, New Delhi- 110027. Online Application ID No. 2023102217627

 The Joint Commissioner of Police, Licensing Unit, 1st floor, Police Station, Defence Colony, New Delhi. (addlcp.lic-dl@nic.in.)

 The Dy. Health Officer, SDMC, West Zone, Vishal Enclave, Rajouri Garden, New Delhi 110027. (dhowest zone@gmail.com)

	Name & address of the building	M/s Sunshine Cuisine Located at Shop No. DE.84, Upper Ground Floor, Tagore Garden, New Delhi- 110027.											
2.	Type of Occupancy	Assembly/ Restaurant											
4 Details of		New											
							5 Fire Cofety di			Nil			
Date of inspection Name of the Inspecting Officers		Nil 08/11/2023 Sarabjeet Singh ADO (MN) Sh. Manmohan Singh											
							9.	Year of Construction	2016 (As per MHA Portal)				
							10	10. Applicant's letter No.		Online Application ID No. 2023102217627 dated 22/10/2023			
The	Said Restaurant is running at Up	per	Ground floor in a	Building Comprised of	Basement -								
S.	+ Upper Ground + 03 upper floors Minimum Standards on fire	s.	BBL /NBC	Provided at site	Remarks								
No.	prevention and fire safety U/R 3	3	Requirement	110vided at site	MR/NMR								
1	Access to building												
	Road width		12 m	Provided	MR								
	Gate width		4.5m	On Main Road	MR								
25 25	Width of internal road		NA	NA	NA								
2	Number, Width, Type & Arrangemen		nt of Exits										
	a. Number of staircases		02	02	MR								
	• Upper Floors		NA NA										
	Basements b. Width of staircases		NA	NA	NA								
	Upper Floors Basements Fire check door Pressurization e. No. of continuous staircases to terrace f. Width of Corridor g. Door Size		1.50m X 2	3 X 1.50m Provided	MR								
			NA NA	NA NA	NA NA								
			144	NA.	INA								
			Required	Provided	MR								
			NA	NA	NA								
			01	Provided	MR								
			NA	NA	NA								
			1.50m X 2	3 X 1.50m Provided	MR								
3	Compartmentation.			Family of a									
	Fire check door		NA	NA	NA								
	Sealing of electrical shafts Fire Rating of shaft door Water Curtain		NA	NA	NA								
			NA	NA	NA								
			NA	NA	NA								
	Fire Dampers		NA	NA	NA NA								
4	Smoke Management System.			I MA									
	Basements		NA	NA	NA								
	Upper floors		Required	Provided									
5	Fire Extinguishers		4.02	Flovided	MR								
	Total numbers Types IS marking		05	D	100000								
			O5 CO ₂ , ABC type ISI marked	Provided	MR								
				Provided	MR								
				Provided	MR								

6	First-Aid Hose Reels.							
	Total numbers on each floor	01	Provided	MR				
	 Length of hose reel hose 	30m	Provided	MR				
	Nozzle diameter	5mm	Provided	MR				
7	Automatic fire detection and alarming system.							
	 Type of detectors 	NA NA	NA NA	NA NA				
	 Location of Main Panel 	NA NA	NA NA	NA NA				
	 Location of Repeater Panel 	NA NA	NA NA	NA.				
	Alternate source of power Hooters' Location	NA NA	NA	NA				
		Required	Provided	MR				
8	MOEFA	NA	NA	NA.				
9	Public Address System.		(1000)					
10	Automatic Sprinkler System.	T NA T	NA	NA				
	Basement	NA NA	NA NA	NA				
	Upper Floor	NA NA	NA NA	NA				
	Sprinkler above false ceiling	l MA	.,,,	1,1.1				
1	Internal Hydrants	100 mm	Provided	MR				
	Size of riser/down-comer	100 mm	Provided	MR				
	Number of hydrants per floor Hose Box	1	Provided	MR				
2	Control Contro	1	Tiovided	1 1111				
2	Yard Hydrants.	NA I	NA	NA NA				
	Total number of hydrants	NA NA	NA NA	NA NA				
	Hose Box	NA	NA	NA				
3	Pumping Arrangements.	r						
- 1	Ground Level							
	Discharge of main Pump	NR	NR	NR				
	> Head of Main pump	NR	NR	NR				
	Number of main pumps	NR	NR	NR				
- 1	Jockey Pump out put	NR	NR	NR				
	> Jockey pump head	NR	NR	NR				
	Standby Pump out put	NR	NR	NR				
	 Standby Pump Head Auto Starting/ Manual stopping 	NR	NR	NR				
	Pump House Access	NR	NR	NR				
		NR	NR	NR				
	Terrace level	4501						
	Discharge of pump	450lpm	Provided	MR				
	 Head of the pump Power Supply 	40 m	Provided	MR				
	Supply	Required	Provided	MR				
+	or pump	Required	Provided	MR				
+	Captive Water Storage for fire fighting.							
	Underground tank capacity	NR	NR	NR				
	▶ Draw-off connection	NR	NR	NR				
	Fire service inlet	NR	NR	NR				
	Access to tank	NR	NR	NR				
+	Overhead Tank capacity	20,000 ltrs	Provided	MR				
F	Exit Signage.	Required	Provided	MR				

		NS					
16	Provision of Lifts.						
	Pressurization of Lift Shaft	NA	NA	NA			
	Pressurization of Lift lobby	NA	NA	NA			
	Communication In lift Car	NA	NA	NA			
	Fireman's Grounding Switch	NA	NA	NA			
	Lift Signage	NA .	NA	NA			
17	Standby power supply	Required	Provided	MR			
18	Refuge Area.						
	> Total Area	NA	NA	NA			
	> Location	NA	NA	NA			
19	Rire Control Room						
	Detector System Panel	NA	NA	NA			
	 Flow Switch Panel PA System Panel Batter backup Building Floor Plans 	NA	NA	NA			
		NA	NA	NA			
		NA	NA	NA			
		NA	NA	NA			
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA			

The fire protection systems provided in the building were test checked and found functional at the time of inspection. All the shortcomings issued by this department have been complied by the management of eating house.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

(Ay cryluse)

Signature of the Inspecting Officer

Name: - Sarabjeet Singh Designation: - ADO (MN)

J. Blukey

8/1

8/1 (202)

Dineeta

allin