GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/GH/2021/ 84

Dated : 11 02 251

FIRE SAFETY CERTIFICATE

Certified that the Hotel Florence located at 2719, Bank Street, Karol Bagh, New Delhi comprised of Basement + Ground + 03 Upper floors, Basement (other property), Ground floor (Reception + shops), 1st floor to 3rd floor (08 guest rooms at each floor), total 24 guest rooms was granted FSC by this department vide letter No.F6/DFS/MS/GH/2017/NDZ/1458 dated 06/10/17. The premises was re-inspected by the officer concerned of this department on 01/02/21 in the presence of Mr. Prashant and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 as Ground floor (Reception + shops), 1st floor to 3rd floor (08 guest rooms at each floor), total 24 guest rooms only with effect from -11/02/2021-for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below. (Framer

Issued -11 02 2021 at New Delhi by.

(Dr. S. K. Tomar) Dy. Chief Fire Officer Delhi Fire Service

Copy to:

The Joint Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi ref. Id No 2021011309630 dated 13/01/21.

Hotel Florence at 2719, Bank Street, Karol Bagh, New Delhi. 2. The Manager,

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT Name & address of the building Hotel Florence at 2719, Bank Street, Karol Bagh, New Delhi 2. Type of occupancy: -Residential, Sub Division-A-1 B + Gr. + 03 Upper floors (total 24 Guest rooms) Basement (other property). Ground floor (Reception + Shops), 1st floor to 3rd floor (08 guest rooms at each floor). Type of case: -Renewal Details of previous FSC:-No. F6/DFS/MS/GH/2017/NDZ/1458 dated 06/10/17. Fire safety directives No.-N/A Date of inspection:-01/02/21 Name of the inspecting officer:-Sh. Ravinder Singh (ADO/CC) Name & designation of officer from the building side:-Mr. Prashant 9. Year of construction:-2000-2001 10. Applicant's letter No1... Id No 2021011309630 dated 13/01/21. Building is comprised of basement, ground and three upper floors and 01 store room at terrace floor which is not in use as per affidavit submitted by applicant Old Case Requirement/ Minimum Standards on fire Provided at site Remarks Existing fire Prevention and fire safety MR/NMR safety arrangements Access to Building 1. 1) Road width N/A 12 mtr. N/A 2) Gate width N/A N/A N/A 3)Width of internal road N/A N/A N/A Number, Width Type & Arrangement of Exits 2. A. Number of staircases MR, Old case 1. Upper floors 01 Nos. 01 Nos. MR, Old case 01 Nos. 01 Nos. 2. Basements B. Width of staircase MR, Old case 1.25 mtr. 1.17 mtr. 1. Upper floors MR, Old case 1.0 mtr. 2. Basements 1.25 mtr. C. Protection of exits 1. Fire check door Required Provided MR(as per Notification dt 27.05.19 N/A N/A N/A 2. Pressurization 01 01 D. No. of continuous MR staircase to terrace N/A 115 cm, 150 cm N/A E. Width of corridor F. Door size N/A 85 cm x 205cm NA Compartmentation 3. N/A N/A N/A 1) Fire check door sealed N/A N/A 2) Sealing of electrical shafts N/A N/A N/A Fire rating of shaft door N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers Smoke Management System 4. Exhaust fan MR 1) Basements 30 ACPH MR 12 ACPH Natural 2) Upper floors Fire Extinguishers 5. 10 Nos. MR 10 Nos 1) Total numbers ABC & CO2 ABC & CO2 MR 2) Types Required Provided MR 3) ISI marking First-Aid Hose Reel 6. MR 1) Total number of eachfloor 01 30 mtr. MR 30 mtr. 2) Length of hose reel hose MR 05 mm 05 mm 3) Nozzle diameter Automatic Fire Detection & Alarming System Provided MR(as per Required 1) Type of detectors CO type Notification

1111

6

				dt 27.05
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power		D.G. set 120 KVA	MR
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System		110.100	
10.	1) Basement	Required	Provided	MR
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor	IN/A	1071	1
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants	IVA	IVA	1.77
12.	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A N/A	N/A N/A	N/A
13.	- In the second	17/74	10//	11//
13.	Pumping Arrangement 1) Ground level	N/A	N/A	N/A
				N/A
	a) Discharge of main	N/A	N/A	N/A
	pump	N// A	N1/A	NI/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main	N/A	N/A	N/A
	pump	NUA	N7/A	11/4
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
		N/A		N/A
	h) Auto starting/Manual	N/A	N/A	NA
	stopping 2) Terrace level		-22.1	+
		450 LPM	450 LPM	MR
	a) Discharge of pump	30 mtr.	30 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
14.	Captive Water Storage for Fir	e Fighting		
	Under ground tank capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank	5000 ltr.	5000 ltr.	MR
_	capacity			
5.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	Required	Provided Provided	MR MR
	d) Fireman's switch	Required	Provided	MR
	e) Lift signage	Required	Provided	MR
	Stand by Power Supply	Required	N/A	N/A
8.	Refuge Area Total area location	N/A N/A	N/A N/A	N/A N/A

19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	Required	Provided	MR
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			N/A

The fire protection systems provided in the building were randomly tested, and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention ire safety measures as required under the rules the FSC issued vide letter no.' S/MS/GH/2017/NDZ/1458 dated 06/10/2017 renewal under rule 35 of the Delhi Fire e rules 2010, is recommended.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

Docco)

\$\frac{1}{31}

\text{Deco}

at and supralmoph

Dycho (MDZ)

M.s.cf " upwaded

M shore