

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

F.6/DFS/MS/EH/2023/SZ/ 3 40 No.

Dated 16/11/2023

## FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s Haldiram Marketing Pvt Ltd located Shop No 19 A & 19 B-21, 22, Ground Floor, Vasant Square Mall, Plot No A, Sector-B, Pocket-V, Commercial Complex Community Centre, Vasant Kunj, New Delhi-110070 in the building comprised of Two tier Basement, lower ground, upper ground plus 03 upper floors owned/occupied by M/s Haldiram Marketing Pvt Ltd have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of department on 08/11/2023 in the presence of Mr. Rahul (Manager) and that the premise is fit for occupancy class Group-D Assembly (Eating House at Ground Floor only) and Validity upto 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 16 / 11 /2023 at New Delhi by

DELMI FIRE SERVICE

Copy to: -

1. The DHO, (Green Park), MCD, Public Health Department, Aurobindo Marg, Green Park, New Delhi-110016 (Ref. MHA Portal Id 2023102417664 dated 27/10/2023)

## Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire-fighting system.

4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016),

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."



-		Tall American				
1	INSPECT	TION REPORT	white the second			
	Name & Address of the Building	M/s Haldiram Marketing Pvt Ltd located Shop No 19A-19B-21, 22, Ground Floor, Vasant Square Mall, Vasant Kunj, New Delhi-110070				
2	Type of Occupancy	Assembly Build	ding Restaurant at Ground	floor only		
3	Building Comprised of	Assembly Building Restaurant at Ground floor only Two tier Basement, lower ground, upper ground plus 03 upper floors				
4	Type of Case	New Case				
5	Details of Previous NOC	Nil	THE PERSON NAMED IN COLUMN	362		
6	Fire Safety Directives Letter No	F.6/DFS/MS/BP/2005/2251 dated 28/10/2005 F.6/DFS/MS/Mall/2022/SZ/CMT/566 Dated 13/12/2022 (Vasant Square Mail NOC)				
7	Date of Inspection	08/11/2023				
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)				
9	Name & Designation of Officers from the building side	Mr. Rahul (Manager)				
10	Year of construction	2008				
11	Applicant letter No.	MHA Portal Id	2023102417664 dated	127/10/2023		
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirement/ Existing Fire	Provided at Site	Remarks MR/NMR		
7040	Access to Building. FSC No. F.6/DFS/MS/	Protection	4T/566 Dated 13/12/2022	Vasant Square		
1		09 m	Provided *	MR		
	Road width	05 m	Provided *	MR		
	Gate width	05 m	Provided *	MR		
	Width of internal road		Tiorided	,		
2	Number, width, type and arrangements of exits.  Provided & Maintained by Vasant Square Mall					
5	a. Number of Staircase		Restt. at Ground floor	N/A		
	Upper floors	N/A	N/A	N/A		
	Basement floor	1071				
	b. Width of Staircase	Provided & Maintained by Vasant Square Mall				
	Upper floors	N/A	N/A N/A	N/A N/A		
	Basement floor	N/A				
	c. Protection of exits	The state of the s	Maintained by Vasant			
	Fire check door	Required	Provided *	MR		
	Pressurization	N/A	NA	N/A		
	d. No. of continuous staircase to terrace	N/A	N/A	N/A		
	e. Width of corridor	N/A	N/A	N/A		
	f. Door size	1.50 m each	1.50m & 1.50m	MR		
3	Compartmentation.		Maintained by Vasant			
	Fire check door.	Required	Provided *	MR		
3	Sealing of electrical shafts.	Required	Provided *	MR		
	Fire rating of shaft door.	2 hrs	Provided*	MR		
	Water curtain	N/A	N/A	N/A		
	Fire dampers.	N/A	N/A	N/A		
l	Smoke Management system.	Provided &	Maintained by Vasant			
	Basement	Required	Exhaust fans provided	MR		
	Upper floors	Required	Exhaust fans provided	MR		
-	Fire Extinguishers.		provided			
	Total numbers	04 Nos	06 Nos.	100		
		04 1408		MR		
	• Types	ISI marked	ABC-04, W.CO <sub>2</sub> -02	MR		
- 1	ISI Marking		Provided	MR		
	Plant Atd Uppe Peels	Provided & Maintained by Vasant Square Mall				
	First Aid Hose Reels.	Provided &	Otto	- dame o midii		
•	First Aid Hose Reels.  Total numbers on each floor.		01 in Restaurant	MR		
		Hose Reel	01 in Restaurant 30m			

7	Automatic Fire Detection and Alarmin			
	Type of detectors	Required	State of the second sec	MR
	Location of Main Panel	Required		MR
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	Required	Provided *	MR
	Hooter's location	Required	Provided *	MR
8.	MOEFA	Required	Provided *	MR
9.	Public Address System	Required	Provided *	MR
10.	Automatic Sprinkler System		& Maintained by Vasan	nt Square Mall
10.	Basement	Required	Provided *	MR
	Ground floors	Required	Provided in Restt.	MR
	Sprinkler above false ceiling	N/A	N/A	N/A
			& Maintained by Vasan	985 1985 198
11.	Internal Hydrants.     Size of Riser/Down-comer	Required	Provided *	MR
		Required	Provided *	MR
	Number of Hydrant per floor	Required	Provided *	MR
	Hose box.		TO BE TO A DESCRIPTION OF THE SECOND OF THE	
12.	Yard Hydrants.		& Maintained by Vasant As above	N/A
	Total number of hydrants.	N/A		
	2. Hose box.	N/A	As above	N/A
13.	Pumping arrangements.			- 1-II
7117	Ground Level	1 Post I Merker To	& Maintained by Vasant	
	> Discharge of main pump.	4500 LPM	Provided *	MR
	Head of main pump.	60 mtr	Provided *	MR
	Number of main pumps.	Two	Provided *	MR
	> Jockey Pump output.	2 x 180 LPM		MR
	> Jockey Pump bead.	60 mtr	Provided *	MR
	> Standby Pump output.	4500 LPM	Provided *	MR
	> Standby Pump head.	60 mtr	Provided *	MR
	> Auto Starting / Manual Stopping.	Required	Provided *	MR
	> Access to pump house	Required	Provided *	MR
	The Branch and Control of the Contro	Provided &	& Maintained by Vasant	Square Mall
	Terrace Level	N/A	N/A	N/A
	Discharge of pump.	N/A	N/A	N/A
	> Head of pump.	N/A	N/A	N/A
	> Power supply.	N/A N/A	N/A	N/A
	> Auto starting of pump.	N/A	k Maintained by Vasant S	TO THE SECOND SE
14.	Captive water storage for Fire Fighting.		Provided *	MR
	Underground tank capacity.	2,50,000 Ltr	Provided *	MR
	> Draw-off connection.	Required	Provided *	MR
- /	> Fire Service Inlet.	Required		MR
- /	> Access to tank.	Required	Provided *	MR
	Overhead tank capacity.	30,000 Ltr	Provided *	MR
15.	Exit Signage.	Required	Provided Vocant S	
16.	Provision of Lifts.		Maintained by Vasant S	Square Mall N/A
	Pressurization of lift shaft.	N/A	N/A	C-100 AVV
1	Pressurization of lift lobby.	N/A	N/A	N/A
1	Communication in lift car.	N/A	N/A	N/A
- 1	Fireman's switch.	N/A	N/A	N/A
	Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided (DG Set)	MR
18.	Refuge Area			
10.		N/A	N/A	N/A
	Total area		N/A	N/A
	Location	N/A		200000000
19.	Fire Control Room.	Provided &	Maintained by Vasant Sq	
-	Detector System Panel.	N/A	N/A	N/A

1.14

		NIZ	MINITED BY	थी == दो महारेत्सम	
	Flow Switch Panel.	T 390 T	N/A	I N/A	
	PA system Panel.	N/A N/A	N/A	N/A	
	Battery backup	N/A	N/A	N/A	
	Building floor plan	N/A	N/A	N/A	
20.	Special Fire Protection System for the	N/A	N/A	N/A	
Note:-	Provided & Maintained by Managemen	nt of Vasant Square	Mall, Vasant Kunj	, New Delhi	
	The fire protection system provided nal at the time of inspection.  Keeping in view of the substantially	in the building v	vere randomly cho	cked and for	
fire pre	vention and fire safety measures as req	satisfactory comp	les it is recommen	ded to issue I	
Safety	Certificate under rule 35 (3) of the Delhi	Circ Canada Dules	2010		
	Accordingly, DEA	rite Service Rules			
	Accordingly, DFA is put up for approva	I and signature pic	ase.	23 -	
	0	dingly, DFA is put up for approval and signature please.			
	Merch		1 28/4		
Signatu	re of the Inspection Officer	Sign	nature of the Inspec	ting Officer	
	Sh. Manoj Kumar Sharma	5.5	Name: Sh. Ra	iesh Kumar	
		Design: ADO (BCP)			
Design	DO (South)		Design.	ADO (Del )	
о но Де	13/11 2023 Dérector M	X11118	·		
	As approved,	6.7.	- letter is	fordi	
	for your	signature	ρ' \	14	

१५/11/3