

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F.6/DFS/MS/Indl./2023/SZ/ 572

Dated: 30/.11.../2023

FIRE SAFETY CERTIFICATE

Certified that the Plot No- J-4, Green Park, Extension, New Delhi 110020 comprised of Basement, Stilt, Ground plus Three Upper Floors owned/ occupied by Mr. Joginder Kumar Goyal & Mrs. Punam Goyal have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and verified by the officers concerned of this department on 24/11/2023 in the presence of Mr. Jayshanker (JE/Bldg) MCD and found that the said building / premises is fit for occupancy class Mercantile Building with effect from 30 / 11 /2023 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on .30 J.11../2023 at New Delhi by

DIRECTOR

DELHI FIRE SERVICE

Copy to:

The Executive Engineer (Bldg) HQ, SDMC, 9th Floor Civic Centre, Minto Road, New Delhi 110002. (Ref. Online ID 10103576)

Conditions for the validity of the safety certificate:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

2. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning

3. The certificate may not be treated in any case for the regularization of the unauthorized

4. The basement shall be strictly in accordance with the provision of UBBL- 2016.

5. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its

6. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.



1	Name & Address of the Building	ON REPORT			
2	Type of Occupancy		en Park, Extension, 1	New Delhi.	
3	Building Comprised of	Mercantile Buildi			
4	Type of Case		Ground plus Three U	pper Floors	
5	Details of Previous NOC	New Case			
6	Fire Safety Directives Letter No	Nil			
7	Date of Online Inspection		023/249 dated 07/07/20)23	
8	Name of the Inspecting Officers	23/11/2023	- 1 - 111 111 - 111		
9	Name & Designation of Officers from the building side	DO (South) & ADO (BCP) Mr. Jayshanker (JE/Bldg) MCD			
10	Year of construction	2023	2048 (1971) - 1952 (1	at a second	
11	Applicant letter No.	Online ID 10103576 dated 21/11/2023			
S. No	Minimum standards on Fire Prevention	UBBL-2016	Provided at Site	-	
	and Fire Safety U/R 33	requirement	Provided at Site	Remarks MR/NMR	
1	Access to Building.		All Application	1/ 1 -51 1	
	Road width	09 mtr	24 mtr	MR	
	Gate width	06 mtr	06 mtr	MR	
	Width of internal road	N/A	N/A	N/A	
2	Number, width, type & arrangement of exits		and and the second		
	a. Number of Staircase	00311	INTERNAL DESAME 16	l vm	
	Upper floors Basement floor	02 No's	02 No's	MR	
	b. Width of Staircase	02 No's	02 No's	MR	
	Upper floors	1.50 mtr each	1.50 mtr each	MR	
	Basement floor	1.50 mtr each	1.50 mtr each	MR	
	c. Protection of exits	1.50 ind cach	1.50 mu cach		
	Page Contract Action (Contract)	Required	Provided	MR	
	Fire check door Pressurization	NA	NA NA	NA NA	
	d. No. of continuous staircase to terrace	7/(07)	Provided	MR	
	e. Width of corridor	Required NA	NA	NA NA	
		139723	A te SUBSECTION A	MR	
	f. Door size	1.50 mtr	1.50 m	MK	
3	Compartmentation.	210	The scale of the state of	1.00	
	Fire check door.	Required	Provided	MR	
	Sealing of electrical shafts.	Required	Provided	MR	
	Fire rating of shaft door. Water curtain	Required	Provided	MR	
	Water curtain Fire dampers.	N/A N/A	N/A N/A	N/A N/A	
102	The Art of the Control of the Contro	N/A	N/A	N/A	
4.	Smoke Management system. Basement	12 ACPH	Provided	MR	
	Upper floors	12 ACPH	Provided	MR	
5,	Fire Extinguishers	12 moral	III pinda jiin ilika		
٥,	Total numbers	25 Nos	30 Nos	MR	
	Types	ABC / Co2	Provided	MR	
	ISI Marking	ISI Marked	Provided	MR	
6.	First Aid Hose Reels.	00	D23-4	MD	
	Total numbers on each floor.	02 at each floor	Provided	MR	
	Length of hose-reel hose.	30 m	Provided	MR	
	Nozzle Diameter	5 mm	Provided	MR	
7	Automatic Fire Detection & Alarming		11-1-5	N7/4	
	Type of detectors	N/A	N/A	N/A N/A	
		N/A	N/A	N/A	

	Location of Main Panel	N/A	N/A	
	Location of Repeater Panel	N/A N/A	N/A N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
	MOEFA (Including Talk Back)	Required	Provided	MR
•	Public Address System	N/A	N/A	N/A
0.	Automatic Sprinkler System		er and solid)	-
	Basement	Required	Provided	MR
	Stilt floor	Required	Provided	MR
	 Sprinkler above false ceiling 	N/A	N/A	N/A
11.	Internal Hydrants.		1.1418 11.61	
	Size of Riser / Down-comer	Required	Provided	MR
-11	Number of Hydrant per floor	Required	Provided	MR
III to	Hose box.	Required	Provided	MR
2.	Yard Hydrants.		Transma en Reserv	
	Total number of hydrants.	N/A	N/A	N/A
3.	Hose box. Pumping arrangements.	N/A	N/A	N/A
٠.	Ground Level	Casa	energy to the latter of	
	Discharge of main pump.	N/A	N/A	N/A
	> Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
	> Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	 Standby Pump head. Auto Starting / Manual Stopping. 	N/A N/A	N/A N/A	N/A
	> Pump House Access	N/A N/A	N/A N/A	N/A N/A
	Terrace Level	TVA	TAN ONLY IN	IVA
	Discharge of pump.	900 LPM	450 LPM	NMR
	> Head of pump.	40 m	Provided	MR
	Power supply.	Required	Provided	MR
	> Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for fire fighting. Underground tank capacity.	N/A	N/A	N/A
	 Underground tank capacity. Draw-off connection. 	N/A	N/A	N/A
	> Fire Service Inlet.	N/A	N/A	N/A
	> Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	30,000 Ltrs	30,000 ltrs	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.		X series and sec	1.00
	Pressurization of lift shaft.	Required	Provided	MR
	 Pressurization of lift lobby. 	Required	Provided	MR
	Communication in lift car.	Required	Provided	MR MR
	Fireman's switch.	Required	Provided Provided	MR
STA	Lift signage.	Required		MR
17	Standby Power Supply	Required	Provided (DG set)	MIK
18.	Refuge Area	270	N/A	N/A
	Total area	N/A N/A	N/A N/A	N/A
	• Location	N/A	1075	1
19.	Fire Control Room. • Detector System Panel.	N/A	N/A	N/A
	 Detector System Panel. 	130.73		1

	Building floor plan	N/A	N/A	N/A
(293)				
	Battery backup	N/A	N/A	N/A
•	PA system Panel.	N/A	N/A	N/A

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 221 dated 10/11/2023.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer

Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Design: ADO (BCP)

As approved, F.I. Letter is forther for your signature of