

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

F.6/DFS/MS/Hospital/2023/SZ/5 78 No.

Dated: 0.5/12../2023

## FIRE SAFETY CERTIFICATE

Certified that the Cloudnine Hospital located at Plot No A-18, Kailash Colony, New Delhi 110048 comprised of Basement, Stilt, Upper Ground plus Three Upper Floors owned/occupied by Kids Clinic India Ltd have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by officer concerned of this department on 29/11/2023 in presence of Mr. Naresh Dhas and that the building is fit for occupancy class "Institutional building" Group-C (Hospital) with effect from 05/12 /2023 for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued 05/12 /2023 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

1. M/s Cloudnine Hospital located at Plot No A-18, Kailash Colony, New Delhi 110048.

2. The Executive Engineer (Bldg)-1, Building Department, Green Park, New Delhi

## Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

The basement shall be used as per the provisions of UBBL-2016 /NBC Part- IV.

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL- 2016), if

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior



-	realite & Address of the Building	ON REPORT  Cloudnine Hospital, (Kids Clinic India Ltd) at Plot No A-18, Kailash Colony, New Delhi 110048.				
3	Type of Occupancy	Institutional building, "Group-C" (Hospital)				
	Building Comprised of	Basement, Stilt, Upper Ground + 03 upper floors				
4	Type of Case	New Case				
5	Details of Previous NOC	Nil				
6	Fire Safety Directives Letter No.	F6/DFS/MS/2023/BP/675 dated 10.04.2023				
7	Date of Inspection	29/11/2023				
8	Name of the Inspecting Officers		) (RCP)			
9	Name & Designation of Officers from the building side	DO (South) & ADO (BCP) Mr. Naresh Dhas				
10	Year of construction	2023				
11	Applicant letter No.	Outdoor diary no 6655 dated 27/09/2023				
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	requirements	Provided at Site	Remarks		
1	Access to Building.		MR/N			
	Road width	0-4- 1	20.40			
	Gate width	9 mtr	30.48 mtr	MR		
117	Width of internal road	06 mtr	06 mtr	MR		
2	Number, width tree &	-NA-	NA	-NA-		
-	Number, width, type & arrangement of exits.  a) Number of Staircase					
		ACT MAY A				
	> Upper floors.	03 Nos	Provided	MR		
	b) Width of Staircase	02 Nos	Provided	MR		
100	Upper floors	2 mtr & 1.50mtr	2 mtr & 2 x 1.50mtr	1/0		
	➢ Basement floor	2 mtr & 1,50mtr	2 mtr & 1.50mtr	MR		
	c) Protection of exits	Carlot Washington	a und de l'availle	MR		
	➤ Fire check door	Required	Provided	1/0		
	> Pressurization	-NA-		MR		
	d) No. of continuous staircase to terrace	Required	-NA-	-NA-		
	e) Width of corridor	2.4 mtr	Provided	MR		
100	f) Door size	1.25m & 2m	Provided	MR		
3	Compartmentation.	1.25111 & 2111	1.25 m & 2m	MR		
	Fire check door.	Required	Paguired			
	<ul> <li>Sealing of electrical shafts.</li> </ul>		Provided	MR		
	Fire rating of shaft door.     Water curtain	Required	Provided	MR		
		Required	Provided	MR		
	Fire dampers.	-NA-	-NA-	-NA-		
4.	The state of the s	-NA-	-NA-	-NA-		
-	Smoke Management system.		1000000	TIM-		
	Basement	12 ACPH	Exhaust fan Provided	MR		
5.	Upper floors  Fire Fetinguish	12 ACPH	Exhaust fan Provided			
3	Fire Extinguishers.  • Total numbers	Required	55 Nos			
	Types	ISI marked	ABC & Co2	MR		
	ISI Marking	Required		MR		
6.	First Aid Hose Reels.	required	Provided	MR		
- 04	Total numbers on each floor					
-		02 Nos at each	Provided	MR		
-	• I enoth aCharacter		U9-02-7-U3-1-3-7-4			
	Length of hose-reel hose.	30m	Provided	MD		
417	Nozzle Diameter	Smm	Provided			
7	Nozzle Diameter	Smm	Provided	MR . MR		
4 / 2 /		Smm				

	Location of Repeater Panel	-NA-	-NA-	-NA-
	Alternate source of power	Required	Provided	MR
	Hooter's location	Required	All Areas	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	-NA-	-NA-	-NA-
10.				
10.	Basement	Required	Provided	MR
	Upper floors	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11.				
	Size of Riser/Down-comer	100 mm	Provided	MR
	Number of Hydrant per floor	02 Nos	Provided	MR
	Hose box.	02 Nos	Provided	MR
12.	Yard Hydrants.			
	Total number of hydrants.	02 Nos	Provided	MR
	Hose box.	02 Nos	Provided	MR
13,	Pumping arrangements.	1		
	Ground Level			
	Discharge of main pump.	1620 LPM	Provided	MR
	> Head of main pump.	70 mtr	Provided	MR
	> Number of main pumps.		Provided	MR
	> Jockey Pump output.	01 No		
	> Jockey Pump head.	180 LPM	Provided	MR
	> Standby Pump output	70 mtr	Provided	MR
	Standby Pump head.	1620 LPM	Provided	MR
		70 mtr	Provided	MR
	Auto Starting/Manual Stopping	Required	Provided	MR
	➤ Pump house access.	Required	Provided	MR
	Terrace Level			
	<ul> <li>Discharge of pump.</li> <li>Head of pump.</li> </ul>	-NA-	-NA-	-NA-
	> Power supply.	-NA-	-NA-	-NA-
	Auto starting of pump.	-NA-	-NA-	-NA-
14.	Captive water storage for fire fighting.	-NA-	-NA-	-NA-
	Underground tank capacity.	1,50,000 Ltrs	Devided	3.45
	> Draw-off connection.	Required	Provided Provided	MR
	➤ Fire Service Inlet.	Required	Provided	MR
	Access to tank.	Required	Provided	MR
	<ul> <li>Overhead tank capacity.</li> </ul>	10,000 Ltrs	Provided	MR MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			IVEK
	Pressurization of lift shaft.	Required	Provided	MR
	<ul> <li>Pressurization of lift lobby.</li> </ul>	Required	Provided	MR
	Communication in lift car.	Required	Provided	MR
	Fireman's switch.	Required	Provided	MR
7.	Lift signage.	Required	Required	MR
8.	Standby Power Supply	Required	Provided (DG Set)	MR
0.	Refuge Area			
	Total area	-NA-	-NA-	-NA-
•	Location	-NA-	-NA-	-NA-
9,	Fire Control Room.			11/4-
	Detector system panel.	-NA-	-NA-	NIA
	Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel.	-NA-		NA-
		1111	-NA-	NA-

होसाव -NA--NA-Battery backup. -NA-Building floor plan. -NA--NA--NA-Special Fire Protection System for the Required LT, HT & MR Transformers provided Protection of special Risk, if any. with Co2 flooding The fire protection system provided in the building were randomly checked and found functional at the time of inspection. Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 1929 dated 06/09/2023. Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010 Accordingly DFA is put up for approval and signature please. Signature of the Inspecting Officer Signature of the Inspection Officer Name: Sh. Rajesh Kumar Name: Sh. Manoj Sharma Design: ADO (BCP) Design: DO (South) Anglows
As approved, F.1. cetter in portup for
your signature of 1/12/23