

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

F.6/DFS/MS/EH/2023/SZ/ 354 No.

Dated 05/12/2023

FIRE SAFETY CERTIFICATE

Certified that th Eating House in the Name & Style of M/s Nukkad Cafe And Bar located at Third Floor, HS-7, Kailash Colony Market, Delhi 110048 Comprised of Basement Ground plus Three upper floor owned/Occupied by A Unit Flying Sparrow Hospitality Pvt Ltd have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 29/11/2023 on in the presence of Mr. Kanishk Tuteja and found that the premise is fit for occupancy Group "D" (Assembly Building) and validity upto 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued on 05/12/2023 at New Delhi by

Copy to: -

1. The Dy. Health Officer, MCD, Public Health Department, Aurobindo Marg, Green Park, New Delhi-110016. (Ref. MHA Portal 2023111618538 dated 16/11/2023)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. The basement shall be used as per the provisions of UBBL 2016 /NBC Part- IV.

4. All the staff members must know the correct method of operation of fire fighting system.

5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first of Delhi Fire Service Rules 2010. form is available www.dfs.delhigovt.nic.in

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if

any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



आज़ादीक अमृत महोत्सव

	INSPECTIV	ON REPORT	and the second	_	
1 10	Cofe And Der (A	Unit Flyi			
	lame & Address of the Building	M/s Nukkad Cafe And Bar (A Unit Flyin Sparrow Hospitality Pvt Ltd) located at HS- Third Floor, Kailash Colony Market, Dell 110048			
2	Type of Occupancy	Restaurant at 3 rd floor only			
3	Building comprised of	Basement, Ground plus Three upper floors			
	Type of Case	New case			
	Details of Previous NOC				
	Fire Safety Directives Letter No	Nil			
		Nil			
	Date of Inspection	29/11/2023			
	Name of the Inspecting Officers	DO (South) & ADO (BCP)			
10.1	Name & Designation of Officers from the building side	Mr. Kanishk Tuteja			
10	Year of construction	2023			
11	Applicant letter No.	MHA Portal 2023111618538 dated 16/11/2023			
	Minimum standards on Fire Prevention and Fire Safety U/R 33	NBC/ UBBL 2016	Provided at Site	Remarks MR/NMR	
1	Access to Building.		The rail		
1	Road width	09 m	09 m	MR	
	Gate width	06 m	06 m	MR	
2	Width of internal road	NA	N/A	N/A	
- 111	Number, width, type & arrangement of e	exits	4		
97	Number of Staircase Upper floors	00.11			
199	Basement floor	02 No	02 Nos	MR	
ATT	b. Width of Staircase	-NA-	N/A	N/A	
7.316	Upper floors	1.50 mtr each	1.50 mtr & 1.60 mtr) AD	
177	Basement floor	-NA-	N/A	MR N/A	
377	c. Protection of exits		All Princes whereas	IVA	
75	Fire check door	-NA-	N/A	N/A	
JAN	Pressurization	-NA-	N/A	N/A	
	d. No. of continuous staircase to terrace e. Width of corridor		Provided	MR	
387	f. Door size	N/A 1.50 mtr each	N/A	N/A	
3	Compartmentation.	1.50 mir each	1.50 m each	MR	
	Fire check door.	274	A red section		
, Je	Sealing of electrical shafts.	-NA-	N/A	N/A	
	Fire rating of shaft door.	-NA-	N/A N/A	N/A	
	Water curtain	-NA-	N/A N/A	N/A N/A	
1 0	Fire dampers.	-NA-	N/A	N/A N/A	
4	Smoke Management system.	1 100		IVA	
	Basement	-NA-	N/A	277	
81	Upper floors	Required	Natural ventilation	N/A MR	
5	Fire Extinguishers.			IVIK	
	Total numbers	Required	08 Nos	MR	
	Types	ABC / CO2	ABC & Co2	MR	
6	ISI Marking First Aid Hose Books	ISI marked	Provided	MR	
0	First Aid Hose Reels. • Total numbers on each floor.	02.24	THE CO. THE P. T. L.	#4.	
	Length of hose-reel hose.	02 Nos 30m	Provided	MR	
	Nozzle Diameter	5mm	Provided Provided	MR	
7	Automatic fire detection & alarming system.		riovided	MR	
	Type of detectors	-NA-	Denvided a	NTA.	
I	And the second s	11/1-	Provided	-NA-	

N 100

				6.
	Location of Main Panel	-NA-	Provided	-NA-
	Location of Repeater Panel	-NA-	-NA-	-NA-
	Alternate source of power	-NA-	Provided	-NA-
S.A.	Hoofer's location	-NA-	Provided	-NA-
8	MOEFA	Required	Provided	MR
9	Public Address System	-NA-	-NA-	NA-
10	Automatic Sprinkler System			
1	Basement	-NA-	Provided	NA-
	Upper floors	-NA-	Provided	NA-
	Sprinkler above false ceiling	-NA-	-NA-	NA-
11	Internal Hydrants.	4		
	Size of Riser/Down-comer	Required	Provided	MR
	Number of Hydrant per floor	Required	Provided	MR
	Hose box.	Required	Provided	MR
12	Yard Hydrants.	quireu	Livided	
R)47	Total number of hydrants.	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
13	Pumping arrangements.		- 100 P	
	Ground Level	la la		
	➤ Discharge of main pump.	2280 LPM	Provided	MR
	➤ Head of main pump.	40m	Provided	MR
	Number of main pumps.	01	Provided	MR
	Jockey Pump output.	180 LPM	Provided	MR
	➢ Jockey Pump head.	40m	Provided	MR
	Standby Pump output.	2280 LPM	Provided at terrace	MR
	Standby Pump head.	40m	Provided	MR
	Auto Starting / Manual Stopping.	Required	Provided	MR
	> Pump House Access	Required	Provided	MR
	Terrace Level			
	 Discharge of pump. 	900 LPM	Provided	MR
	> Head of pump.	40 m	Provided	MR
	Power supply. Auto starting of pump	Required	Provided	MR
14	 Auto starting of pump. Captive water storage for Fire Fighting. 	Required	Provided	MR
	Underground tank capacity.	30 k UG + 70	1980 - 1981 - 1	
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	k Terrace	Provided	MR
	 Draw-off connection. Fire Service Inlet. 	Required	Provided	MR
	> Access to tank.	Required	Provided	MR
	Overhead tank capacity.	Required	Provided	MR
10	See Miller	10,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.		Wat a	
	 Pressurization of lift shaft. 	-NA-	-NA-	-NA-
	 Pressurization of lift lobby. 	-NA-	-NA-	-NA-
	 Communication in lift car. 	-NA-	-NA-	-NA-
	Fireman's switch.	-NA-	-NA-	-NA-
	1 A 1:A -:	274		
17	Lift signage. Standby Power Supply	-NA-	-NA-	-NA-

1



18	Refuge Area			
9	Total area	-NA-	-NA-	-NA-
	Location	-NA-	-NA-	-NA-
19	Fire Control Room.			
	Detector System Panel.	-NA-	-NA-	-NA-
	Flow Switch Panel.	-NA-	-NA-	-NA-
	PA system Panel. Battery backup Building floor plan	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any :	-NA-	-NA-	-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 624 dated 15/11/2023.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer

Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Design: ADO (BCP)

F.t. letter is fortife