



**FIRE SAFETY CERTIFICATE**

Certified that the Jeevan Anmol Hospital located at Mayur Vihar, Phase-1, Opp. Pratap Nagar, Delhi-110091, owned/ occupied by Jeevan Anmol Hospital comprised of Basement + Ground + Three upper floors, was granted FSC vide letter no. F6/DFS/MS/Hospital/2020/NDZ/311 dated 17/08/2020. The hospital building was inspected by the officer concerned of this department on 01.12.2023 in the presence of Mr. Jitender Sharma and found that the hospital building have deemed complied with the fire prevention and fire safety requirement in accordance with Rule 33 of the Delhi Fire Service Rule, 2010 and found that the building is fit for occupancy class "Institutional Building" Group -'C' with effect from 07/12/2023 for a period of three years, subject to condition, printed overleaf.

Issued on 07/12/2023 at New Delhi by.

(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE

**Copy to:-**

1. Dr. Neera Sondhi (Medical Superintendent), Jeevan Anmol Hospital located at Mayur Vihar, Phase-1, Opp. Pratap Nagar, Delhi-110091.
2. The Director General of Health Services M.O. I/C Nursing Home Cell, GNCT of Delhi, F-17, Karkardooma, Delhi-110032.

**Conditions for the validity of Fire Safety Certificate**

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
8. Basement shall be used as per NBC/UBBL.
9. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.



**INSPECTION REPORT**

1	Name & address of the building	Jeevan Anmol Hospital located at Mayur Vihar, Phase-1, Opp. Pratap Nagar, Delhi-110091.
2	Building is comprised of	Basement + Ground + 03 upper floors only.
3	Type of occupancy	Institutional Building Group 'C' Hospital
4	Type of case	Renewal
5	Details of previous FSC	F6/DFS/MS/Hospital/2020/NDZ/311 dated 17/08/2020
6	Fire safety direction letter no.	DFS Act 2007 & Rules 2010
7	Date of inspection	01.12.2023
8	Name of the inspecting officers	Yashwant Singh Meena (ADO/LN)
9	Name of the designation of officer From the building side	Mr. Jitender Sharma
10	Year of construction	2000
11	Applicant's letter no	Outdoor Diary No. 8932 dated 21/11/2023

S.No	Minimum Standards on fire Prevention and fire safety requirements U/R 33	Requirement as per NBC/UBBL	Provided at Site	Remarks MR/NMR	
1	<b>Access to building</b>				
	a	Road width	9.0 mtrs.	13 mtrs MR	
	b	Gate width	4.5 mtrs.	05 mtrs MR	
	c	Width of internal road	NA	NA NA	
2	<b>Number, Width, Type and Arrangement of Exits</b>				
	A	Number of staircases			
	a	Upper floor	02 nos.	02 nos. + 1 ramp	MR
		Basement	02 nos. + 1 ramp	02 nos. + 1 ramp	MR
	B	Width of staircases			
	a	Upper floor	2.0 mtrs	01 no. of 2.0 mtrs. & 01 no. of 1.80 mtrs. & 2.3 mtrs Ramp	MR ✓
		Basement	1.5 mtrs.	2.0 mtrs., 1.80 mtrs & 1.5 mtrs ramp	MR
	C	Protection of exits			
	a	Fire check door	Required	Provided	MR
		Pressurization	NA	NA	NA
	D	No. of continuous staircases to terrace	02 nos.	02 nos.	MR
	E	Width of corridor	2.0 mtrs	2.0 mtrs	MR
	F	Door size	1.0 mtr	1.0 mtr & 2.0 mtrs	MR
3	<b>Compartmentation</b>				
	a	Fire check door	Required	Provided MR	
	b	Sealing of electrical shafts	Required	Provided MR	
	c	Fire rating of shaft door	NA	NA NA	
	d	Water curtain	NA	NA NA	
	e	Fire dampers	NA	NA NA	
4	<b>Smoke Management System.</b>				
	a	Basement	Required	Provided MR	
	b	Upper floor	Required	Provided MR	

(u)



<b>5.</b>	<b>Fire Extinguisher</b>				
	a	Total numbers	20 nos.	52 nos.	MR
	b	Types	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	MR
	c	ISI marking	ISI marked	ISI marked	MR
<b>6</b>	<b>First-aid-Hose Reels.</b>				
	a	Total numbers of each floor	02 nos.	02 nos.	MR
	b	Length of hose reel hose	30 mtrs.	30 mtrs.	MR
	c	Nozzle diameter	05 mm	05 mm	MR ✓
<b>7</b>	<b>Automatic fire detection and alarming system.</b>				
	a	Type of detectors	Smoke	Smoke	MR
	b	Location of main panel	Required	Provided in fire control	MR
	c	Location of repeater panel	Required	Provided	MR
	d	Alternate source of power	Required	Provided	MR
	e	Hooters	Required	Provided near staircase	MR
<b>8</b>	<b>MOEFA</b>				
			Required	Provided	MR ✓
<b>9</b>	<b>Public address System.</b>				
			Required	Provided	MR
<b>10</b>	<b>Automatic Sprinkler System.</b>				
	a	Basement	Required	Provided	MR
	b	Upper floors	NA	NA	NA
	c	Sprinkler above false ceiling	NA	NA	NA
<b>11</b>	<b>Internal Hydrants</b>				
	a	Size of riser	100 mm	100 mm	MR
	b	Number of hydrants per floor	02 nos.	02 nos.	MR
	c	Hose Box	02 nos.	02 nos.	MR ✓
<b>12</b>	<b>Yard Hydrants.</b>				
	a	Total number of hydrants	NA	03 nos.	MR
	b	Hose Box	NA	03 nos.	MR
<b>13</b>	<b>Pumping Arrangements.</b>				
	A	Ground Level			
	a	Discharge of main Pump	1680 LPM	1680 LPM	MR
	b	Head of Main Pump	88 m	88m	MR
	c	Number of main pumps	01 nos.	01 nos.	MR
	d	Jockey pump out put	180 LPM	180 LPM	MR
	e	Jockey pump head	88 m	88m	MR
	f	Standby pump out put	1680 LPM	1680 LPM	MR
	g	Standby pump head	88 m	88m	MR
	h	Auto starting /manual stopping	Required	Provided	MR ✓
	i	Pump House Access	Required	Provided	MR
	B	Terrace Level			
	a	Discharge of pump	NA	NA	NA
	b	Head of the Pump	NA	NA	NA
	c	Power supply	NA	NA	NA
	d	Auto Starting of pump	NA	NA	NA

W


90



<b>14</b>	<b>Captive Water Storage for Fire Fighting.</b>				
a	Underground tank capacity	1,00,000 ltrs	1,00,000 ltrs	MR	
b	Draw-off connection	Required	Provided	MR	
c	Fire service inlet	Required	Provided	MR	
d	Access to tank	Required	Provided	MR	
e	Overhead Tank capacity	20,000 ltrs	25,000 ltrs	MR	
<b>15</b>	<b>Exit Signage.</b>		Required	Provided	MR ✓
<b>16</b>	<b>Provision of Lifts.</b>				
a	Pressurization of Lift Shaft	Required	Provided	MR	
b	Pressurization of Lift lobby	NA	NA	NA	
c	Communication in lift car	Required	Provided	MR	
d	Firemen's grounding switch	Required	Provided	MR	
e	Lift Signage	Required	Provided	MR	
<b>17</b>	<b>Standby power supply</b>		Required	Provided	MR
<b>18</b>	<b>Refuge Area.</b>				
a	Total area	NA	NA	NA	
b	Location	NA	NA	NA	
<b>19</b>	<b>Fire Control Room</b>				
a	Detector system panel	NA	NA	NA	
b	Flow switch panel	NA	NA	NA	
c	PA system panel	NA	NA	NA	
d	Battery backup	NA	NA	NA	
e	Building Floor Plans	NA	NA	NA	
<b>20</b>	<b>Special Fire Protection systems for protection of special Risks, if any:</b>		NA	Provided Local Application	NA

The fire protection system was randomly checked and tested and was found functional at the time of inspection. The shortcomings issued vide letter no. F6/DFS/MS/Hospital/NDZ/2023/4142 dated 03.11.2023 by this department have been rectified by the management.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, it is recommended to grant Fire Safety Certificate under Rules 37 of Delhi Fire Service Rules 2010.

  
 01/12/2023  
 Signature of the Inspecting Officer  
 Name: Yashwant Singh Meena  
 Designation: - ADO (L.N)

DY.CFO/NDZ

C.F.O.

6/11/2023

Director

6/12/23