



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No.F.6 DFS/MS/School/2023/SZ/875

Dated: 12 / 12 / 2023

FIRE SAFETY CERTIFICATE

Certified that the Bala Pritam Guru Harkrishan INT public School, located at Vasant Marg, Vasant Vihar, New Delhi 110037 comprised of Two building Blocks, Ground plus One upper floor & Ground plus Two upper floors owned/occupied by Bala Pritam Guru Harkrishan INT public School, have complied with the fire prevention and fire safety requirements accordance with Directorate of Education Circular F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 issued by Director of Education, Govt. of NCT of Delhi and verified by officer concern of this department on 01/12/2023 in the presence of Mr. Virendra Kumar Tiwari and that the school building is fit for occupancy Group -B "Educational Building" (School running at Ground and First Floor only) as above with effect from $\frac{12}{12}$ 2023 for period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules: 2010.

Issued on 12/12:2023 at New Delhi by

DIRECTOR

DELHI FIRE SERVICE

Copy to: -

 The Principal, Bala Pritam Guru Harkrishan INT public School, located at Vasant Marg, Vasant Vihar, New Delhi 110037

The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."



NIL

1	INSPECTION REPORT					
2783	Name & Address of the Building	Bala Pritam Guru Harkrishan INT public School, a Vasant Marg, Vasant Vihar, New Delhi 110037				
2	Type of Occupancy	Educational, Group-B (School)				
3	Building Comprised of	Two Building Blocks, Ground plus one upper floor & Ground plus two upper floor.				
4	Type of Case	New Case				
5	Details of Previous NOC	Nil New Case				
6	Fire Safety Directives Letter No		dated 01/03/2011			
7	Date of Inspection	01/12/2023				
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)				
9	Name & Designation of Officers from the building side	Mr. Virender Kumar Tiwari				
10	Year of construction	2000				
11	Applicant letter No.	BPGHIPS/DFS/2023/1050 dated 22/11/2023				
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	As per DOE Requirement	Provided at Site	Remarks MR/NMR		
1	Access to Building.					
	Road width	09 mtr	09 mtr	MR		
	Gate width	-NA-	NA	-NA-		
	Width of internal road	-NA-	-NA-	-NA-		
2	Number, width, type & arrangement of exits.					
	a) Number of Staircase		1			
	Upper floors.	A Block-02 Nos	02 No Provided	MR		
		B Block- 02 Nos	03 Nos Provided	MR		
	Basement floor.	-NA-	-NA-	-NA-		
	b) Width of Staircase					
	> Upper floors	1.50mtr/0.75mtr	A Blk- 1.21 mtr each B Blk - 1.21 mtr each	MR MR		
	➢ Basement floor	-NA-	-NA-	-NA-		
	c) Protection of exits					
	➤ Fire check door	-NA-	-NA-	-NA-		
	> Pressurization	-NA-	-NA-	-NA-		
	d) No. of continuous staircase to terrace	Required	Provided	MR		
	e) Width of corridor	1.50 mtr	Provided	MR		
	f) Door size	Required	Provided	MR		
3	Compartmentation.	Required	Tiovided	MIK		
	Fire check door.	-NA-	-NA-	-NA-		
47.	Sealing of electrical shafts.	-NA-	-NA-	-NA-		
Y" [Fire rating of shaft door.	-NA-	-NA-	-NA-		
	Water curtain	-NA-	-NA-	-NA-		
	Fire dampers.	-NA-	-NA-	-NA-		
4.	Smoke Management system.		1112	-NA-		
	Basement	-NA-	-NA-	-NA-		
	Upper floors	-NA-	-NA-	-NA-		
5.	Fire Extinguishers.		-140-	-NA-		
	Total numbers	20 Nos	40 Nos	MR		
	Types	ABC	ABC & Co2 Type	MR		
	ISI Marking	ISI mark	Provided	MR		
6.	First Aid Hose Reels.	tota himin	LIONINGO	I MK		
<u> </u>	Total numbers on each floor.	02 no each	Provided	100		
	Length of hose-reel hose.	30m	Provided	MR		
	Nozzle Diameter	5mm	Provided	MR		
7	Automatic fire detection & alarming system.	Juni	Flovided	MR		



N/13

आज़ादा के अमृत महोत्सव

	Type of detectors	-NA-	-NA-	-NA-
	Location of Main Panel	-NA-	-NA-	-NA-
	Location of Repeater Panel	-NA-	-NA-	-NA-
	Alternate source of power	-NA-	-NA-	-NA-
	Hooter's location	-NA-	-NA-	-NA-
8.	MOEFA	-NA-	-NA-	-NA-
9.	Public Address System	-NA-	-NA-	-NA-
10.	Automatic Sprinkler System			
	Basement	-NA-	-NA-	-NA-
	Upper floors	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11.	Internal Hydrants.	146		
	Size of Riser/Down-comer	-NA-	-NA-	-NA-
	 Number of Hydrant per floor 	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
12.	Yard Hydrants.			
	Total number of hydrants.	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
13.	Pumping arrangements.			
	Ground Level			
	 Discharge of main pump. 	-NA-	-NA-	-NA-
	Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	Jockey Pump output.	-NA-	-NA-	-NA-
	Jockey Pump head.	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	 Standby Pump head. 	-NA-	-NA-	-NA-
	Auto Starting / Manual Stopping.	-NA-	-NA-	-NA-
	> Pump house access.	-NA-	-NA-	-NA-
	Terrace Level			-IVA-
	Discharge of pump.	450 LPM	Provided	MR
	Head of pump.	40m	Provided	MR
	Power supply.	Required	Provided	MR
3117	Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for fire fighting.		Trovided	MIK
	 Underground tank capacity. 	-NA-	-NA-	-NA-
	Draw-off connection.	-NA-	-NA-	-NA-
	Fire Service Inlet.	-NA-	-NA-	The state of the s
	Access to tank.	-NA-	-NA-	-NA-
	Overhead tank capacity.	10,000 ltrs	Provided	-NA-
15.	Exit Signage.	Required	Provided	MR
6.	Provision of Lifts.	1	Tiovided	MR
	 Pressurization of lift shaft. 	-NA-	-NA-	1 227
	 Pressurization of lift lobby. 	-NA-		-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	Fireman's switch.	-NA-	-NA-	-NA-
	Lift signage.		-NA-	-NA-
7.	Standby Power Supply	-NA-	-NA-	-NA-
8.	Refuge Area	-NA-	-NA-	-NA-
	Total area			
	The state of the s	-NA-	-NA-	-NA-
•	• Location	-NA-	-NA-	
9.	Fire Control Room.			-NA
	Detector system panel.	-NA-		
		11/1-	-NA-	-NA

अमृत महोत्सव

NIM

	Flow switch panel.	-NA-	-NA-	-NA-
- 1	PA system panel.	-NA-	-NA-	-NA-
	Battery backup.	-NA-	-NA-	-NA-
	 Building floor plan. 	-NA-	-NA-	-NA-
20.	Special Fire Protection System for the Protection of special Risk, if any.	-NA-	-NA-	-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued &

communicated by this department vide letter of even no 557 dated 21/11/2023.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Name: Sh. Rajesh Kumar

Design: ADO (BCP)

DO (8D)

As approved, f.T. tetter is pully or your, signature ?!