



FIRE SAFETY CERTIFICATE

Certified that the M/s **The Frank Anthony Public School** located at **Lajpat Nagar- IV, New Delhi- 110024**, comprised of four blocks: **Junior Block** – Ground + 2 upper floors, **Middle Block** – Lower Ground + Upper Ground + 2 upper floors, **Senior Block** – Ground + 2 upper floors, **Admin/Olive Anthony block** – Ground + 2 upper floors, was granted Fire Safety Certificate (FSC) by this department vide letter no. F6/DFS/MS/School/2020/SZ/587 dated 30.12.2020. The school building was re-inspected by Assistant Divisional Officer (M. Road) from this department on 08.12.2023 in the presence of Mr. Dilip Kumar (Estate Manager) and found that the building/premises has deemed complied with the fire prevention and fire safety requirements in accordance with the circular no. 262-362 dated-17.01.2005 issued by the Directorate of Education and the building comprised of four blocks (**Junior Block** – Ground + 2 upper floors, **Middle Block** – Lower Ground + Upper Ground + 2 upper floors, **Senior Block** – Ground + 2 upper floors, **Admin/Olive Anthony block** – Ground + 2 upper floors) is fit for occupancy of Group B “**Educational Building**” with effect from 12/12/2023. renewed for a period of three years, subject to conditions printed below.

Issued on...12/12/2023...at New Delhi by.

(Atul Garg)

Director

Delhi Fire Service

Copy to:-

1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.
2. The Principal, M/s The Frank Anthony Public School located at Lajpat Nagar- IV, New Delhi- 110024.

Conditions for the validity of Fire Safety Certificate:-

1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
2. All the means of escape shall be kept free of all the type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned..
6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT				
1	Name and address of the building:	M/s The Frank Anthony Public School, located at Lajpat Nagar-IV, New Delhi - 110024.		
2	Building is comprised of	Junior Block - Ground + 2 upper floors Middle Block - Lower Ground + Upper Ground + 2 upper floors Senior Block - Ground + 2 upper floors Admin/Olive Anthony block - Ground + 2 upper floors		
3	Type of occupancy	Educational Building (School) ' Group B''		
4	Type of case:	Renewal		
5	Details of previous FSC:	F6/DFS/MS/School/2020/SZ/587 dated 30.12.2020		
6	Fire safety directives no.:	DOE Circular no.262-362 dated 17/01/2005		
7	Date of inspection:	08.12.2023		
8	Name of the inspecting officer:	ADO Rajesh Kumar Shukla (M. Road)		
9	Name and designation of the officer from the building side:	Mr. Dilip Kumar (Estate Manager)		
10	Year of construction:	2006-07		
11	Reference letter no.:	Outdoor diary no. 10180 dated 29.11.2023		
S,No	Minimum Standards on fire Prevention and fire safety requirements U/R 33	Requirement as per D.O.E Circular dated 17.01.2005	Provide at site	Remarks MR/NMR
1	Access to Building			
	A Road width	Required	6.0 mtrs	MR
	B Gate width	Required	4.5 mtrs	MR
	C Width of internal roads	NA	NA	NA
2	Number, Width, Type & Arrangement of Exits			
	A No. of staircase:			
	a) Upper floor	Required	Jr.Block-3 nos. Mid. Block-2 nos. Sr. Block - 4 nos. Admin/Olive - Block- 4 nos.	MR
	b) Basements	NA	NA	NA
	B Width of the staircase:			
	a) Upper floor	Required	- Jr.Block-1.10 m x 2nos. & 1.50 m - Mid. Block-1.50 m, 1.30 m - Sr. Block - 1.50 m x 4 nos. Admin/Olive Block- 1.50 m x 4 nos.	MR
	b) Basements	NA	NA	NA
	C Protection of exits			
	a) Fire check door	NA	NA	NA
	b) Pressurization	NA	NA	NA
	D No. of continuous staircase to terrace:	Required	Jr. bk- 1no. Mid bk- 1 no., Sr. bk- 1no. & Admin bk- 2 nos.	MR
	F Width of the corridor	Required	1.50 m	MR
	E Door size	1.0 mtrs. (for class room)	1.0 mtrs. (for class room)	MR
3	Compartmentation:			
	A Fire check doors	NA	NA	NA
	B Sealing of electrical shafts	NA	NA	NA
	C Fire rating of shaft doors	NA	NA	NA
	D Water curtain	NA	NA	NA
	E Fire dampers	NA	NA	NA
4	Smoke Management System:			
	A Upper floors	NA	NA	NA
	B Basements	NA	NA	NA
5	Fire Extinguishers			
	A Total numbers	20 nos.	20 nos.	MR
	B Types	CO ₂ & ABC	CO ₂ & ABC	MR
	C ISI marking	ISI Marked	Provided	MR

22. 2

6	First Aid Hose reel			
A	Total no. at each floor	2 nos. each floor/ block	Provided	MR
B	Length of hose reel	30 mtrs.	30 mtrs.	MR
C	Nozzle diameter	5 mm	5 mm	MR
7	Automatic Fire Detection and Alarm System (ADAS)			
A	Type of detectors	NA	NA	NA
B	Location of main panel	NA	NA	NA
C	Location of repeater panel	NA	NA	NA
D	Alternate power source	NA	NA	NA
E	Hooter's location	NA	NA	NA
8	MOEFA	Required	Provided	MR
9	Public Address System	NA	Provided	NA
10	Automatic Sprinkler System			
A	Basement	NA	NA	NA
B	Upper floor	NA	NA	NA
C	Sprinklers above false ceiling	NA	NA	NA
11	Internal Hydrants			
A	Size of the riser/down comer	Required	100 mm	MR
B	No. of hydrants per floor	Required	02 nos. each block	MR
C	Hose box	Required	02 nos. each block	MR
12	Yard Hydrants			
A	Total no. of hydrants	NA	NA	NA
B	Hose box	NA	NA	NA
13	Pumping Arrangements			
A	Ground Level			
	a) Discharge of main pump	NA	NA	NA
	b) Head of main pump	NA	NA	NA
	c) Number of main pump	NA	NA	NA
	d) Discharge of jockey pump	NA	NA	NA
	e) Head of jockey pump	NA	NA	NA
	f) Discharge of standby pump	NA	NA	NA
	g) Head of standby pump	NA	NA	NA
	h) Auto starting/ manual stopping	NA	NA	NA
B	Terrace Level			
	a) Discharge of terrace pump	Required	1450 LPM at ground connected to overhead tank	MR
	b) Head of terrace pump	40 m	40 m	MR
	c) Alternate power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
14	Captive Water Storage for Fire Fighting			
A	Underground tank capacity	25,000 ltrs	25,000 ltrs	MR
B	Draw off connection	NA	NA	NA
C	Fire service inlet	NA	NA	NA
E	Access to tank	NA	NA	NA
D	Overhead tank capacity	10,000 Ltrs	50,000 ltrs	MR
15	Exit Signage	Required	Provided	MR
16	Provision of lift			
A	Pressurization of lift shaft	NA	NA	NA
B	Pressurization of lift lobby	NA	NA	NA
C	Communication in lift car	NA	NA	NA
D	Fireman switch	NA	NA	NA
E	Lift signage	NA	NA	NA
17	Standby Power Supply	NA	NA	NA

2/14

18	Refuge Area			
A	location	NA	NA	NA
B	Total area	NA	NA	NA
19	Fire Control Room			
A	Fire detection system panel	NA	NA	NA
B	Flow switch panel	NA	NA	NA
C	P A system panel	NA	NA	NA
D	Battery backup	NA	NA	NA
E	Building floor plan	NA	NA	NA
20	Special Fire Protection for special risk if any			NA

Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided But Not Functional (PNF).

The fire protection systems provided in the building were tested checked and found properly functional at the time of inspection.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education Circular 262-362 Dated-17/01/2005, the FSC issued vide letter no. F6/DFS/MS/School/2020/SZ/587 dated 30.12.2020 is recommended to be renewed.

R K
08/12/23

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (M. Road)

DO (SD)

meel
16/12/23

CP
11/12/2023

Director

meel
11/12/23
AD

well