## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No.F6/DFS/MS/NDZ/BNQT/2023/ 53

Dated: 13 / 12 /2023

## FIRE SAFETY CERTIFICATE

Certified that the Bells N Bliss Banquet located at Shop no. G1E, G1, G2 & G3, Cross River Mall, CBD Ground, Shahdara, Delhi -110032, running at ground floor in building comprised of two Basement, Ground plus three upper floors, owned /occupied by Bells N Bliss Banquet, have complied with the Fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules,2010 and verified by the officer concerned of this department on 30.11.2023 in the presence of Mr. Maanas Goyal (Owner) and found that the building/premises is fit for occupancy class "Assembly" (Group-D) Banquet Hall (at ground floor only) with effect from 13 12 223 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 of sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010 printed below.

Issued 13 12 2 23 at New Delhi by.

DIRECTOR
DELHI FIRE SERVICE

## Copy to:-

- The Owner, Bells N Bliss Banquet located at Shop no. G1E, G1, G2 & G3, Cross River Mall, CBD Ground, Shahdara, Delhi -110032.
- The Joint Commissioner of police (Lic.), Ist Floor, P.S Defence Colony, New Delhi-24 w.e.f. - MHA portal ID - 2023112218772 dated 22/11/2023.

## Conditions for the validity of Fire Safety Certificate:

- The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction
- 7. Basement shall be used strictly as per Building By-Laws 1983.
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

4/7

| 1   | Name                             | 0.   |  | SPECTION REPO   |                   | 010 01            |  |  |
|-----|----------------------------------|--|--|---|-------------------|-------------------|--|--|
|     | Name & address of the building   |  |  | Bells N Bliss Banquet located at Shop no. G1E, G1G2 & G3, Cross River Mall, CBD Ground, Shahdara Delhi -110032. |                   |                   |  |  |
| 2   | Build                            | ing i  | s comprised of                             | Two Basement  | Ground + 03 upper | floors only       |  |  |
|     |                                  |  |  | (Banquet Hall is Ground floor only)   |                   |                   |  |  |
| 3   | Type of occupancy                |  |  | Assembly Building Banquet Hall  |                   |                   |  |  |
| 4   |                                  | Type of case   |  | New Case  |                   |                   |  |  |
| 5   | Details of previous FSC          |  |  | Nil (FSC also issued to the Cross River Mall vide lette   |                   |                   |  |  |
|     |                                  |  |  | No.F6/DFS/MS/2023/NDZ/27 dated 19/01/2023.  |                   |                   |  |  |
| 6   | Fire safety direction letter no. |  |  | NBC Part-IV   |                   |                   |  |  |
| 7   | Date of inspection               |  |  | 30.11.2023  |                   |                   |  |  |
| 8   | Name of the inspecting officers  |  |  | Yashwant Singh Meena (ADO/LN)   |                   |                   |  |  |
| 9   | Name                             | of   | the designation of<br>om the building side |   |                   |                   |  |  |
| 10  |                                  |  | onstruction                                |   |                   |                   |  |  |
| 11  |                                  |  |  | Application no. 2023112218772 dated 22/11/2023  |                   |                   |  |  |
| S.N | o M                              | Applicant's letter no Minimum Standards on fire Prevention and fire safety   |  | NBC Part-IV<br>Requirement  | Provided at Site  | Remarks<br>MR/NMF |  |  |
|     |                                  | req  | uirements U/R 33                           |   |                   |                   |  |  |
| 1   | Acc                              | cess   | to building                                |   |                   | Tym               |  |  |
|     | а                                | a Road width   |  | 12 mtrs.  | 24 mtrs           | MR                |  |  |
|     | b                                | . Comment of the comm |  | 4.5 mtrs.   | 7.0 mtrs          | MR<br>MR          |  |  |
|     | c Width of internal road         |  | idth of internal road                      | 6.0 mtrs.   | 6.0 mtrs          | Tivite            |  |  |
| 2   | _                                |  | r, Width, Type and A                       | rrangement of Ext   | 15                |                   |  |  |
|     | A                                | N  | lumber of staircases                       | 374   | NA                | NA                |  |  |
|     |                                  | a  | Upper floor                                | NA<br>NA  | NA NA             | NA                |  |  |
|     | -                                | b  | Basement Vidth of staircases               | INA   | 11/1              |                   |  |  |
|     | B                                | +  | Upper floor                                | NΛ  | NA                | NA                |  |  |
|     |                                  | b  | Basement                                   | NΛ  | NA                | NA                |  |  |
|     | C                                |  | otection of exits                          |   |                   |                   |  |  |
|     | -                                | a  | Fire check door                            | Required  | Provided          | MR                |  |  |
|     |                                  | b  | Pressurization                             | NΛ  | NA                | NA                |  |  |
|     | D                                | No   | . of continuous ireases to terrace         | NΛ  | NA                | NA                |  |  |
|     | E                                |  | dth of corridor                            | NA  | NA                | NA                |  |  |
|     | F                                |  | or size                                    | 2.0 mtrs. x 02  | 2.0 mtrs. X 04    | MR                |  |  |
| 3   |                                  |  | rtmentation                                |   |                   |                   |  |  |
| 3   | a Fire check door                |  | check door                                 | Required  | Provided          | MR                |  |  |
|     | b Sealing of electrical shafts   |  | ing of electrical                          | N/A   | N/A               | N/A               |  |  |
|     | c                                |  | rating of shaft door                       | N/A   | N/A               | N/A               |  |  |
|     | d                                |  | er curtain                                 | N/A   | N/A               | N/A               |  |  |
|     | e                                |  | dampers                                    | N/A N/A N/A   |                   |                   |  |  |
| 4   | Smoke Management System.         |  |  |   | T                 | Terror            |  |  |
|     | a                                |  |  | NA .  | NA                | NΛ                |  |  |
|     | b                                | b Upper floor  |  | Required  | Provided          | MR                |  |  |

| 5.  | Fire Extinguisher                             |   | 04 nos.               | 06 nos.                                 | MR   |  |  |  |
|-----|---|---|-----------------------|---|------|--|--|--|
|     | a   | Total numbers                               | CO <sub>2</sub> & ABC | CO <sub>2</sub> & ABC                   | MR   |  |  |  |
|     | b   | Types                                       | 1SI marked            | ISI marked                              | MR   |  |  |  |
|     | c ISI marking                                 |   | 151 marked            |   |      |  |  |  |
| 6   | First-aid-Hose Reels.                         |   |                       | Provided In the Mall Provided by the MR |      |  |  |  |
|     | a   | Total numbers of each floor                 | 06 nos.               | Provided by the Mall                    | MR   |  |  |  |
|     | b   | Length of hose reel hose                    | 30 mtrs.              | Provided by the Mall                    | 1000 |  |  |  |
|     | c   | Nozzle diameter                             | 05 mm                 | Provided by the<br>Mall                 | MR   |  |  |  |
| 7   | Automatic fire detection and alarming system. |   |                       |   |      |  |  |  |
| 70. | a   | Type of detectors                           | Heat & Smoke          | Provided (                              | N/A  |  |  |  |
|     | b   | Location of main panel                      | Control Room          | Provided                                | N/A  |  |  |  |
|     | c   | Location of repeater panel                  | Security Room         | Provided                                | N/A  |  |  |  |
|     | d   | Alternate source of power                   | Battery & D.G<br>Set  | Provided                                | N/A  |  |  |  |
|     | _   | Hooter                                      | Stair Case            | Provided                                | N/A  |  |  |  |
| 0   | e<br>M  | OEFA  | Required              | Provided                                | MR   |  |  |  |
| 8   |   | blic address System.                        | Required              | Provided                                | MR   |  |  |  |
| 9   |   | tomatic Sprinkler System.                   |                       |   |      |  |  |  |
| 10  | -   | Basement                                    | NA                    | Provided by the Mall                    | NA   |  |  |  |
|     | a   |   | Required              | Provided by the Mall                    | MR   |  |  |  |
|     | b   | Upper floors  Sprinkler above false ceiling | NA                    | Provided by the Mall                    | NA   |  |  |  |
| 11  | Internal Hydrants                             |   |                       |   |      |  |  |  |
| **  | a   | Size of riser                               | NA                    | 100 mm                                  | NA   |  |  |  |
|     | b   | Number of hydrants per floor                | NA                    | 01 no.                                  | NA   |  |  |  |
|     | c   | Hose Box                                    | NA                    | 01 no. N                                |      |  |  |  |
| 12  | Yard Hydrants.                                |   |                       |   |      |  |  |  |
| 12  | a   | Total number of hydrants                    | NA                    | Provided                                | NA   |  |  |  |
|     | b   | Hose Box                                    | NΛ                    | Provided                                | NA   |  |  |  |
|     | 1 13  |   | Provided In the Mall  |   |      |  |  |  |
| 13  | 7/107   | Ground Level                                |                       | /                                       |      |  |  |  |
|     | A   | a Discharge of main Pump                    | 2850 LPM              | 2850 LPM                                | MR   |  |  |  |
|     |   | b Head of Main Pump                         | 60 mtrs.              | 60 mtrs.                                | MR   |  |  |  |
|     |   |   | 02 nos.               | 02 nos.                                 | MR   |  |  |  |
|     | 10  | d Jockey pump out put                       | 180 LPM x 02          | 180 LPM x 02 /                          | MR   |  |  |  |
|     |   |   | 60 mtrs.              | 60 mtrs.                                | MR   |  |  |  |
|     | 1   | f Standby pump out put                      | 2850 LPM              | 2850 LPM                                | MR   |  |  |  |
|     |   |   | 60 mtrs.              | 60 mtrs. (                              | MR   |  |  |  |
|     | V.  | h Auto starting /manual stopping            | Required              | Provided /                              | MR   |  |  |  |
|     |   | i Pump House Access                         | Required              | Provided                                | MR   |  |  |  |
|     | B Terrace Level                               |   |                       |   |      |  |  |  |
|     |   | a Discharge of pump                         | NA                    | NA                                      | NA   |  |  |  |
|     |   | b Head of the Pump                          | NA                    | NA                                      | NA   |  |  |  |
|     |   | c Power supply                              | NA                    | NA                                      | NA   |  |  |  |
|     |   | d Auto Starting of pump                     | NA                    | NA                                      | NA   |  |  |  |

Bells N Bliss Banquet located at Shop no. G1E, G1, G2 & G3, Cross River Mall, CBD Ground, Shahdara, Delhi -110032

| 4  | Captive Water Storage for Fire Fight                                     | ting. Pr             | Provided In the Mall                                     |          |  |  |  |
|----|--|----------------------|--|----------|--|--|--|
|    | a Underground tank capacity  | INA                  | 2,00,000 Ltrs. NA  |          |  |  |  |
|    | b Draw-off connection  | NA                   | Provided by the Mall                                     | NA       |  |  |  |
|    | c Fire service inlet   | NA                   | Provided by the Viall                                    | NA       |  |  |  |
|    | d Access to tank   | N/A                  | Provided by the Mall                                     | NA       |  |  |  |
|    | e Overhead Tank capacity   | 20,000 ltrs.         | 50,000 hrs.  | MR       |  |  |  |
| 5  | Exit Signage.  | Required             | Provided   | MR       |  |  |  |
| 6  | Provision of Lifts.  | Pro                  | Provided In the Mall                                     |          |  |  |  |
|    | a Pressurization of Lift Shaft   | NA NA                | Provided   | NA       |  |  |  |
|    | b Pressurization of Lift lobby   | NA<br>NA<br>NA<br>NA | Provided<br>Provided<br>Provided<br>Provided             | 2222     |  |  |  |
|    | c Communication in lift car  |                      |  |          |  |  |  |
|    | d Firemen's grounding switch   |                      |  |          |  |  |  |
|    | e Lift Signage   |                      |  |          |  |  |  |
| 17 | Standby power supply   | NA                   | Provided   | NA       |  |  |  |
| 18 | D. Comp. Associ  |                      |  |          |  |  |  |
|    | a Total area   | NA .                 | NA   | NA<br>NA |  |  |  |
|    | b Location   | NA                   | NA   | MA       |  |  |  |
| 19 | Fire Control Room  | Prov                 | ided In the Mall   | NIA      |  |  |  |
| -  | a Detector system panel  | NA<br>NA             | Provided<br>Provided<br>Provided<br>Provided<br>Provided | 22222    |  |  |  |
|    | b Flow switch panel  |                      |  |          |  |  |  |
|    | c PA system panel  | NA .                 |  |          |  |  |  |
|    | d Battery backup   | NA                   |  |          |  |  |  |
|    | e Building Floor Plans   | NA.                  | Provided in all  | NA       |  |  |  |
| 20 | Special Fire Protection systems for protection of special Risks, if any: | NA                   | LT & HT<br>Panels  | Att type |  |  |  |

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards of fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

04/12/2013

Signature of the Inspecting Officer

Name

Yashwant Singh Meena

Designation ADO (L.N)

DY.CFO/NDZ

Sind was

C.FO.

8 101 2022 616/2022