

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/EH/2023/SZ/36/

Dated: 13 / 12 /2023

## FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s Brown Lounge and Bar located at Second Floor, Paras Cinema, Plot No 1, Kalkaji District Centre Nehru Place, New Delhi-110019 in the building comprised of Basement, Ground, Mezzanine plus Three upper floors owned/ occupied by Unit of Browne Lounges and Bar LLP have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 05/12/2023 in the presence of Mr. Deepak Sahni and that the premise is fit for occupancy class Group-D Assembly Building (Restaurant at Second Floor only) and validity upto 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 13/12/2023 at New Delhi by

(ATUL GARG) DIRECTOR

delhi fire service

Copy to: -

1. The DHO, Public Health Department, MCD, Central Zone, Jal Vihar Lajpat Nagar, New Delhi-110024. (Ref. MHA Portal ID 2023112718940 dated 28/11/2023)

## Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."



1		INSPECTION REPORT					
	Nan	ne & Address of the Building	M/s Brown Lounge and Bar (A Unit of Browne Lounges and Bar LLP) located at Second Floor, Paras Cinema, Plot No 1, Kalkaji District Centre Nehru				
2	Тур	e of Occupancy	Place, New Delhi-110019				
3	Bui	ding Comprised of	Eating House at 2 <sup>nd</sup> Floor only				
4	Typ	of Case	Basement, Ground, Mezzanine plus Three Upper Floor				
5	Det	ils of Previous NOC	New case				
6	Fire	Safety Disset	Nil				
7	Date	Safety Directives Letter No of Inspection	UBBL-2016				
8	Nan	of hispection	05/12/2023				
9	Nan	ne of the Inspecting Officers	DO (South) & ADO (BCP)				
	from	ne & Designation of Officers	Mr. Deepak Sahni				
10	Ves	the building side	Second from the network				
11	A	of construction	2005 yadd ay weddydd le todrau				
S. No.	App	licant letter No.	MHA Portal ID 2023112718940 dated 28/11/2023				
1	115	imum standards on Fire Prevention Fire Safety U/R 33	Requirement/ Existing Fire	Provided at Site	Remarks MR/NMR		
	Acc	ess to Building. Protection   FSC No.F.6/DFS/MS/Assembly/2022/SZ/Cinema/132 Date					
		29/03/2	022 Paras Cinem	a District Centre Nehru P	loop Veller		
	346	Road width	12m	Provided*			
		Gate width	4.5m		MR		
		• Width of internal road	6 6 6 10	Provided*	MR		
2	Nu	aber, width, type and arrangements of	Camita.	Provided*	MR		
	a.	Number of Staircase					
		Upper floors	Provided &	Maintained by Paras	Cinema		
		Basement floor	02 Nos	04 Nos	MR		
	b.	Width of Staircase	02 Nos	Provided*	MR		
	1	• Upper floors	Provided & Maintained by Paras Cinema				
		Basement floor	02 mtr	02 mtr each	MR		
	c.	Protection of exits	02 mtr	Provided*	MD		
		Fire check door	Provided 8	Maintained by Paras	Cinama		
	500	• Pressurization	Required	Provided*	MR		
	d.		Required	Provided*			
	0.	No. of continuous staircase to terrace	Required	Provided*	MR		
		Width of corridor	N/A	N/A	MR		
3	_	Door size	1.50 mtr each	1.50 m & 1.50 m	N/A		
3	Con	partmentation.		Maintained 1.50 m	MR		
	8.	Fire check door.	N/A	Maintained by Paras	Cinema		
	Mil	Sealing of electrical shafts.	N/A	N/A	N/A		
	87	Fire rating of shaft door.	N/A	N/A	N/A		
	1	Water curtain	N/A	N/A	N/A		
		Fire dampers.	N/A	N/A	N/A		
4.	Smo	ke Management system.		N/A	2211		
		Basement	Provided &	Maintained by Paras	Cinema		
		Upper floors		As above	N/A		
5.	EV.	Extinguishers.	Required	Exhaust fans provided			
3.	rire	D.=1/	A.A.		MR		
	3-4	Total numbers	06 Nos	06 Nos.	-6		
	•	Types	A	ABC-04, W.CO <sub>2</sub> -02	MR		
	•	ISI Marking	ISI marked	Provided	MR		
6.	First	Aid Hose Reels.	Provided	& Maintel -	MR		
	Total numbers on each floor.		7,000	& Maintained by Paras	Cinema		
		Length of hose-reel hose.	Hose Reel	one in Restaurant	MR		
		Nozzle Diameter	1.001	30m	MR		
	1		Of 3	5mm	MD		
7	Auto	matic Fire Detection and Alarming s	vetem Dans	ed & Maintained by Pa			



- 1	5 Thomas and decreased	Required	Smoke & Heat	MR
	Type of detectors	Required	Provided*	MR
	Location of Main Panel     Location of Bank Panel	N/A	N/A	N/A
	Location of Repeater Panel	1000000	As above	MR
	Alternate source of power	Required Required	Provided*	MR
8.	Hooter's location     MOEFA	HITESTON SEE AN AUGUSTOS	Provided*	MR
9,	Public Address System	Required	Provided*	MR
10.	Automatic Sprinkler System	Required	Maintained by Paras	75 19 17 7 11
	Basement		Provided*	MR
	Upper floors	Required	Provided*	MR
	1.7.7	Required		N/A
11.	Sprinkler above false ceiling     Internal Hydrants.	N/A	N/A	100000
	Size of Riser/Down-comer		Maintained by Paras	MR
	Number of Hydrant per floor	Required	Provided*	MR
	Hose box.	Required	Provided*	1 100000
12.	Yard Hydrants.	Required	Provided*	MR
	Total number of hydrants.		Maintained by Paras C	_
	2. Hose box.	Required	Provided*	MR
13.	Pumping arrangements.	Required	Provided*	MR
	Ground Level	Dunida, a o	Material II a	
		2280 LPM	Maintained by Paras C	
	<ul> <li>Discharge of main pump.</li> <li>Head of main pump.</li> </ul>	60 mtr	Provided*	MR
	<ul> <li>Number of main pumps.</li> </ul>	Two	Provided*	MR
	Jockey Pump output.	180 LPM	Provided*	MR
	> Jockey Pump head.	60 mtr	Provided*	MR
	Standby Pump output.	2280 LPM	Provided*	MR
	Standby Pump head.	60 mtr	Provided*	MR
	> Auto Starting / Manual Stopping.	Required	Provided*	MR
	Access to pump house	Required	Provided*	MR
	Terrace Level	Required Provided* MR Provided & Maintained by Paras Cinema		
	Discharge of pump.	N/A	N/A	
	> Head of pump.	N/A	N/A N/A	N/A
	> Power supply.	N/A	N/A N/A	N/A
	> Auto starting of pump.	N/A		N/A
14.	Captive water storage for Fire Fighting.	N/A N/A N/A Provided & Maintained by Paras Cinema		
	Underground tank capacity.	75,000 Ltrs	1,00,000 ltr	
	Draw-off connection.	Required	Provided*	MR
	Fire Service Inlet.	Required	Provided*	MR
	> Access to tank.	Required	Provided*	MR
	Overhead tank capacity.	10,000 Ltrs		MR
15.	Exit Signage.	Required	Provided* Provided	MR
16.	Provision of Lifts.			MR
	Pressurization of lift shaft.	Required	Maintained by Paras ( Provided*	_
	Pressurization of lift lobby.	Required		MR
	Communication in lift car.	Required	Provided* Provided*	MR
	Fireman's switch.	Required		MR
	Lift signage.	Required	Provided*	MR
17	Standby Power Supply	•	Provided*	MR
18.	Refuge Area	Required	Provided (DG Set)	MR
201	Total area	3000		1
	Location	N/A	N/A	N/A
9.	Fire Control Room.	N/A	N/A	N/A
,	Detector System Panel.	Provided & Maintained by Paras Cinema		
	Flow Switch Panel.	Required	Provided*	MR
	TION SWITCH Faller.	Required	Provided*	MR

1

W



1	PA system Panel.			
	Battery backup	Required	Provided*	MR
	<ul> <li>Building floor plan</li> </ul>	Required	Provided*	MR
20.	Special Fire Protection S	Required	Provided*	MR
Protection of special Risk, if any:		Required	Provided*	MR

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 535 dated 25/09/2023.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly DFA is put up for approval and signature please.

Signature of the Inspection Officer

Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Design: ADO (BCP)

CFO (HQ)

interface my / 1/1/3

12/12/23