

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001



No F 6 / DFS / MS / 2023 /School/WZ/ 880

Dated 12/12/223

FIRE SAFETY CERTIFICATE

Certified that the Rising Era Convent School located at Kh. No. 96, Near Telephone Exchange, Khera Khurd, Delhi-110082 comprised of Ground and First floor owned/occupied by Rising Era Convent School was issued FSC by this department vide letter No F6 /DFS/MS/2020/WZ/498 dated 11.11.2020. The premises was re-inspected by the officer concerned of this department on 01.12.2023 in the presence of Sh. Suresh Chander (Chairman), and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy Group B Educational with effect from .12.12.223..... for a period of three years, subject to compliance of the conditions mentioned below:

Issued on ... 12 1.2.2.3 at New Delhi by

Director Ph. 011-23414000

Copy to:-

1. The Director, Education, Government of NCT of Delhi. Old Sect. Delhi-110054

 Principal, Rising Era Convent School located at Kh. No. 96, Near Telephone Exchange, Khera Khurd, Delhi-110082.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

 The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

INSPECTION REPORT 1. Name a address of the building :

Rising Era Convent School, located at Kh. No. 96, Near Telephone

Exchange, Khera Khurd, Delhi- 110082.

 Type of Occupancy
 Building Comprised of
 Type of Case
 Details of Previous NOC
 Fire Safety directives letter No
 Date of Inspection
 Name of Inspecting Officer
 Name and designation of officers

 From the building side

 Year of Construction Educational

Ground plus First floor Renewal

F6/DFS/MS/2020/WZ/498 dated 11/11/2020 DOE circular No. 3298-3398 dated 01/03/2011

01/12/2023

R.K.Sinha, ADO (BW)

Sh. Suresh Chander (Chairman)

S. No.	Minimum	's letter No. :	RECS/DFS/23-24/40 DOE	dated 23/11/2023	
1.	Access to	and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR
	• Ro	ad width	6 m	4.5 m	
	• Ga	e width		4.3 m	MR(old case)
		A STATE OF THE STA	4.5 m	Directly Accessible	MR
	• Wi	ith of internal road	NA	NA	
2.	Number, V	idth, Type & Arrangeme	ent of Frite	- NA	NA
		II.	ant of Exits		
	a. Number	of staircases			
	• Up	per Floors	02		
		57,855	02	02	MR
		ements	NA	NA	1111
	b. Width of	staircases			NA
1	• Up	er Floor			
-			1.50 m each	Provided	MR
	• Bas	ements	NA	NA	
ı	c. Protection	of evits	2000	NA	NA
		check door			
-			NA	NA	NA
	• Pres	surization	NA	NA	SCHOOL STATES
ŀ	J N 0	▼ COMMANDED COMMAND	ENVAL	INA	NA
	d. No. of co terrace	. No. of continuous staircases to			
-	189 - 1189 850		NA	NA	NA
L	e. Width of	Corridor	NA	NA	
1	f. Door Size		G.F 1 m	Provided	NA
-	Compartmen	tation	F.F 1.20 m	Flovided	MR
+		g/-527-01653/0			
	• Fire c	neck door	NA	NA	***
	 Sealing 	g of electrical shafts	NA	1964 - 191	NA
-				NA	NA
L	Fire R	ating of shaft door	NA	NA	NA
	 Water 	Curtain	NA		INA
\vdash			241	NA	NA
	Fire D	ampers	NA	NA	NA
S	moke Manag	ement System			INA
	 Basem 	ents	NA		
	• Upper		1.70.000	NA	NA
	11.0		Required	Naturally Ventilated	MR
Fi	re Extinguis	ners			5-20/20/20
		umbers	1 @ 300 sqm	P	
-			© 200 squi	Provided	MR
	 Types 		ABC Type	Provided	MR



		١.	
N	_	10	•

	 IS marking 	The same of the sa		- 6		
6.	The state of the s	Required	Provided			
	First-Aid Hose Reels Total numbers on each floor			77.		
		NA	NA	NA		
	Deligiti of flose reel hose	NA	NA	NA		
	Nozzle diameter	NA	NA	NA		
7.	Automatic fire detection and alarming system					
	Type of detectors NA NA NA					
	Location of Main Panel	N	NA	NA		
	Location of Repeater Panel	NA				
	Alternate source of power	NA	NA	NA		
	and of power	NA	NA	NA		
	Hooters' Location	NA	NA	NA		
8.	MOEFA	NA				
9.	Public Address System	NA NA	NA NA	NA NA		
10.	Automatic Sprinkler System	- W-A-W	11/1	NA.		
	A STATE OF THE STA					
	Dasement	NA	NA	NA		
	Ground Floor	NA	NA	NA		
	Sprinkler above false ceiling	NA	NA	NA		
11.	Internal Hydrants					
	Size of riser/down-comer	NA	NA	274		
	Number of hydrants per floor	NA	NA NA	NA		
	Hose Box	NA	1/98/2/44	NA		
12.	Yard Hydrants	NA	NA	NA		
	Total number of hydrants	NA	NA	NA		
	Hose Box	NA	NA	NA		
3.	Pumping Arrangements					
	Ground Level					
	➢ Discharge of main Pump	NA	NA	1		
	➤ Head of Main pump	NA NA		NA		
-	> Number of main pumps	50400000	NA	NA		
	27455 T. 54550 T. 555	NA	NA	NA		
	> Jockey Pump out put	NA	NA	NA		
	> Jockey pump head	NA	NA	NA		
	Standby Pump out put	NA	NA	NA		
	Standby Pump Head	NA	NA	NA		
	> Auto Starting/Manual	NA	NA	NA NA		
	Stopping		E-COURTS N	NA.		
	Pump House Access	NA	NA	NA		
-+	Terrace level	d				

	10
/√	1 1

		Discharge of pump		N-17		
X	3	Head of the pump	NA	NA	NA	
1	1	14, 1	NA	NA	NA	
1	>		NA	NA .	NA	
14.	1	Vater Storage for 5	NA	NA	NA	
	. Captive Water Storage for fire fighting					
	>	rderground tank capacity	NA	NA	NA NA	
		Draw-off connection	NA	NA	NA	
	>	Fire service inlet	NA	NA	NA	
	-	Access to tank	NA	NA	NA NA	
1.5		erhead Tank capacity	NA	NA	NA NA	
15.	Exit Signa	1 0 T - 2 2 2	Required	Provided		
16.	Provision	of Lifts.	244/3	/4	MR	
		surization of Lift Shaft	NA	NA NA	NA.	
	• Pre	surization of Lift lobby	NA	NA	NA	
	• Cor	nmunication In lift Car	NA	NA NA	NA	
	• Fire	man's Grounding Switch	NA		NA	
		Signage		NA _	NA	
7.	Standby po	wer supply	NA NA	NA	NA	
8.	Refuge Are	•		NA	NA	
-	12.27			101.29		
	> Tota		NA	NA		
.	> Loca		NA		NA	
. ,	Fire Contro	Room	- 7	NA	NA	
	Detec	tor System Panel				
-		Switch Panel	NA	NA	NA	
-			NA	NA	NA	
-		stem Panel	NA	NA		
-		backup	NA		NA	
-	Buildir	ng Floor Plans	NA	NA	NA	
Sp.	ecial Fire Pi	rotection System 6	NA	NA	NA	
1.1	orection or s	pecial Risks, if any:		NA	NA	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Note: Electric meter and electrical panel are not under the staircase.

Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safely measures as required under DOE circular no. 3298-3398 dated 01/03/2011, it is recommended to renew the Fire Safety Certificate F6/DFS/MS/2020/WZ/498 dated 11/11/2020. issued vide letter number