(-60





## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No. F.6/DFS/MS/School/2023/SZ/905

## FIRE SAFETY CERTIFICATE

Certified that the Aadyant School located at Plot No. 10-11, Nelson Mandela Marg, Near Gurudwara, Vasant Kunj, New Delhi-110070, comprised of Basement, Ground and two upper floors owned/occupied by Manohar Memorial Educational Society was issued FSC by this department vide letter No F6/MS/DFS/School/SZ/2019/189 Dated 25/01/2019. The school premises was re-inspected by officer concerned of this department on 11/12/2013 in the presence of Mr. Yoginder Kumar and observed that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class "Educational Building" Group-B, with effect from \_\_\_\_\_\_ 2023 for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 18 /12/2023 at New Delhi by

DELMI FIRE SERVICE

Copy to: -

1. The Principal, Aadyant School (Manohar Memorial Educational Society) at Plot No. 10-11, Nelson Mandela Marg, Near Gurudwara, Vasant Kunj, New Delhi-110070

2. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi-110054

## Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting system.

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



-	INSPECTIO	N REPORT	eria di especia			
1	Name & Address of the Building	Aadyant School (Manohar Memorial Educational				
		- Color, Little III Nologe La II		ela Masa		
		T asame really, New Delmai (1077)				
2	Type of Occupancy	Educational, Grou	D-R (School)			
3	Building Comprised of	Sunken Basement, Ground plus two upper floors				
4	Type of Case	renewal				
5	Details of Previous NOC	F6/MS/DFS/Scho	ol/SZ/2019/189 Dated 2	5-01-2010		
6	Fire Safety Directives Letter No	for B + G + 03 upper floor				
7	Date of Inspection	11-12-2023				
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)				
9	Name & Designation of Officers from the building side	Mr. Yogender Kumar (Estate Manager)				
10	Year of construction	2004				
11	Applicant letter No.	Outdoor Diary No. 19445 dated 27-12-2018				
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC Requirements	Provided at Site	Remarks MR/NMR		
1	Access to Building.		Name and A	T. T		
	<ul> <li>Road width</li> </ul>	6 mtr	12 mtr	MR		
- 1	Gate width	4.5 mtr	5.54 mtr	MR		
	Width of internal road	-NA-	-NA-	2017		
2			The first state of	-NA-		
-	Number, width, type & arrangement of exits.  a) Number of Staircase					
	a) Number of Staircase  > Upper floors.	02 Nos	03 Nos	1 100		
	Basement floor.		1/2/2/3/1970/27	MR		
		02 Nos	Provided	MR		
	b) Width of Staircase	Total re-	all although as			
	> Upper floors	1.50m	1.50m, 1.36m & 1.27m	MR		
	➤ Basement floor	1.50m	1.50m & 1.36m	MR		
	c) Protection of exits		has been true to be	-11/4		
1	> Fire check door	-NA-	-NA-	-NA-		
1	> Pressurization	-NA-	-NA-	-NA-		
1	d) No. of continuous staircase to terrace	Required	01 No	MR		
6	e) Width of corridor	Required	2.58m	MR		
3	f) Door size	Required	1.16m	MR		
3	Compartmentation.	-				
4	• Fire check door.	Required	Provided	MR		
4	Sealing of electrical shafts.	-NA-	-NA-	-NA-		
4	Fire rating of shaft door.	-NA-	-NA-	-NA-		
4	Water curtain     Fire demonstration	-NA-	-NA-	-NA-		
4	• Fire dampers.	-NA-	-NA-	-NA-		
-	Smoke Management system.  Basement	20 /	all the maker of	- 12		
9-1		30 a/c per hour	Exhaust fan provided			
Alle I	Upper floors	12 a/c per hour	Exhaust fan provided	MR		
5	Fire Extinguishers.	VIS 1711	11/1/10/11			
9-1	Total numbers	Required	17 Nos	MR		
7	• Types	ABC/CO2	ABC & CO2	MR		
	ISI Marking	ISI mark	Provided	MR		
6	First Aid Hose Reels.	101 mark	Flovided	IVIK		
1	Total numbers on each floor.		D 21.1	1 100		
4- 1	Length of hose-reel hose.	One	Provided	MR		
	Nozzle Diameter	30m	Provided	MR		
		5mm	Provided	MR		

7/-	
आज़ादी	75.00
अमृत म	Blee

7	Automatic fire detection & alarming system.	Y 197 17	-NA-	-NA
	Type of detectors	-NA-	-NA-	-NA
	<ul> <li>Location of Main Panel</li> </ul>	-NA-	-NA-	-NA
	Location of Repeater Panel	-NA-	-NA-	-NA
	<ul> <li>Alternate source of power</li> </ul>	-NA-		_
	Hooter's location	-NA-	-NA-	-NA
8	MOEFA	-NA-	-NA-	-NA
9	Public Address System	Required	Provided	MR
10	Automatic Sprinkler System			
	Basement	Required	Provided	MR
	Upper floors	-NA-	-NA-	-NA
	<ul> <li>Sprinkler above false ceiling</li> </ul>	-NA-	-NA-	-NA
11	Internal Hydrants.		75. 15.	
	Size of Riser/Down-comer	100 mm	Provided	MR
	Number of Hydrant per floor	One	Provided	MR
	Hose box.	One	Provided	MR
12	Yard Hydrants.	ROSS PALL STREET	AND THE REAL PROPERTY.	
10	Total number of hydrants.	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
13	Pumping arrangements.			
- 1	Ground Level		121	
	Discharge of main pump.	-NA-	-NA-	-NA-
	➤ Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	Jockey Pump output.	-NA-	-NA-	-NA-
	Jockey Pump head.	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	<ul> <li>Auto Starting/Manual Stopping.</li> <li>Pump house access.</li> </ul>	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	Terrace Level		ALL CAMPS OF IV	
	Discharge of pump.	Required	450 LPM	MR
	> Head of pump.	Required	40 mtr	MR
	Power supply.	Required	Provided	MR
14	Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.			
	Underground tank capacity.	20,000 Ltr	Provided	MR
	Draw-off connection.	-NA-	-NA-	-NA-
	Fire Service Inlet. Access to tank.	Required	Provided	MR
		-NA-	-NA-	-NA-
15	Overhead tank capacity.  Exit Signage.	10,000 Lts	Provided	MR
16	Exit Signage. Provision of Lifts.	Required	Provided	MR
	Pressurization of lift shaft.	, and the same of	The state of the s	
		-NA-	-NA-	-NA-
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	• Fireman's switch.	-NA-	-NA-	-NA-
17	Lift signage.  Standb. B	-NA-	-NA-	-NA-
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area		Taylor.	
	Total area	-NA-	-NA-	-NA-
	Location	2 100 2 187 3 to 1	414.1	-14/4-

Aadyant School at Plot No 10-11, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070



-0 1	rire Control Room.			
19 1	Detector system panel.	-NA-	-NA-	-NA-
	<ul> <li>Flow switch panel.</li> </ul>	-NA-	-NA-	-NA-
	<ul> <li>PA system panel.</li> </ul>	-NA-	-NA-	-NA-
	Battery backup.	-NA-	-NA-	-NA-
- 11	Building floor plan.	-NA-	-NA-	-NA-
20 5	a Line Protection System for the Protection of special Dist. 15			-NA-

The fire protection system provided in the building / premises were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No F6/MS/DFS/School/SZ/2019/189 Dated 25-01-2019, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

Aadyant School at Plot No 10-11, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070

CFO (HO)

As approve, F.J. lettel is putup for your.
Signature Pl.