GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2023/SZ | 898 FIRE SAFETY CERTIFICATE

Dated: 18 12 2023

Certified that the Govt. Boys Sr. Sec. School, Goela Khurd, New Delhi-110071, comprised of total five blocks 01 block having ground floor only and 04 blocks having ground plus one upper floor only, owned/occupied by Govt. of NCT of Delhi was issued FSC by this department vide letter No F.6/DFS/MS//2020/519 dated 27/11/2020 (For 07 Blocks). The school building was re-inspected by the officer concerned of this department on 12/12/2023 in the presence of Sh. Dalip Singh Yadav (Estate-Manager) and found that now two blocks have been demolished by PWD comprised of ground floor only. The school building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on. 18 19 2023 at New Delhi.

DELHI FIRE SERVICE

Copy to:-

1. The Principal, Govt. Boys Sr. Sec. School, Goela Khurd, New Delhi-110071

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of

occupants in case of emergency.

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

6. The certificate may not be treated in any case for the regularization of the unauthorized

construction, if any.

7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior

to its expiry.

10/26

INSPECTION REPORT

1. Name & address of the building : Govt. Boys Sr. Sec. School, Goela khurd, New Delhi-110071

. Building comprised of : 05 Blocks Block-1 having ground floor only 4 blocks

having G+1 upper floor only

3. Type of Occupancy : Educational 4. Type of Case : Renewal

5. Details of Previous NOC : F.6/DFS/MS//2020/519 dated 27/11/2020 (For 07 blocks)

6. Fire Safety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011

7. Date of inspection : 12/12/2023
8. Name of Inspecting Officer : A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side : Sh. Dalip Singh Yadav (Estate Manager)

10. Year of Construction : Before 2011

S. No.	Applicant's letter No. : GBSSS/GK/ Minimum Standards on fire prevention and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR				
1.	Access to building		1.40 %					
	Road width	Accessible 06 m	10 m	MR				
	Gate width	4.5 m	06 m	MR				
	Width of internal road	N/A	N/A	N/A				
2.	Number, Width, Type & Arrangement of Exits							
_	a. Number of staircases		34414					
	Upper Floors	01 No. in each	Provided	MR Old				
	Basements	Block		Case				
	b. Width of staircases	N/A	N/A	N/A				
	Upper Floor							
	Basements	1.50 m	1.50 m, 1.50 m, 1. 1.60 m	40 & MR, Old Case				
		N/A	N/A	N/A				
	c. Protection of exits		The second second					
	Fire check door	N/A	N/A	N/A				
	Pressurization	1586017855	N/A	N/A				
		N/A	IVA	1				
	d. No. of continuous staircases to			21/4				
	terrace .	N/A	N/A	N/A				
	e. Width of Corridor	1.50 m	1.70 m	MR				
	f. Door Size	1.0 m	1.0 m(double de	oor) MR				
١.	Compartmentation							
	Fire check door	N/A	N/A	: N/A				
	Sealing of electrical shafts	N/A	N/A	N/A				
	Fire Rating of shaft door	N/A	N/A	N/A				
	Water Curtain		N/A	N/A				
	Fire Dampers	N/A	N/A	N/A				
	The second of th	N/A	INA	1071				
	Smoke Management System	T 100	N/A	N/A				
	Basements	N/A	N/A	1978				
	Upper floors	Required	Natural Ventilation provided	MR				
i.	Fire Extinguishers		a deligação					
	Total numbers	20 No's	Provided	MR				
	• Types	ABC/CO ₂ type	Provided	MR				
	IS marking	ISI marked	ISI marked	MR				
	First-Aid Hose Reels	1						
	Table 1	N/A	N/A	N/A				
Till	Total numbers on each floor	N/A N/A	N/A	N/A				
4	Length of hose reel hose	N/A	N/A	N/A				
0 /	Nozzle diameter		11111					

fe

W

N/27

Ant	omatic fire detection and alarming system		N/A	N/A
Aut	Type of detectors	N/A		N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	. I of nower	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	1.22.2
M	OEFA	N/A	Provided	N/A
P	ublic Address System	N/A		
	1. C. Lilon System		N/A	N/A
. A	utomatic Sprinkler System	N/A	N/A	N/A
	Basement	N/A	N/A	N/A
	Ground Floor Folse ceiling	N/A	11.7.5	
	Sprinkler above false ceiling		N/A	N/A
1. I	nternal Hydrants	N/A	N/A	N/A
	Circ of riser/down-collici	N/A	N/A	N/A
	Number of hydrants per floor	N/A		
	Hose Box		N/A	N/A
2.	Yard Hydrants	N/A	N/A	N/A
	Total number of hydrants	N/A		
	Hose Box			
13.	Pumping Arrangements	2114	N/A	N/A
	Ground Level Discharge of main Pump	N/A	N/A	N/A
	Light of Main pump	N/A	N/A	N/A
	Number of main pullips	N/A	N/A	N/A
	lockey Pump out put	N/A		N/A
	I select numn head	N/A	N/A	N/A
	> Standby Pump out put	N/A	N/A	N/A
13	> Standby Pump Head > Auto Starting/Manual Stopping	N/A	N/A	N/A
	> Auto Starting Walls	N/A	N/A	N/A N/A
		N/A	N/A	13.7.4
	> Pump House Access			N/A
	Tan level	N/A	N/A	N/A N/A
	Discharge of pump	N/A	N/A	N/A
	> Head of the pullip	N/A	N/A	N/A
	Power SupplyAuto Starting of pump	N/A	N/A	
	Captive Water Storage for fire fighting		N/A	N/A
14.	Underground tank capacity	N/A	N/A	N/A
	Draw-off connection	N/A	N/A N/A	N/A
	Fire service inlet	N/A	N/A N/A	N/A
	> Access to tank	N/A		N/A
	Overhead Tank capacity	N/A :	N/A N/A	N/A
1.	Exit Signage.	N/A		
15.	Provision of Lifts.	•		No Lift)
16.		N/A	N/A	N/A
	Pressurization of Lift Shaft Pressurization of Lift lobby	N/A	N/A	N/A
	ainstign In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
		N/A	N/A	N/A
17.	Standby power supply		0354000	
18.	Refuge Area.		T 3115	2111
	> Total Area	N/A	N/A	N/A
1	> Location	N/A	N/A	N/A

N/A	N/A	N/A
N/A	N/A	N/A
	N/A N/A N/A N/A	N/A N/A N/A N/A N/A N/A N/A N/A N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number <u>F.6/DFS/MS/School/2020/519</u> dated 27/11/2020 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note: Previously the school building is running in seven blocks, 03 Blocks having ground floor and 4 Blocks having ground plus one upper. As per letter submitted by the Principal (placed at C- 26) 2 blocks having ground floor only was demolished by PWD & only 05 blocks are in use for schooling purpose.

Signature of Inspecting Officer

Name:- R.K.Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

Directa

My