

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110 001.

No.F.6/DFS/MS/Business/2023/SZ/ 603

Dated: 18/12/2023

FIRE SAFETY CERTIFICATE

Certified that the **Vishwa Deep Building, Plot No. 04, District Centre, JanakPuri, New Delhi-110058**, comprised of basement, ground floor, upper ground & eleven upper floors owned/occupied by Niagara Hotels & Builders Pvt. Ltd. was issued NOC for occupancy of the building by this department vide letter No. F6/DFS/MS/94/1252 dated 26/08/1994. The building was re-inspected by the officers concerned of this department on 07/12/2023 in the presence of Mr. T.N.Singh (Manager) and found that the management have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class "Business" w.e.f. the date of issue of this certificate for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on.....18/12/2023..... at New Delhi.

(Atul Garg)
Director
Delhi Fire Service

Copy to:-

1. The Manager, Vishwa Deep Building, Plot No. 04, District Centre, JanakPuri, New Delhi-110058.

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
4. The trained staff should be available round the clock.
5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
7. Basement shall be used as per the building bye laws.
8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

11/8

INSPECTION REPORT

1. Name & address of the building : Vishwa Deep Building, Plot No.-04, District Centre, Janak Puri, New Delhi-110058
2. Building comprised of : Basement, ground floor, upper ground & eleven upper floors.
3. Type of Occupancy : Mixed (Mercantile & Business)
4. Type of Case : ~~New~~ - *Renewal*
5. Details of Previous NOC : F6/DFS/MS/94/1252 dated 26/08/1994
6. Fire Safety directives letter No : N/A
7. Date of inspection : 06/12/2023
8. Name of Inspecting Officers : A.D.O. R.K.Yadav & DO Vedpal Chhikara
9. Name and designation of officers From the building side : Sh. T.N.Singh (Manager)
10. Year of Construction : 1992
11. Applicant's letter No. : Nil dated 15/11/2023


S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR
1.	Access to building	Accessible	12 m	MR
	• Road width	N/A	N/A	N/A
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	Three	Provided	MR
	• Basements	Two	Provided	MR
	b. Width of staircases			
	• Upper Floor	Required	1.40, 1.32 & 1.30 m	MR old case
	• Basements	Required	1.40 m, 1.30 m	MR old case
	c. Protection of exits			
	• Fire check door	Required	Provided	MR
	• Pressurization	N/A	N/A	N/A
	d. No. of continuous staircases to terrace	Two	Provided	MR
	e. Width of Corridor	Required	Provided	MR
	f. Door Size	1.0 m	1.0 m	MR
3.	Compartmentation			
	• Fire check door	Required	Provided	MR
	• Sealing of electrical shafts	Required	Provided	MR
	• Fire Rating of shaft door	02 hrs.	Provided	MR
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
	• Basements	Required	Provided	MR
	• Upper floors	Required	Natural ventilation provided	MR
5.	Fire Extinguishers			
	• Total numbers	04 no.'s at each floor	Provided	MR
	• Types	W/CO ₂ / CO ₂ /ABC type	Provided	MR
	• IS marking	ISI marked	Provided	MR

6.	First-Aid Hose Reels			
	• Total numbers on each floor	One	Provided	MR
	• Length of hose reel hose	30 m	Provided	MR
	• Nozzle diameter	5 mm	Provided	MR
7.	Automatic fire detection and alarming system in electrical installations			
	• Type of detectors	Required	Provided	MR
	• Location of Main Panel	Required	G. Floor	MR
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	Required	Provided	MR
	• Hooters' Location	Required	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	• Basement	Required	Provided	MR
	• Ground Floor	N/A	N/A	N/A
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	• Size of riser/down-comer	100 MM	Provided	MR
	• Number of hydrants per floor	One	Provided	MR
	• Hose Box	One	Provided	MR
12.	Yard Hydrants			
	• Total number of hydrants	2 Nos.	Provided	MR
	• Hose Box	Required	Provided	MR
13.	Pumping Arrangements (Pump house is common for Vishwa Sadan & Vishwa Deep situated at Vishwa Deep.			
	• Ground Level			
	➤ Discharge of main Pump	2850 LPM	Provided	MR
	➤ Head of Main pump	90 m	Provided	MR
	➤ Number of main pumps	Two	Provided	MR
	➤ Jockey Pump out put			
	➤ Jockey pump head	180 LPM	Provided	MR
	➤ Standby Pump out put	40 m	Provided	MR
	➤ Standby Pump Head	2850 LPM	Provided	MR
	➤ Auto Starting/Manual Stopping	90 m	Provided	MR
		Required	Provided	MR
	➤ Pump House Access	Required	Provided	MR
	• Terrace level			
	➤ Discharge of pump	N/A	N/A	N/A
	➤ Head of the pump	N/A	N/A	N/A
	➤ Power Supply	N/A	N/A	N/A
	➤ Auto Starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting			
	• Underground tank capacity	3,00,000 ltrs.	Provided	MR
	➤ Draw-off connection	Required	Provided	MR
	➤ Fire service inlet	Required	Provided	MR
	➤ Access to tank	Required	Provided	MR
	• Overhead Tank capacity	50,000 Ltrs	Provided	MR
15.	Exit Signage.	Required	Provided	MR


MR	AR	R				
			Provision of Lifts			
			• Pressurization of Lift Shaft	N/A	N/A	N/A
			• Pressurization of Lift lobby	N/A	N/A	N/A
			• Communication In lift Car	Required	Provided	MR
			• Fireman's Grounding Switch	Required	Provided	MR
			• Lift Signage	Required	Provided	MR
17.			Standby power supply	Required	Provided	MR
18.			Refuge Area.			
			➤ Total Area	Required	Provided	MR
			➤ Location	Required	Provided	MR
19.			Fire Control Room			
			• Detector System Panel	Required	Provided	MR
			• Flow Switch Panel	N/A	N/A	N/A
			• PA System Panel	Required	Provided	MR
			• Battery backup	Required	Provided	MR
			• Building Floor Plans	N/A	N/A	N/A
20.			Special Fire Protection System for Protection of special Risks, if any:	Required	Provided	MR

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings issued vide letter No. F6/DFS/MS/2022/SZ/2016 dated 19/09/2023 has been complied.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter number F6/DFS/MS/94/1252 dated 26/08/1994 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.


 Signature of Inspecting Officer
 Name:-R.K.Yadav
 Designation:-Asstt. Divisional Officer


 Signature of Inspecting Officer
 Name:- Vedpal Chhikara
 Designation:- Divisional Officer

C.F.O. (South Zone)

 14/12/2023
 Director
 13/12/23