

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. F.6/DFS/MS/School/SZ/2023/9/0

Dated: 18/ 12/2023

FIRE SAFETY CERTIFICATE

Certified that the Air Force Senior Secondary School located at Marut Camp, Lok Kalyan Marg, New Delhi.-110003, comprised of ground floor only, owned/occupied by Air Force Senior Secondary School was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/School/SZ/2021/35 dated 13/01/2021. The school premise was re-inspected by the officer concerned of this department on 11/12/2023 in the presence of Ms. Kavitha Menon (Principal) and found that the said school building have deemed complied with the fire prevention and fire safety requirement in accordance with Directorate of Education Circular No. F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01/03/2011 and that the building/premises is fit for occupancy class Group-B (Educational Building) with effect from 18 / 12/2023 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 18/12/22 at New Delhi by

DIRECTOR Delhi Fire Service

Copy to: -

- 1. The Principal, Air Force Senior Secondary School, Marut Camp, Lok Kalyan Marg, New
- 2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape / entry / exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided there in shall be maintained in good working conditions at
- 3. Any loss of life or property due to non-functional fire safety measure shall be at the responsibility
- 4. All the staff members must know the correct method of operation of fire fighting system.
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3. of UBBL-2016), if any.
- 6. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The foam is available on www.dfs.delhigovt.nic.in.

N-11

100	INSPECTIO	N REPORT	Secondary School	Marut	
1.	Secondary School,	-03			
	AND THE REST	Camp, Lok Kalyan Marg, New Delhi-03			
2.	2) 50 02 02 0	Educational Group-B (School)			
3.		Ground floor only Renewal			
4.	I I VDE OI Case		I/SZ/2021/35 dated	13/01/2021	
5.	Details of previous received	DOE Circular No. 3	298-3398 dated 01.	03.2011	
6.	The Salety directives Better	11/12/2023			
7.	Date of hispection	ADO (ST) Santos	h Kumar	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	
8.	1100110 01 1111	ADO (SJ), Santosh Kumar Smt. Kavitha Menon (Principal)			
9.	from the building side	956 - 100 - 10 M			
10.	Year of Construction	1987	10117 dated 20/1	1/2023	
11.	Applicant's letter No	Outdoor diary No.	Provided at		
S. No.	The state of the s	Requirements/ Existing Fire Protection System	site	MR/NMR	
727 1			3	Lym	
1.	Access of building	Accessible	6m	MR	
	Road width	NA	NA	NA	
	Gate width	1 C - C 1 C - C - C - C - C - C - C - C	NA	NA	
	 Width of internal road 	NA	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
2.	Number, width, Type & Arrangements	of exits	A STATE OF THE STATE OF		
2.	a. Number of staircases	1000,000	1374	NA	
	Upper floors	NA	NA		
	11 7.75 0.31	NA	NA	NA	
	Basements	and the	district and strict of	1	
	b. Width of staircases	NA	NA	NA	
	Upper floors	U.S. San	NA	NA	
	Basements	NA	IVA		
	c. Protection of exits	and the second	TANK WEIGHT S	NA	
	Fire check door	NA	NA	NA	
	Pressurization	NA	NA		
	d. No of continuous staircase to terrac	e NA	NA	NA	
		NA	NA	NA	
	f. Door Size	1m	Provided	MR	
2	Compartmentation		The same	,	
3	Fire check door	NA	NA	NA	
	• Fire check door	NA	NA	NA	
1	Sealing of electrical shafts The Prince of the Adapt	NA	NA	NA	
	Fire Rating of shaft door	NA	NA	NA	
	Water Curtain	NA	NA	NA	
AU	Fire Dampers	11/1	14 15 2 15 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
4.	Smoke managements System	NA .	INIA	NA	
S. Carlo	Basements	NA	NA	NA NA	
	Upper floors	NA	NA	IVA	
5.	Fire Extinguishers	Marko at Make	1 - 2 - 2 - 2	1/10	
J.	Total numbers	25 Nos	50 Nos	MR	
	• Types	ABC/W.CO ₂	ABC/CO ₂ /W.CO ₂	_	
4	ISI marking	ISI Marked	Provided	MR	
	First – Aid Hose Reels	The state of	author I		
6.		NA	NA	NA	
1	Total numbers on each floor		The state of the s	NA	
	 Length of hose reel hose 	NA	NA	, Harriston	
	Nozzle diameter	NA	NA	NA	



N-12

	 Automatic fire detection and alarming s Type of detector 	NA	NA	NA
	Location of Main Panel	NA	NA NA	NA
		NA	NA	NA
	Location of Repeater Panel Alternate source of power	NA	NA NA	NA
	Alternate source of power Hooters' Location	228/1055/4		NA NA
3.	MOEFA	NA NA	NA NA	NA NA
).	Public Address System	NA NA	NA NA	NA NA
0.	Automatic Sprinkler System	NA	INA	INA
0.	Basements	NA	NA	NA
	Upper Floor	NA	NA NA	NA
	Sprinkler above false ceiling	NA	NA NA	NA
1.	Internal Hydrants	IVA	III	1411
1.		NA	TATA	NIA
	Size of riser/down-comer	NA	NA	NA
	Number of hydrants per floor	NA	NA NA	NA
	Hose Box	NA	NA	NA
12.	Yard Hydrants			
	 Total number of hydrants 	NA	NA	* NA
1	Hose Box	NA	NA	NA
13.	Pumping Arrangements			/
	Ground Level	Contract =	A	
	Discharge of main pump	NA	NA	NA
	➤ Head of main pump	NA	NA	NA
	Number of main pumps	NA	NA	NA
	Jockey pump out put	NA	NA	NA
	Jockey pump head	NA	NA	NA
	Standby Pump out put	NA	NA	NA
	> Standby Pump Head	NA	NA	NA
	> Auto Staring/Manual stopping	NA	NA	NA
	> Pump House Access	NA	NA	NA
	Terrace level		TANK BULL AND	
	Discharge of pump	NA	NA	NA
	> Head of the pump	NA	NA	NA
	> Power supply	NA	NA	NA
	> Auto starting of pump	NA	NA	NA
14.	Captive water Storage for fire fighting		Carrier of Carrier of Carrier	
	 Underground tank capacity 	NA	NA	NA
	> Draw of connection	NA	NA	NA
	Fire service inlet	NA	NA	NA
	Access to tank	NA	NA	NA
15	Overhead Tank capacity Evit Signature	NA	NA	NA
15. 16.	Exit Signage	NA	NA	NA
10.	Provision of Lifts Pressurization of Lift Shaft			To a second
		NA	NA	NA
	 Pressurization of lift lobby Communication in lift Car 	NA	NA	NA
	Fireman's Grounding Suit	NA	NA	NA
	Fireman's Grounding SwitchLift Signage	NA	NA	NA
17.		NA	NA	NA
= 3 to (2000)	Standby power supply	NA	NA	NA
18.	Refuge Area		Tr. II Take	-
	> Total area	NA	NA	NA
	> Location	NA	Sec. Style Sec. St.	1111

19.	Fire control room			
1	➤ Detector system panel	NA	NA	NA
	➤ Flow Switch Panel	NA	NA	NA
	➤ PA System Panel	NA	NA	NA
	➤ Battery backup	NA	NA	NA
	➤ Building Floor Plans	NA	NA	NA
20.	Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA	NA

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules the fire safety Certificate issued vide letter No. F.6/DFS/MS/School/SZ/2021/35 dated 13/01/2021, renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (SJ)

DO (SD)

Mill Tapayy

2 | mgh | 2025

Directa

Monda

Sir

- letter is putup for your Singnature pl

Director MISININ

15.12.23