

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001**



No F 6 / DFS / MS / 2023 /School/WZ/ 9 /5

Dated | 8 | 12 | 20 23

FIRE SAFETY CERTIFICATE

Certified that the Herald Public School located at Lampur Road, New Basti, Bankner, Delhi-110040 comprised of Ground and First floor owned/occupied by Herald Public School was issued FSC by this department vide letter No F6 /DFS/MS/2019/WZ/1461 dated 17.07.2019. The premises was re-inspected by the officer concerned of this department on 06.12.2023 in the presence of Mrs. Bharti (Principal), and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy Group B Educational with effect from ... 18. 1.12. for a period of three years, subject to compliance of the conditions mentioned below:

Issued on ... 1.8. 1.2. 3at New Delhi by

Ph. 011-23414000

Copy to:-

Bl. /L 1. The Director, Education, Government of NCT of Delhi. Old Sect. Delhi-110054

2. Principal, Herald Public School, Lampur Road, New Basti, Bankner, Delhi-110040.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

INSPECTION REPORT

1. Name & address of the building : Herald Public School, located at Lampur Road, New Basti, Bankner,

Delhi- 110040.

Type of Occupancy Building Comprised of Type of Case : Educational 3. Ground plus First floor

4. Renewal

5. Details of Previous NOC F6/DFS/MS/2019/WZ/1461 dated 17/07/2019 6. Fire Safety directives letter No DOE circular No. 3298-3398 dated 01/03/2011 7. Date of inspection 06/12/2023

8. Name of Inspecting Officer

R.K.Sinha, ADO (BW) 9. Name and designation of officers

From the building side

Mrs. Bharti (Principal) 10. Year of Construction 2009 as per N-1

P	linimum Standards on f revention and fire safety		PS/Fire/10/2023 date DOE Requirement	Provided at site	Remarks
+	ccess to building				MR/NMR
-	Road width	Maria .	6 m	Provided	MR
-	Gate width Width of internal	pio [®]	4.5 m	Directly Accessible	MR
+	width of filternal		NA	NA	NA
	Number, Width, Type &	Arrangement	of Exits	1 (6-41)	
	a. Number of staircases				
	- Stancases				
	 Upper Floors 		01	03	MR
	Basements		NA	NA	NA
	b. Width of staircases				
	Upper Floor				
		350	1.50 m	1.5 m, 0.86 m & 1.16 m	MR
	Basements		NA	NA	NA
	c. Protection of exits		- 1 10		
	 Fire check door 		NA	711	
				NA	NA
	Pressurization		NA	NA	NA
	d. No. of continuous st terrace	aircases to	NA	NA	NA
	e. Width of Corridor		NA	NA	NA
	f. Door Size		1 m	Provided	
3.	Compartmentation			o rided	MR
	Fire check door		N11	- 1 ng 1 - 1 -	
			NA	NA	NA
	Sealing of elect		NA	NA	NA
	Fire Rating of s	shaft door	NA	NA	NA
	Water Curtain		NA	NA	NA
	Fire Dampers		NA	NA	NA
4.	Smoke Management System				
	Basements		NA	\ \tag{\tag{\tag{\tag{\tag{\tag{\tag{	
	Upper floors			NA	NA
			Required	Naturally Ventilated	MR
5.	Fire Extinguishers				
	Total numbers	3	1 @ 300 sqm	Provided	MR
	• Types		ABC Type	Provided	MR
	IS marking		Required	Provided	
			A		MR

N	1	2
r	-1	1

		N-17		5		
6.	First-Aid Hose Reels					
	Total numbers on each floor	NA	NA	NA.		
	Length of hose reel hose	NA	NA	NA		
	Nozzle diameter	NA	NA	NA		
7.	Automatic fire detection and alarmin					
	Type of detectors	NA	NA			
	Location of Main Panel	20200	Massier v a series	NA		
	Location of Repeater Panel	NA	NA	NA		
		NA	NA	NA		
	Alternate source of power	NA	NA	NA		
	Hooters' Location	NA	NA	. NA		
8.	MOEFA	NA	NA			
9.	Public Address System	NA	NA NA	NA NA		
10.	Automatic Sprinkler System		A series of the series	le sarais		
	Basement	NA	NA			
	Ground Floor	NA	NA NA	NA		
	Sprinkler above false ceiling	NA	NA NA	NA		
11.	Internal Hydrants		NA	NA		
_						
	one of fisch/down-comer	NA	NA	NA		
	Number of hydrants per floor	NA	NA	NA		
12.	Hose Box	NA	NA	NA		
12.	Yard Hydrants					
	Total number of hydrants	NA	NA	eser Vietning A		
	Hose Box	NA		NA		
3.	Pumping Arrangements		NA	NA		
+	Ground Level			100		
-	Discharge of main Pump	NA				
	➤ Head of Main pump	NA NA	NA	NA		
-	➤ Number of main pumps	NA	NA	NA		
-	> Jockey Pump out put	NA	NA	NA		
-	> Jockey pump head	NA	NA	NA		
-	The state of the s	NA	NA	NA		
-	- amp out put	NA	NA	NA		
-	Tump Head	NA	NA	NA		
	➤ Auto Starting/Manual Stopping	NA	NA	NA NA		
1	> Pump House Access	NA	NA	and the second		
+	Terrace level		NA	NA		
			1 - 7			
1000	Discharge of pump					

DA.

/			70. 12			
X	1	Head of the pump	NA	NA	NA	
\	1	Power Supply	NA	NA	NA	
	Auto Starting of pump Captive Water Storage for fire fighti		NA	NA	NA	
			ting			
11.	Captive	Vater Storage for me nga	NA NA	NA	NA	
	• 4	nderground tank capacity	NA	NA	NA	
	P	Draw-off connection		NA	NA	
	> Fire service inlet > Access to tank		NA		NA	
			NA	NA		
	>	ACTION AND ADDRESS OF THE PARTY	NA	NA	NA	
	• 0	erhead Tank capacity	Required	Provided	MR	
15.	Exit Signa	ge.	Keduned			
16.	Provision	of Lifts.			NA NA	
	• Pre	ssurization of Lift Shaft	NA	NA	9.020	
			NA	NA	NA	
		ssurization of Lift lobby	NA	NA	NA	
	1	nmunication In lift Car		NA	NA	
	• Fire	man's Grounding Switch	NA	V/44/4/4		
	• Lift	Signage	NA	NA	NA NA	
17.		wer supply	NA	NA	NA	
18.	Refuge Area.					
	> Tota	l Area	NA	NA	NA	
	> Loca	tion	NA	NA	NA	
19.	Fire Contro Room					
	• Dete	tor System Panel	NA	NA	NΛ	
	• Flow	Switch Panel	NA	NA	NA	
	• PAS	ystem Panel	NA	NA	NA	
		y backup	NA	NA	NA	
		ing Floor Plans	NA	NA	NA	
		rotection System for special Risks, if any:	NA	NA	NA	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Note: Electric meter and electrical panel are not under the staircase.

Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under DOE circular no. 3298-3398 dated 01/03/2011, it is recommended to renew the Fire Safety Certificate issued vide letter number F6/DFS/MS/2019/WZ/1461 dated 17/07/2019.

10d. 13/12/22 Dy(folwy)

Ymg 19/12

Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W.

Designation : ADO/B.W.

0