C-30

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2023/SZ/9/6

Dated: 18/12/2023

FIRE SAFETY CERTIFICATE

Certified that the Columbia Foundation Sr. Sec. School, D-Block, Vikaspuri, New Delhi-110018 comprised of ground floor plus three upper floors, owned/occupied by Columbia Foundation Sr. Sec. School issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/School/2020/SZ/520 dated 27/11/2020. The School building was re-inspected by the officer concerned of this department on 11/12/2023 in the presence of Sh. R.P. Gupta (Admin.) and found that the School have deemed complied the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class "Educational" for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on. 18/12/2023 at New Delhi.

DIRECTOR DECHI FIRE SERVICE

Copy to:-

- The Principal, Columbia Foundation Sr. Sec. School, D-Block, Vikaspuri, New Delhi-110018
- Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

Columbia Foundation Sr. Sec. School, D-Block, Vikaspuri, New 1. Name & address of the building:

Delhi-110018

G+3 upper floors Building comprised of Educational Type of Occupancy 3. Renewal Type of Case 4.

F6/DFS/MS/School/2020/SZ/520 dated 27/11/2020 5. Details of Previous NOC

N/A 6. Fire Safety directives letter No

11/12/2023 7. Date of inspection 8. Name of Inspecting Officer A.D.O. R.K. Yadav

9. Name and designation of officers

Sh. R.P.Gupta (Admin.) From the building side

1996 10. Year of Construction

| S. No. | 11. Applicant's letter No. : CFS/202. Minimum Standards on fire prevention and fire safety U/R 33 | 3/572 dated 26/09/ Requirement as per FSC dt. 27/11/2020 | Provided at site | Remarks MR/NMR |
|------------|--|---|----------------------|---------------------------------|
| 1. | Access to building | The same of | | |
| | Road width Gate width Width of internal road | Accessible 06 mtrs 4.5 m N/A | 10 m 3.8 m N/A | MR MR, being old case N/A |
| 2. | Number, Width, Type & Arrangement of Exit | s | | 11 5 1 |
| | a. Number of staircases | | | - 1911 24 |
| | Upper Floors | 02 No's | 02 No's | MR |
| | Basements | N/A | N/A | N/A |
| | b. Width of staircases | | | |
| | Upper Floor Basements | 1.50 m | 1.40 m & 1.35 m | MR old case |
| | c. Protection of exits | N/A | N/A | N/A |
| | Fire check door | | | |
| | Pressurization | N/A | N/A | N/A |
| | d. No. of continuous staircases to | N/A | N/A | N/A |
| | terrace | 情行在 | Martin Jan St. 7 | |
| | e. Width of Corridor | Required | Provided | MR |
| | | 1.50 m | 1.70 m | MR |
| | f. Door Size | 1.0 m | 1.10m | MR . |
| 3. | Compartmentation | | TO THE PARTY OF THE | |
| | Fire check door | N/A | N/A | N/A |
| | Sealing of electrical shafts | N/A | N/A | N/A |
| | Fire Rating of shaft door Water Curtain | N/A | N/A | 2/0/2007 |
| | Fire Dampers | 72 9000 0000 20 | | N/A |
| | I in Dampers | N/A N/A | N/A | N/A |
| 4. | Smoke Management System | IVA | N/A | N/A |
| | Basements | N/A | N/A | **** |
| | \$1 - YY, | IVA | IN/A | N/A |
| 5. | • Upper floors | Required | Natural ventilation | MR |
|) , | Fire Extinguishers | | | |
| | Total numbers | 16 no.'s | Provided | 72 1 2 |
| | Types | ABC/CO ₂ type | | MR |
| | IS marking | 10005000 | Provided | MR |
| | | ISI marked | ISI marked | MR |

| _ | • |
|---|---|
| | |
| 6 | |

| - 1 | D 1 | | | |
|--------|--|--|--|-------------------|
| | First-Aid Hose Reels | | | |
| | Total numbers on each floor | 01 no. | Provided | MR |
| | Length of hose reel hose | 30 mtrs | Provided | MR |
| | Nozzle diameter | 5 mm | Provided | MR |
| N2 | Automatic fire detection and alarming system | I have | | |
| 100 | Type of detectors | N/A | N/A | N/A |
| | Location of Main Panel | N/A | N/A | N/A |
| | Location of Repeater Panel | N/A | N/A | N/A |
| | Alternate source of power | N/A | N/A | N/A |
| | Hooters' Location | N/A | N/A | N/A |
| 3. | MOEFA | N/A | N/A | N/A N/A |
|). | Public Address System | N/A | Provided | IN/A |
| 10. | Automatic Sprinkler System | N/A | N/A | N/A |
| | Basement | N/A N/A | N/A | N/A |
| | Ground Floor Sprinkler shows false spiling | N/A | N/A | N/A |
| 11. | Sprinkler above false ceiling Internal Hydrants | IN/A | 1071 | 77 |
| 11. | Size of riser/down-comer | N/A | 100 mm | N/A |
| | Number of hydrants per floor | N/A | One | N/A |
| | Hose Box | N/A | One | N/A |
| 12. | Yard Hydrants | The state of the control of the cont | | C 10 |
| | Total number of hydrants | N/A | N/A | N/A N/A |
| | Hose Box | N/A | N/A | N/A |
| 13. | Pumping Arrangements | 1 | | |
| | Ground Level ➤ Discharge of main Pump | N/A | N/A | N/A |
| | > Head of Main pump | N/A | N/A | N/A |
| | > Number of main pumps | N/A | N/A | N/A |
| | > Jockey Pump out put | N/A | N/A | N/A |
| | Jockey pump headStandby Pump out put | N/A | N/A | N/A |
| | Standby Pump out putStandby Pump Head | N/A | N/A | N/A |
| | > Auto Starting/Manual Stopping | N/A | N/A | N/A |
| | The state of the s | N/A | N/A | N/A |
| - | | N/A | N/A | N/A |
| | Pump House Access | | | |
| | Terrace level | 450 LPM | 450 LPM & 180 | MR, being old cas |
| | Discharge of pump Head of the pump | 30 m | LPM provided Provided | MR |
| | > Power Supply | Required | Provided | MR |
| | ➤ Auto Starting of pump | Required | Provided | MR |
| | | | A STATE OF THE STA | |
| 14. | Captive Water Storage for fire fighting | • | | |
| -F0(5) | Underground tank capacity | N/A | N/A | N/A |
| | Draw-off connection | N/A | N/A | N/A |
| | > Fire service inlet | N/A | Provided | N/A |
| | Access to tank Overhead Tank capacity | N/A | N/A | N/A |
| | Overnead Fank capacity | 5,000 ltrs | 6000 ltrs Provided | MR |
| | | Required | Provided | MR |
| 15. | Exit Signage. | | | |
| | | | | No Lift |
| 16. | Provision of Lifts. Pressurization of Lift Shaft | N/A | N/A | N/A |
| | n intion of Lift lobby | N/A | N/A | N/A |
| | Communication In lift Car | N/A | N/A | N/A |
| | Fireman's Grounding Switch | N/A | N/A | N/A |
| | | | | |
| | Lift Signage | N/A | N/A | N/A |
| | Lift Signage Standby power supply / | N/A N/A | N/A N/A | N/A N/A |

| | | My | | | |
|---|-----|-----|-----|--|--|
| Refuge Area. | | | | | |
| > Total Area | N/A | N/A | N/A | | |
| > Location | N/A | N/A | N/A | | |
| Fire Control Room | | | | | |
| Detector System Panel | N/A | N/A | N/A | | |
| Flow Switch Panel | N/A | N/A | N/A | | |
| PA System Panel | N/A | N/A | N/A | | |
| Battery backup Building Floor Plans | N/A | N/A | N/A | | |
| - Building Floor Plans | N/A | N/A | N/A | | |
| Special Fire Protection System for Protection of special Risks, if any: | N/A | N/A | N/A | | |

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter number F6/DFS/MS/School/2020/SZ/520 dated 27/11/2020 renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer 2023

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer

D.O. (South West)

14/12/22

CCD(52)

Mugh

14/12/23

Deneeta)

My 1/2/23

For hetter a put up 1

on sign plea

CR ECTOR ALLAND