

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2023/School/911

Dated: 18 / 12 /2023

## FIRE SAFETY CERTIFICATE

Certified that M.C. Primary Co-ed School (School ID No. 1253036) located at EE- Block, Sant Ravidas Nagar, Jahangir Puri, Delhi-110033 comprised of 02 blocks interconnected, ground & first floor only owned/occupied by M.C. Primary Co-ed School was issued FSC by this department vide letter no. F6/DFS/MS/2008/2031 dated 21.07.2008 (ground floor only). The premises was inspected by the officer concerned of this department on 07.12.2023 in presence of Sh. Vijay Kr. Gupta (Principal) and observed that all the fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education vide letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy class "Group B Educational" with effect from ... 18 112 120 23 for a period of three years, subject to compliance of the

Issued on ... 18 / 12/2023 at New Delhi

Ph:-011-23414000

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi – 110054.

2. The Principal, M.C. Primary Co-ed School (School ID No. 1253036) located at EE- Block, Sant Ravidas Nagar, Jahangir Puri, Delhi-110033.

## Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition

3. Any loss of life or property due to non-functional fire safety measures shall be at the

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms. form

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its

## INSPECTION REPORT

1. Name & address of the building

: M.C Primary Co-ed School at Sant Ravidas Nagar, EE-Block, Jahangirpuri,

Delhi-110036. (School ID No. 1253036)

Type of Occupancy 2.

: Educational

Composition of building 3.

: 02 blocks interconnected Ground & first floor only

Type of Case 4.

: Renewal

Details of previous NOC

: F6/DFS/MS/2008/2031 dated 21.07.2008 (ground floor only)

Fire Safety directives letter No

Date of inspection 7.

: 07.12.2023

Name of the Inspecting Officers

: ADO (RN)

9. Name and designation of officers

from the building side

: Sh. Vijay Kr. Gupta (Principal)

10. Year of Construction

: 2013

	Min mum Standards on fire prevention and fire safety U/R 33	Requirement as per Rule 35 (6)	Provided at site	Remarks MR/NMR			
1	Access to building						
	Road width	Accessible	Accessible	MR			
	Gate width	Accessible	Accessible	MR			
	Width of internal road	NA	NΛ	NΛ			
2	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	Upper Floors	02	02	MR			
	• Basements						
	b. Width of staircases	1.50m	Provided	MR			
	Upper Floors	ALCONOMIC CO.	NΛ	NA			
	Basements	NA	NA				
	c. Protection of exits	NA	NA	NA			
	Fire check door	NA	NA	. NA			
	Pressurization	NA	NA	NA			
	d. No. of continuous staircases to terrace	NA	NA	NA			
	e. Wid h of Corridor	01m	Provided	MR			
	f. Door Size						
È.	Compartmentation.	NA	NA	NA			
	Fire check door     Sealing of electrical shafts	NA	NA	NΛ			
	Sealing of electrical shalls     Fire Rating of shaft door	NA	NA	NΛ			
	Water Curtain	NA	NΛ	NΛ			
	Fire Dampers	NA	NA	NA			
	Smoke Management System.						
	Basements	NA	NA				
	Upper floors	Required	Natural Ventilation	MR			
	Fire Extinguishers						
	Total numbers	05nos	05nos	MR			
		ABC/Co2	ABC—05	MR			
	Types     ISI marking	ISI Marked	Yes	MR			
	First-Aid Hose Reels.						

	149					
	Yatal numbers on each floor	NA	NA	NA		
	1 angth of hose reel hose	NA.	NA	× /		
	Nezzile dismeter	NA.	NA	NA NA		
7	Automatic fire detection and alarming system.					
	Type of detectors	NA	NA	NA		
	Location of Main Panel	NA	NA	N/A		
	Lexation of Repeater Panel	NA	NA	NA NA		
	Alternate source of power	NA	NA	NA		
	Housers' Location	N/A	NA	NA		
ı	MOEFA	NA	NA	NA		
9	Public Address System.	NA NA	NA	NA		
10	Automatic Sprinkler System.					
1000		NA	NA .	NA		
	Basement     Illiana Floor	NA NA	NA NA	NA		
	Upper Floor     Seciet to above false critical		NA NA	NA		
	Sprinkler above false ceiling	NA	NA			
11	Internal Hydrants					
	Size of riser/down-comer	NA	NA NA	NA NA		
	Number of hydrants per floor     Hose Box	NA	NA.	NA NA		
		NA	NA	NA		
2	Yard Hydrants.					
	Total number of hydrants	NA.	NA	NA:		
	Hose Box	NA	NA	NA.		
3	Pumping Arrangements.					
	Ground Level					
	➤ Discharge of main Pump	N/A	N/A	N/A		
	➤ Head of Main pump	N/A	N/A	N/A		
	<ul> <li>Number of main pumps</li> </ul>	70,000	N/A	N/A		
	<ul> <li>Jockey Pump out put</li> </ul>	N/A				
	<ul> <li>Jockey pump head</li> </ul>	N/A	N/A	N/A		
	<ul> <li>Standby Pump out put</li> </ul>	N/A	N/A	N/A		
	<ul> <li>Standby Pump Head</li> </ul>	N/A	N/A	N/A		
	<ul> <li>Auto Starting/ Manual stopping</li> <li>Pump House Access</li> </ul>	N/A	N/A	N/A		
	Terrace level	N/A	N/A	N/A		
	<ul> <li>Discharge of pump</li> </ul>					
	> Head of the pump	NA	N/A	NA.		
	➤ Power Supply	NA	N/A	NA.		
	<ul> <li>Auto Starting of pump</li> </ul>	N/A	N/A	N/A		
		N/A	N/A	N/A		
	Captive Water Storage for fire fighting.					
	Underground tank capacity	NA	NA NA	NA.		
	> Draw-off connection	NA	NA	NA		
		^		2		

ĺ

V	-				
	F 8 3	Fire service inlet	NA	NΛ	NΛ
	53 4	Access to tank	NA	NA	NA
		Overhead Tank capacity	NA	N/A	NA
5	Exit Sig		NA	NA	NΛ
6	Provision of Lifts.				
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	1	Pressurization of Lift lobby	N/A	N/A	N/A
		Communication In lift Car	N/A	N/A	N/A
	<ul> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> </ul>	N/A	N/A	N/A	
		N/A	N/A	N/A	
17	Standby	power supply	N/A	N/A	N/A
18	Refuge Area.				
	>	Total Area	N/A	N/A	N/A
	>	Location	N/A	N/A	N/A
19	Fire Control Room				
	•	Detector System Failer	N/A	N/A	N/A
	•	The section runer	N/A	N/A	N/A
	<ul> <li>PA System Panel</li> <li>Batter backup</li> <li>Building Floor Plans</li> </ul>	N/A	N/A	N/A	
		N/A	N/A	N/A	
			N/A	N/A	N/A
20	Special Protect	Fire Protection Systems for ion of special Risks, if any:	N/A	N/A.	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. F6/DFS/MS/School/2015/550 dated 17.03.2015.

Keeping in view the satisfactory compliance of the minimum standard on fire prevention and fire safety requirements as stipulated under the circular issued by Director of Education dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. F6/DFS/MS/2008/2031 dated:21.07.2008

Signature of the Inspecting Officer Name :- C.L. Meena

Designation:- ADO/RN

Dy. Chief Fire Officer (WZ)