22/12/2023 GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2023/SZ/ 93

Dated:

FIRE SAFETY CERTIFICATE

Certified that the Govt. Girls Secondary School, Baprola Vihar, New Delhi-110043 comprised of ground plus one upper floor, owned/occupied by Govt. Girls Secondary School was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/School/2021/SZ/39 dated 06/12/2023. The school building was re- inspected by the officer concerned of this department on 18/12/2023 in the presence of Smt. Jai Shree (HOS) and found that the School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on 22 12 20 23 at New Delhi.

DIRECTOR

Copy to:-

- 1. The Principal, Govt. Girls Secondary School, Baprola Vihar, New Delhi-110043
- Director of Education, 2. Govt. of NCT of Delhi, Old Secretariat, New Delhi - 110054

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its

INSPECTION REPORT

1. Name & address of the building : Govt. Girls Secondary School, Baprola Vihar, New Delhi-110043

2. Building is comprised of ground plus one upper floor

3. Type of Occupancy Educational 4. Type of Case Renewal

5. Details of Previous NOC F.6/DFS/MS/School/2021/SZ/39 dated 13/01/2021

6. Fire Safety directives letter No F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011

7. Date of inspection 18/12/2023 8. Name of Inspecting Officer A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side Smt. Jai Shree (HOS)

	The second second	um Standards on fire prevention and Tety U/R 33	Requirement	Provided at site	Remarks MR/NMR
	Access	to building			MR
	•	Road width Gate width	Accessible 4.5 mtrs	Provided Directly accessible from	MR
	•	Width of internal road	N/A	road N/A	N/A
2.	Numb	er, Width, Type & Arrangement of Exits			west 1
••	a Nur	nber of staircases			110
	a. Ivui	Upper Floors	02 no.'s	02 no.'s	MR
	1.	Basements	N/A	N/A	N/A
	b. Wie	th of staircases			
,	•	Upper Floor Basements	1.50 M & .75 M	1.47 M each	MR
			N/A	N/A	N/A
		-ifavits	3,7,5		
	c. Pro	tection of exits Fire check door	N/A	N/A	N/A
	•	Pressurization	N/A	N/A	N/A
		T 1033ut 124tton	13/23	2.77.71.7	
	d. No. of continuous staircases to terrace e. Width of Corridor		Required	One	MR
			1,50 m	1,80 m	MR
				The same of	
		oor Size	lm	lm	MR
3.	Comr	artmentation			
-	•	Fire check door	N/A	N/A	N/A
		Sealing of electrical shafts	N/A	N/A	N/A
		Fire Rating of shaft door	N/A	N/A	N/A
		Water Curtain	N/A	N/A	N/A
	•	Fire Dampers	N/A	N/A	N/A
	0 :	te Management System		500000	
4.	1723802.0000.000	Basements	N/A	N/A	N/A
	•	To supplie the supplier of	Required	Natural	MR
	•	Upper floors	required	Ventilation provided	, interest
	-	Extinguishers		•	
-	Kiro				
5.	-		06 No's	Provided	MR
5.	Fire	Total numbers Types	06 No's ABC/CO ₂ type		MR MR

1/12

	Town All W. D. J.			
6.	First-Aid Hose Reels			
	Total numbers on each floor	N/A	N/A	N/A
	Length of hose reel hose	N/A	N/A	N/A
	Nozzle diameter	N/A	N/A	N/A
7.	Automatic fire detection and alarming system	n		1 200
7.	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	 Alternate source of power 	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			2.77
	Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants	1 500	NI/A	N/A
	Size of riser/down-comer	N/A	N/A N/A	N/A N/A
	Number of hydrants per floor Uses Pay	N/A N/A	N/A N/A	N/A
	Hose Box	IN/A	IVA	INA
12.	Yard Hydrants	N/A	N/A	N/A
	 Total number of hydrants Hose Box 	N/A	N/A	N/A
13.	Pumping Arrangements	1471		
	Ground Level			
	 Discharge of main Pump 	N/A	N/A	N/A
	> Head of Main pump	N/A	N/A	N/A
	 Number of main pumps Jockey Pump out put 	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	> Standby Pump out put	N/A	N/A	N/A
	 Standby Pump Head Auto Starting/Manual Stopping 	N/A	N/A	N/A
	Auto Starting Wandar Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
	The second secon	N/A	N/A	N/A
	 Pump House Access Terrace level 			
	► Discharge of pump	N/A	N/A	N/A
	➤ Head of the pump	N/A	N/A	N/A
	> Power Supply	N/A	N/A	N/A
	> Auto Starting of pump	N/A	N/A	N/A
4.	Captive Water Storage for fire fighting		N.	
	Underground tank capacity	N/A	N/A	N/A
	 Draw-off connection Fire service inlet 	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
	F '4 0'	N/A	N/A	N/A
5.	Exit Signage.	N/A	N/A	N/A

NB		
1-		-

A STATE OF	N	NILS			(No Lift)	
V	Provis	ion of Lifts.			N/A	
	•	Pressurization of Lift Shaft	N/A	N/A	N/A	
	•	riessurization of Lie Late	N/A	N/A	N/A	
		Collimunication In Ite Car	N/A	N/A	N/A	
		Fireman's Grounding Switch Lift Signage	N/A	N/A	N/A	
		Sitt Signage	N/A	N/A	N/A	
17. 5	Stand	by power supply	N/A	N/A		
10			10.72			
8.	Refug	Refuge Area.				
	>	Total Area	N/A	N/A	N/A	
	A	Location	\$40.00m/24.3	N/A	N/A	
			N/A		N/A	
9.	Fire C	Fire Control Room N/A				
	•	Detector System Panel	N/A	N/A	N/A	
	•	Flow Switch Panel	N/A	N/A	N/A	
	•	PA System Panel	N/A		N/A	
	•	Battery backup	N/A	N/A	N/A	
	•	Building Floor Plans	N/A	N/A		
0.		I Fire Protection System for Protection of Risks, if any:	N/A	N/A	N/A	

The fire protection systems provided in the building were tested checked and found functional at the time

In view of the deemed compliance of the minimum standards of fire prevention and fire safety of inspection. measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2021/SZ/39 dated 13/01/2021 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name:- R.K. Yadav

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

Dinecta