

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

F.6/DFS/MS/EH/2023/SZ/371 No.

Dated. 22/.12./2023

FIRE SAFETY CERTIFICATE

Certified that th Eating House in the Name & Style of M/s Halwai Food Tech Pvt Ltd located at Ground and First Floor, D-215, Khasra No 601 Krishna Park, Main Devli Road, Khanpur, Hauz Khas, New Delhi 110080 Comprised of Basement Ground plus Three upper floor owned/Occupied by Halwai Food Tech Pvt Ltd have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 18/12/2023 on in the presence of Mr. Pardeep Kumar and found that the premise is fit for occupancy Group "D" Assembly Building (Restaurant at GF & FF only) and validity upto 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 22 / 12 /2023 at New Delhi by

Copy to: -

1. The Dt. Health Officer, (MCD), Public Health Department, Aurobindo Marg, Green Park, New Delhi-110016. (Ref. MHA Portal 2023112718921 dated 27/11/2023)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. The basement shall be used as per the provisions of UBBL 2016 /NBC Part- IV.

4. All the staff members must know the correct method of operation of fire fighting system.

5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules The form is available 2010. www.dfs.delhigovt.nic.in

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



	Dien	ECTION DEPORT	A DE LE SE				
1 :	Name & Address of the Building	and First Floor D-215, Khasra No 601 Krishn					
- 3		Park, Main De	Park, Main Devli Road, Khanpur, Hauz Khas, Ne Delhi 110080				
2	Type of Occupancy		t Ground & First floo				
3	Building comprised of	Basement, Gro	ound plus Three upper	floors			
4	Type of Case	New case					
5	Details of Previous NOC	Nil	The state of the s				
6	Fire Safety Directives Letter No	Nil	To see a second				
7	Date of Inspection	18/12/2023	Karak - H				
8	Name of the Inspecting Officers	DO (South) &	ADO (BCP)	- a - 1			
9	Name & Designation of Officers		Mr. Pradeep Kumar				
10	from the building side Year of construction	2023	The property of the party of th				
2000	AND AND COMPANY OF THE PROPERTY OF THE PROPERT	MHA Portal 2	MHA Portal 2023112718921 dated 27/11/2023				
11	Applicant letter No.		Provided at Site	Remarks			
S. No.	Minimum standards on Fire Preventi and Fire Safety U/R 33	on UBBL 2016	Provided at Site	MR/NMR			
1	Access to Building.	etta il est	7,004,08108	MR			
	Road width	09 m	09 m	MR			
	Gate width	06 m	06 m N/A	N/A			
	Width of internal road	NA	IVA				
2	Number, width, type & arrangement	of exits	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	The Target			
	a. Number of Staircase		Provided	MR			
	• Upper floors	02 Nos -NA-	N/A	N/A			
	Basement floor	-NA-	REAL PROPERTY.				
	b. Width of Staircase	1.50 mtr each	Provided	MR			
	Upper floors	-NA-	N/A	N/A			
	Basement floor c. Protection of exits	74-	Dr. Topent Jupopie	2 1			
	Fire check door	-NA-	N/A	N/A N/A			
	Pressurization	-NA-	N/A	Provided			
	d. No. of continuous staircase to terra	ace Required	Provided N/A	N/A			
	e. Width of corridor	N/A	1.50 mtr &1.50 mtr	MR			
1	f. Door size	1.50 mtr each	1.50 mu &1.50 ma	20.00			
3	Compartmentation.		1, 49 11	N/A			
	• Fire check door.	-NA-	N/A	N/A N/A			
_ "	Sealing of electrical shafts.	-NA-	N/A N/A	N/A			
	Fire rating of shaft door.	-NA-	N/A	N/A			
	Water curtain	-NA-	N/A	N/A			
45	 Fire dampers. 	-IVA-	**************************************				
4	Smoke Management system.		Isia acus est a 1	N/A			
	Basement	-NA-	N/A Natural ventilation	MR			
	Upper floors	Required	Natural ventuation	IVIIC			
5	Fire Extinguishers.	Desired	08 Nos	MR			
	Total numbers	Required ABC / CO2	ABC & Co2	MR			
	• Types	ISI marked	Provided	MR			
	ISI Marking Till Add Hose Reels	IDI IIIIII	Tuesday of	27.2			
6	First Aid Hose Reels. Total numbers on each floor.	01 Nos	Provided	MR			
	Length of hose-reel hose.	30m	Provided	MR MR			
	Nozzle Diameter	5mm	Provided	MIK			
7	Automatic fire detection & alarming system	m.	A Lagrangia and the control of	11.04			
	Type of detectors	-NA-	-NA-	-NA-			

	-
M)

		N)5	आ	ज़ादी का अमृत महोत्स्
	Location of Main Panel			भमृत महोत्स
	Location of Repeater Panel	-NA-	-NA-	-NA-
	Alternate source of power	-NA-	-NA-	-NA-
	Hoofer's location	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
8	MOEFA	Required	Provided	100
9	Public Address System	-NA-		MR
10	Automatic Sprinkler System	-NA-	-NA-	-NA-
	Basement		200 - 31 .	
	Upper floors	-NA-	-NA-	-NA-
	the state of the s	-NA-	-NA-	-NA-
11	Sprinkler above false ceiling Internal Hudge 4	-NA-	-NA-	-NA-
11	Internal Hydrants.			1 - 1 -
	Size of Riser/Down-comer	Required	Provided	MR
	Number of Hydrant per floor	Required	Provided	MR
	Hose box.	Required	Provided	MR
12	Yard Hydrants.	E COLOR		IVIIC
mire	Total number of hydrants.	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
13	Pumping arrangements.	1111	-11/4-	-NA-
, A	Ground Level		or family is the st	
	Discharge of main pump.	-NA-	-NA-	-NA-
	> Head of main pump.	-NA-	-NA-	-NA-
	> Number of main pumps.	-NA-	-NA-	-NA-
	> Jockey Pump output.	-NA-	-NA-	-NA-
	> Jockey Pump head.	-NA-	-NA-	-NA-
	> Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	> Auto Starting / Manual Stopping.	-NA-	-NA-	-NA-
	> Pump House Access	-NA-	-NA-	-NA-
	Terrace Level		-NA-	-NA-
		900 LPM	Provided	1 MD
	 Discharge of pump. Head of pump. 	40 m	Provided	MR MR
	> Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14	Captive water storage for Fire Fighting.	142	12 - 17 - 182	
	Underground tank capacity.	-NA-	-NA-	-NA-
	> Draw-off connection.	-NA-	-NA-	-NA-
	Fire Service Inlet.	-NA-	-NA-	-NA-
	Access to tank.	-NA-	-NA-	-NA-
- 41	Overhead tank capacity.	20,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	Park Total		
	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	 Pressurization of lift lobby. 	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	• Fireman's switch.	-NA-	-NA-	-NA-
	Lift signage.	-NA-	-NA-	-NA-
- 1	Standby Power Supply			



Refuge Area			
Total area Location	-NA-	-NA-	-NA-
	-NA-	-NA-	-NA-
Fire Control Room.			
Detector System Panel.	-NA-	-NA-	-NA-
Flow Switch Panel.	-NA-	-NA-	-NA-
PA system Panel.		-NA-	-NA-
Battery backup Building floor plan	-NA-	-NA-	-NA-
	-NA-	-NA-	-NA-
Special Fire Protection System for the Protection of special Risk, if any:	-NA-	-NA-	-NA-
The same of the sa	Total area Location Fire Control Room. Detector System Panel. Flow Switch Panel. PA system Panel. Battery backup Building floor plan Special Fire Protection System for the	Total area Location -NA- Location -NA- Fire Control Room. Detector System Panel. Flow Switch Panel. PA system Panel. PA system Panel. Battery backup Building floor plan -NA- Special Fire Protection System for the	Total area Location -NANANANA- Fire Control Room. Detector System PanelNANANANANANANANA

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 625 dated 15/11/2023.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer

Www

Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Design: ADO (BCP)

CFO (HQ)

Hugh H 12 2022

Dôreeta

Ano 1000

29/12/23