

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

F.6/DFS/MS/Hospital/2023/SZ/ 624 No.

Dated: 24././2\_/2023

## FIRE SAFETY CERTIFICATE

Certified that the Dr. B.R Sur Homeopathic Medical Collage, Hospital & Research Centre Situated at Nanakpura, Moti Bagh, New Delhi 110021 comprised of Ground plus three upper floors was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/Hospital/2020/SZ/451 dated 03-11-2020. The Hospital was re-inspected by officers concerned of this department on 22/12/2023 in the presence of Mr. Yogesh Kumar and observed that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class Group-C Institutional Building (Hospital) with effect from 29 /12 /2023 for period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued 29/12 2023 at New Delhi by

DIRECTOR Délhi Fire Service

Copy to: -

1. Mr. Neeraj Gupta (Principal/HOD) Dr. B.R Sur Homeopathic Medical Collage, Hospital & Research Centre Situated at Nanakpura, Moti Bagh, New Delhi 110021

## Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL- 2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.



NISS

-	DIGRECTIC	N DEPOPT				
-		INSPECTION REPORT  Dr. B.R Sur Homeopathic Medical Collage, Hospita				
	Name & Address of the Building	& Research Centre Situated at Nanakpura, Moti Bagn,				
2		New Delhi 110021 Institutional building, "Group-C" (Hospital)				
3	Type of Occupancy	Ground + 03 upper floors.				
4	Building Comprised of	Renewal				
5	Type of Case	F.6/DFS/MS/Hospital/2020/SZ/451 dated 03-11-2020				
6	Details of Previous NOC					
7	Fire Safety Directives Letter No	Nil				
8	Date of Inspection	22/12/2023 DO (South) & ADO (BCP)				
9	Name of the Inspecting Officers  Name & Designation of Officers from the building side	DO (South) & ADO (BCP) Mr. Yogesh Kumar				
10	Year of construction	1979				
11	Applicant letter No.	Email dated 29/11/2023				
S. No.	Minimum standards on Fire Prevention	Old NOC Provided at Site Remark				
	and Fire Safety U/R 33	requirements		MR/NMF		
1	Access to Building.					
	Road width	Accessible	9 mtr	MR		
-	Gate width	5 mtr	5 mtr	MR		
	Width of internal road	-NA-	-NA-	-NA-		
2	Number, width, type & arrangement of exits.					
	a) Number of Staircase					
	> Upper floors.	02 Nos	Provided	MR		
-1	Basement floor.	-NA-	-NA-	-NA-		
- 1	b) Width of Staircase					
- /	> Upper floors	1,30 mtr (each)	2 mtr & 1.3 mtr	MR		
	➤ Basement floor	-NA-	-NA-	-NA-		
	c) Protection of exits			E015-15-		
	> Fire check door	-NA-	-NA-	-NA-		
	> Pressurization	-NA-	-NA-	-NA-		
	d) No. of continuous staircase to terrace		Provided			
- 1	e) Width of corridor	Required -NA-	-NA-	MR -NA-		
10	n Door size	1mtr	1 mtr & 1.50 mtr			
3	Compartmentation.	1 IIIII 1	1 mu & 1.30 mu	MR		
-	Fire check door.	-NA-	NA	1 274		
			-NA-	-NA-		
, 1	Sealing of electrical shafts.	Required -NA-	Provided	MR		
	Fire rating of shaft door.	-NA-	-NA-	-NA-		
	Water curtain		-NA-	-NA-		
	• Fire dampers.	-NA-	-NA-	-NA-		
4.	Smoke Management system.	20.10777				
	Basement	30 ACPH	-NA-	-NA-		
	Upper floors	12 ACPH	Natural ventilation	MR		
5.	Fire Extinguishers.					
	Total numbers	Required	36 Nos	MR		
	Types	ISI marked	ABC & Co2	MR		
	ISI Marking		Provided	MR		
6.	First Aid Hose Reels.		1 TOVICES	MK		
0.	Total numbers on each floor.	02 Nos at each	Description	1		
	Section 2015 All Control of the Cont	Transferrence of the contraction	Provided	MR		
	Length of hose-reel hose.	30m	Provided	MR		
	Nozzle Diameter	5mm	Provided	MR		
7	Automatic fire detection & alarming system.					



N139

		Demised	Ground floor	MR
	Location of Main Panel	Required -NA-	-NA-	-NA-
	Location of Repeater Panel     Alternate source of power	Required	Provided	MR
	Hooter's location	Required	All Areas	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	Basement	-NA-	-NA-	-NA-
	Upper floors (except EE area)	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11.	Internal Hydrants.			
	<ul> <li>Size of Riser/Down-comer</li> </ul>	150 mm	Provided	MR
	Number of Hydrant per floor	02 Nos	Provided	MR
	Hose box.	02 Nos	Provided	MR
12.	Yard Hydrants.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	galeridansk priesent i	177 3
	Total number of hydrants.	-NA-	04 Nos	-NA-
	Hose box.	-NA-	04 Nos	-NA-
13.	Pumping arrangements.	15	12 1-4	
	Ground Level		and the second of the second	
	Discharge of main pump.	1620 LPM	Provided	MR
	> Head of main pump.	60 mtr	Provided	MR
	Number of main pumps.	01 Nos	Provided	MR
	<ul> <li>➢ Jockey Pump output.</li> <li>➢ Jockey Pump head.</li> </ul>	180 LPM	Provided	MR
	Standby Pump output.	60 mtr	Provided	MR
	> Standby Pump head.	1620 LPM	Provided	
	Auto Starting/Manual Stopping.	60 mtr	Provided	MR
	Pump house access.	777 COST (1777 PE)		MR
	- M	Required	Provided	MR
	Terrace Level	Required	Provided	MR
	➤ Discharge of pump.	-NA-	1460 I DV C 100 I TO 1	
	➤ Head of pump.	-NA-	450 LPM & 180 LPM	-NA-
	➤ Power supply.	-NA-	Provided	-NA-
	Auto starting of pump.	-NA-	Provided Provided	-NA-
14.	Captive water storage for fire fighting.	1.11	Tiovided	-NA-
	<ul> <li>Underground tank capacity.</li> </ul>	50,000 Ltr	1.00.0001	
	Draw-off connection.	Required	1,00, 000 ltrs	MR
	Fire Service Inlet.	Required	Provided	MR
15.	Access to tank.	Required	Provided Provided	MR
	Overhead tank capacity.	10,000 Ltr	Provided	MR
6.	Exit Signage.	Required	Provided	MR
٠,	Provision of Lifts.		- TOTIGG	MR
	Pressurization of lift shaft.	-NA-	-NA-	NIA
	Pressurization of lift lobby.     Communication in 150	-NA-	-NA-	-NA-
	Communication in lift car.     Fireman's switch.	Required	Provided	-NA-
		Required	Provided	MR
7.	Lift signage.  Standby Parker S.	Required	Required	MR
8.	Standby Power Supply	Required	Provided (DG Set)	MR
-	Refuge Area		Trovided (DG Set)	MR
	Total area	-NA-	-NA-	
	Location	-NA-		-NA-
9.	Fire Control Room.		-NA-	-NA-







	Detector system panel.     Flow switch panel.	Required -NA-	Provided -NA-	MR -NA-
	<ul> <li>PA system panel.</li> </ul>	Required	Provided	MR
	<ul> <li>Battery backup.</li> </ul>	Required	Provided	MR
	Building floor plan.	-NA-	-NA-	-NA-
20.	Special Fire Protection System for the Protection of special Risk, if any.	Required	LT, HT & Transformers provided with Co2 flooding	MR

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued &

communicated by this department vide letter of even no 1819 dated 28/08/2023.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/Hospital/2020/SZ/451 dated 03-11-2020, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Muy

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma Design: DO (South) Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

26 m 2023
Directo My 10/m

F.t. lette is put up of my, pl

Di- 1000 29/10/20

1 Myll 20/14.