आज़ादी ब अगृत महोत्सव

No.F6/DFS/MS/School/NDZ/2023/940

Dated: 29/12/2023

FIRE SAFETY CERTIFICATE

Certified that the Govt. Girls Sr. Sec. School located at Saboli, Delhi-110093, comprised of ground plus one upper floor (two old blocks), owned/occupied by Govt. Girls Sr. Sec. School was issued Fire Safety Certificate vide letter No. F6/DFS/MS/School/20020/NDZ/344 dated 11/09/2020. The School building was re-inspected by the officer concerned of this department on 22/12/2023 in presence of Mr. Subhash Chand, Estate Manager and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the Fire Prevention and Fire Safety requirements in accordance with Circular No. F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by Director of Education and that the building is fit for occupancy class "Educational" (Group-B) with effect from 29/12/2023 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010. Subject to conditions printed below.

Issued on 29 12 202 at New Delhi by.

(ATI/L GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to:-

- 1. The Joint Director of Education, Director of Education, Lucknow Road, Delhi-110054
- 2. The Principal, Govt. Girls Sr. School at Saboli, Delhi-110093.

Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

			INSPEC	TION REPOR	T			
	Name & address of the building			Govt. Girls Sr. Sec. School located at Saboli Delhi-110093.				
2	Building is comprised of			Ground + 01 upper floors (02 old building blocks)				
3	Type of occupancy			Educational Building				
1	. The state of		case	Renewal				
		_	of previous FSC	F6/DFS/MS/School/20020/NDZ/344 dated				
5	Deta	1113	or previous roe	11/09/2020				
6	Fire safety directives letter no.		ety directives letter no.	F16/Estate/CC/Fire Safety/2011/3298-3398 dated 01.03.2011.				
7	Date	e of	inspection	22.12.2023				
8			of the inspecting officers	Vashwant Sing	h Meena ADO (L.N)			
9	Nar	ne	of the designation of from the building side		hand, Estate Manage			
10			f construction	1997				
11	1277	200	ant's letter no.	Email dated 19	/12/2023			
70.00		_	um standard of fire		Provided at	Remarks		
S.N o	503374	2000	ntion and fire safety U/R		site	MR/NMR		
1	Access to Building:			l.	•			
	Α	R	oad width	6.0 mtrs.	6.0 mtrs.	MR		
	В	G	ate width	N/A	N/A	N/A		
	C Width of internal road			N/A	N/A	N/A		
2	Number, Width, Type and Arrangement of Exits:							
7	A	N	umber of staircases					
		a	Upper floor block 1	01 nos.	01 nos.	MR		
			Upper floor block 2	01 nos.	01 nos.	MR		
		c	Basement	N/A	N/A	N/A		
	В		Vidth of staircases			5		
		a	Upper floor block 1	1.50 mtrs	1.50 mtrs /	MR		
		-	Upper floor block 2	1.50 mtrs	1.50 mtrs /	MR		
		b	Basement	N/A	N/A	N/A		
	C		rotection of exits					
	_	a	[N/A	N/A	N/A		
		b	Pressurization	N/A	N/A	N/A		
	D	1997	No. of continuous staircases o terrace	01 nos.	01 nos. each block	MR		
	E		Vidth of corridor	1.50 mtrs.	1.50 mtrs.	MR		
	F	I	Door size	1.0 mtrs.	1.0 mtrs.	MR		
3	Compartmentation:							
	A	The state of the s		NA	NA	NA		
	В	S	Sealing of electrical shafts	N/A	N/A	N/A		
	C	_	ire rating of shaft door	N/A	N/A	N/A		
	D	-	Water curtain	N/A	N/A	N/A		
	E	_	rire dampers	N/A	N/A	N/A		
4	Sr	_	te Management System:	A				
	A	-	Basement	N/A	N/A	N/A		
	B	I	Jpper floor	N/A	N/A	N/A		

W

alla HIII

	A	Extinguisher: Total numbers	08 nos.	27 nos.	MR		
	В	Types	CO ₂ & ABC	CO ₂ & ABC	MR		
	C	ISI marking	ISI Marked	Provided	MR		
6	35	st-Aid-Hose Reel:	151 Warked	11011400			
U	A	Total numbers of each	N/A	N/A	N/A		
	D	floor	N/A	N/A	N/A		
	B	Length of hose reel hose	COMPANY	N/A	N/A		
_	C	Nozzle diameter	N/A	896.63			
7	Automatic Fire Detection and Alarming System:						
	A	Type of detectors	N/A	N/A	N/A		
	B	Location of main panel	N/A	N/A N/A	N/A		
	C	Location of repeater panel	N/A	N/A	N/A		
	D	Alternate source of power	N/A N/A	N/A N/A	N/A		
0	E	Hooters	1-	N/A N/A	N/A		
8	-	OEFA:	N/A		N/A		
9	-	blic Address System:	N/A	N/A	INIA		
10	-	tomatic Sprinkler System:	Trin I a		LATIA		
	A	Basement	N/A	N/A	N/A		
	B	Upper floor	N/A	N/A	N/A		
	C	Sprinkler above false ceiling	N/A	N/A	N/A		
11	In	ternal Hydrants:					
	A	Size of riser/down-comer	N/A	N/A	N/A		
	В	Number of hydrants per floor	N/A	N/A	N/A		
	C	Hose box	N/A	N/A	N/A		
12	Yard Hydrants:						
	A	Total number of hydrants	N/A	N/A	N/A		
	В	Hose box	N/A	N/A	N/A		
13		mping Arrangements:	1				
1	-	Fround level					
1	10.5	Discharge of main pump	N/A	N/A	N/A		
	A	Head of main pump	N/A	N/A	N/A		
	В		N/A	N/A	N/A		
	C	Number of main pumps	N/A	N/A	N/A		
	D	Jockey pump out put	- Marines de la company	N/A	N/A		
	E	Jockey pump head	N/A N/A	N/A	N/A		
	F	Standby pump out put		N/A	N/A		
	G	Standby pump head	N/A	N/A N/A	N/A		
	H	Auto starting /manual	N/A	IVA	NA		
		stopping	27/4	N/A	N/A		
	I	Pump house access	N/A	IN/A	1471		
2	Te	rrace Level		DI/A	N/A		
-	A	Discharge of pump	N/A	N/A	N/A		
	В	Head of the pump	N/A	N/A	N/A		
	C	Power supply	N/A	N/A	N/A		
- 1	D	Auto starting of pump	N/A	N/A	IN/A		



14	Ca	ptive Water Storage for Fire Fight	N/A	N/A	N/A	
7.	A	Underground tank capacity	N/A	N/A	N/A	
	B	Draw-off connection	THE RESERVE OF LINE AND ADDRESS OF THE PARTY	N/A	N/A	
	C	Fire service inlet	N/A	N/A	N/A	
	Ď	Access to tank	N/A	N/A	N/A	
	E	Overhead tank capacity	N/A	N/A	N/A	
15	Exit Signage:		N/A	INA		
	Provision of Lifts:					
16		Pressurization of lift shaft	N/A	N/A	N/A	
	A	Pressurization of lift lobby	N/A	N/A	N/A	
	B	Communication in lift car	N/A	N/A	N/A	
	C	Firemen's grounding switch	N/A	N/A		
	D		N/A	N/A	N/A	
	E	Lift signage	N/A	N/A	N/A	
17	Sta	ndby Power Supply:				
18	Refuge Area:		N/A	N/A	N/A	
24000	A	Total area		N/A	N/A	
		Location	N/A	137.2		
19	Fir	e Control Room:	127/4	N/A	N/A	
-	A	Detector system panel	N/A	N/A	N/A	
ŀ	B	Flow switch panel	N/A	N/A	N/A	
ł	C	PA system panel	N/A	N/A	N/A	
1	D	Battery backup	N/A	N/A	N/A	
ł	E	Building floor plans	N/A	N/A	N/A	
20	Special Fire Protection systems for protection of special Risks, if any:		N/A	IWA		

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education Circular no F16/Estate/CC/Fire Safety/2011/3298-3398 dated 01.03.2011, the FSC issued vide letter no. F6/DFS/MS/School/20020/NDZ/344 dated 11/09/2020 is recommended to be renewed.

Signature of the Inspecting Officer

Name:- Yashwant Singh Meena

Designation:- ADO (L.N)

Dy.CFO(MDZ)

26/2/23

Dinector

Andrin

P. T. O