

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

F.6/DFS/MS/EH/2023/SZ/374 No.

Dated..26/.12/2023

FIRE SAFETY CERTIFICATE

Certified that th Eating House in the Name & Style of M/s Tatou situated at Unit No 203A & 303, First Floor & Second Floor, D-58 & D-59, Khasra no 286-1 and 286-1, 100 ft road Chattarpur, New Delhi 110074 Comprised of Basement Ground plus Two upper floor owned/Occupied by A Unit of Yuvi Triumph Pvt Ltd have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 23/12/2023 on in the presence of Mr. Sarukh and found that the premise is fit for occupancy Group "D" Assembly Building (Restaurant at First & Second only) and validity upto 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 26 / 12 /2023 at New Delhi by

DELHI FIRE SER

Copy to: -

1. The Dt. Health Officer, (MCD), Public Health Department, Aurobindo Marg, Green Park, New Delhi-110016. (Ref. MHA Portal 2023122119804 dated 22/12/2023)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. The basement shall be used as per the provisions of UBBL 2016 /NBC Part- IV.

4. All the staff members must know the correct method of operation of fire fighting system.

The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. form is available on www.dfs.delhigovt.nic.in

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."





	rame & Address	of the Rustal	ION REPORT			
110			M/s Tatou (A Unit of Yuvi Triumph Pvt situated at Unit No 203A 7 303, First Floor			
2	Type of Occupano	W.	Second Floor, D-58 & D-59, Khasra no 286-1			
3	Building comprised of		286-1, 100 ft road Chattarpur, New Delhi 110074 Restaurant at First Floor & Second floor only			
4	Type of Case					
5	Details of D		Basement, Ground plus Two upper floors			
6	Details of Previou	s NOC	New case			
7	rire Safety Direction		Nil			
			Nil			
8	Name of the Inspect		23/12/2023			
9	Name of the Inspecting Officers Name & Designation		DO (South) & ADO (BCP)			
10	Name & Designation of Officers from the building side Year of construction		Mr. Sarukh (Manger)			
11	A 1		2022			
S. No.	Applicant letter N	0.	MHA Portal 2023122119804 dated 22/12/2023			
3. No.		ds on Fire Prevention R 33	UBBL 2016	Provided at Site	Remarks MR/NMR	
•	Access to Building.	4.14			WINININ	
	 Road width 		09 m	09 m	MR	
	Gate width		06 m	06·m	MR	
2	Width of int	ernal road	NA	N/A	N/A	
	Number, width, ty	pe & arrangement of e	xits			
	a. Number of Stai					
	Upper floor Basement fl		02 Nos	Provided	MR	
	b. Width of Staire		-NA-	N/A	N/A	
	Upper floor:		1.50 mtr each	Provided	MR	
	Basement floor		-NA-	N/A	N/A	
	c. Protection of ex	rits			157753711	
	Fire check d		-NA-	N/A	N/A	
	Pressurization		-NA- Required	N/A Provided	N/A Provided	
	*****	us staircase to terrace	N/A	N/A	N/A	
	f. Door size		1.50 mtr each	1.50 mtr &1.50 mtr	MR	
3	Compartmentation					
			-NA-	N/A	N/A	
		lectrical shafts.	-NA-	N/A	N/A	
-	Sealing of each of the sealing	f shaft door.	-NA-	N/A	N/A	
	Water curtain		-NA-	N/A	N/A	
	Fire damper	S	-NA-	N/A	N/A	
4	Smoke Management system.					
	Basement		-NA-	N/A	N/A	
	 Upper floors 		Required	Natural ventilation	MR	
5	Fire Extinguishers.		Peguired	08 Nos	MR	
	Total numbers		Required ABC / CO2	ABC & Co2	MR	
	Types ISI Marking		ISI marked	Provided	MR	
	ISI Marking A id Hose Rec	S.	- ji		300000	
6	First Aid Hose Reels. Total numbers on each floor.		01 Nos	Provided	MR	
	r of hose-reel hose.		30m	Provided	MR	
	1 Diameter		5mm	Provided	MR	
7	Automatic fire detect	ion & alarming system.				
1	Type of dete	etors	Smoke & Heat	Provided	MR	





	Location of Main Panel	Required	Provided	MI
	Location of Repeater Panel	-NA-	-NA-	-NA
	Alternate source of power	Required	Provided	ME
	Hoofer's location	Required	Provided	MF
	10000	Require		
8	MOEFA	Required	Provided	MF
	Public Address System	-NA-	-NA-	-NA
9	32.262			1
10	Automatic Sprinkler System	-NA-	Provided	-NA
	Basement	-NA-	-NA-	-NA
	Upper floors	-NA-	-NA-	-NA
	Sprinkler above false ceiling	-1174		
11	Internal Hydrants.	(<u>1</u>		MR
	Size of Riser/Down-comer	100mm	Provided	MR
	Number of Hydrant per floor	01 Nos	Provided	MR
	Hose box.	01 Nos	Provided	MIK
12	Yard Hydrants.	100	The second	40 00
	Total number of hydrants.	-NA-	-NA-	-NA-
	Total number of nydrams. Hose box.	-NA-	-NA-	-NA-
13	Pumping arrangements.		4	
-	Ground Level		100 37 7 2	
	100 No. 100 No	2280 LPM	Provided	MR
	 Discharge of main pump. Head of main pump. 	60m	Provided	MR
	 Head of main pump. Number of main pumps. 	02 no	Provided	MR
	> Jockey Pump output.	180 LPM	Provided	MR
	> Jockey Pump head.	60m	Provided	MR
	Standby Pump output.	2280 LPM	Provided	MR
	Standby Pump head.	60m	Provided	MR
	Auto Starting / Manual Stopping.	Required	Provided	MR
	Pump House Access	Required	Provided	MR
	Terrace Level	Patricks Family		-0
	> Discharge of pump.	450 LPM	Provided	MR
	> Head of pump.	40 m	Provided	MR
	> Power supply.	Required	Provided	MR MR
14	 Auto starting of pump. Captive water storage for Fire Fighting. 	Required	Provided	MIK
190		01111	D. C. L.	MR
	 Underground tank capacity. Draw-off connection. 	01 lakhs Required	Provided Provided	MR
	Fire Service Inlet.	Required	Provided	MR
	> Access to tank.	Required	Provided	MR
	 Overhead tank capacity. 	10,000 Ltrs	20,0000 ltr	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	 Pressurization of lift lobby. 	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	Fireman's switch.	-NA-	-NA-	-NA-
	Lift signage.	-NA-	-NA-	-NA-
17	Standby Power Supply	-NA-	-NA-	-NA-

7

V





	-NA-	-NA-	-NA-
Fire Control Room.	-NA-	-NA-	-NA-
Detector System Panel. Flow Switch P.	-NA-	-NA-	-NA-
	-NA-	-NA-	-NA-
Special Fire Protection System for the Protection of special Risk, if any:	-NA-	-NA-	-NA-
	Detector System Panel. Flow Switch Panel. PA system Panel. Battery backup Building floor plan Special Fire Protection System for the	Location -NA- Fire Control Room. Detector System Panel. Flow Switch Panel. PA system PanelNA- Battery backup Building floor plan -NA- Special Fire Protection System for the	-NANANANANANANANA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer

Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Design: ADO (BCP)

СБО (НО)

18 12023

Denetar

59/1

36/15/53 18/03/53