

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

F.6/DFS/MS/EH/2023/SZ/381 No.

Dated. 2.9/.12./2023

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style M/s ITP Laidback Cafe situated at 1st 2nd & 3rd floor, M-51, M- Block Market, Greater Kailash - II, New Delhi 110048 comprised of basement (not part of restt.) ground and three upper floor owned/occupied by Unit of World of Shalom Restaurant Pvt Ltd was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/EH/SZ/2021/09 dated 07/01/2021. The restaurant premise was re-inspected by the officer concerned of this department on 20/12/2023 in the presence of Sh. Dhiraj Arora of the restaurant and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" Restaurant at 1st 2nd & 3rd floor only) and validity upto 31/03/2026 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 29 / 12 /2023 at New Delhi by

(ATEL GARG) DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Dy. Health Officer, Public Health Department, MCD, Green Park, Delhi- 110016 (Ref. MHA Portal No. 2023112918969 dated 07/12/2023)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the

3. All the staff members must know the correct method of operation of fire fighting

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

5. This fire safety certificate may not in any way be treated as regularization (Clause UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of

UBBL-2016), if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six מונמ

1	INSPECTIO	N REPORT	आजादी	Wit .			
1	Name & Address of the Building	M/s ITP Laidback Café (Unit of World of Shalom Restaurant Pvt Ltd) situated at 1 st 2 nd & 3 rd floor, M-51, M- Block Market, Greater Kailash – II, New Delhi 110048					
2	Type of Occupancy	Restaurant at 1st 2nd & 3rd Floor only					
3	Building Comprised of	Basement, Ground + Three upper floors					
4	Type of Case	Renewal					
5	Details of Previous NOC	F.6/DFS/MS/EI	H/SZ/2021/09 dated 07/0	01/2021			
6	Fire Safety Directives Letter No	Cir.No.F.6/DFS/	EH/MS/ 2005/718 dated 04	1/04/2005			
7	Date of Inspection	20/12/2023	Market City 21 St.	17 0			
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)					
9	Name & Designation of Officers from the building side	Mr. Dhiraj Arora					
10	Year of construction	1999					
11	Applicant letter No.	MHA Portal No. 2023112918969 dated 07/12/2023					
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Curro		Remarks MR/NMR			
1	Access to Building.			-1 Ta			
	Road width	Required	9m	MR			
	Gate width	N/A	N/A	N/A			
	Width of internal road	N/A	N/A	N/A			
2	Number, width, type & arrangement of ex	its.					
	a) Number of Staircase						
	> Upper floors.	02 Nos	02 Nos	MR			
	➤ Basement floor.	N/A	Not part of Restt.	N/A			
	b) Width of Staircase	And I	3000 1-000 3000				
	> Upper floors	1m & 1.25 m	1m & 1.25 m	MR (old case)			
	> Basement floor	N/A	N/A	N/A			
	c) Protection of exits	75,000 000					
	➤ Fire check door	N/A	N/A	N/A			
	> Pressurization	N/A	N/A	N/A			
	d) No. of continuous staircase to terrace	Required	One	MR			
	e) Width of corridor	N/A	N/A	N/A			
	f) Door size	1 mtr	1 m (2 Nos)				
3	Compartmentation.		T III (Z NOS)	MR (old case			
	Fire check door.	N/A	N/A	NIA			
	Sealing of electrical shafts.	N/A	N/A N/A	N/A			
	Fire rating of shaft door.	N/A		N/A			
	Water curtain	N/A	N/A N/A	N/A			
	Fire dampers.	3-100-3-40		N/A			
4	Smoke Management system.	N/A	N/A	N/A			
	Basement	30 ACPH	N/A	N/A			
	Upper floors	12 ACPH	Exhaust Fans Provided	d MR			
5	Fire Extinguishers.		1111111111111	0.14			
	Total numbers	10 Nos	10 Nos	M			
	Types	ABC/CO ₂	1,012,312,310,000	MR			
	ISI Marking	ISI marked	ABC- & CO ₂ -	MR			
6	First Aid Hose Reels.	151 Hid Ked	Provided	MR			
	Total numbers on each floor.	One	Description				
	Length of hose-reel hose.	20 A TOVIDOD		MR			
	Nozzle Diameter		Provided	MR			
	- MANUTA	5mm	Provided	MR			

	15
N	W
1	

		NIV	91.	ृत मह
	Automatic fire detection & alarming syst	em.		
	 Type of detectors 	N/A	N/A	
	 Location of Main Panel 	N/A	N/A	
	 Location of Repeater Panel 	N/A	N/A	
	Alternate source of power	N/A	N/A	
	Hooter's location	N/A	N/A	
	140-25-24-25		Provided	
8	MOEFA	Required	N/A	1
9	Public Address System	N/A	NIA	-
10	Automatic Sprinkler System		N/A	III
	Basement	N/A	Provided	N
	Ground floor.	Required	N/A	N
	Sprinkler above false ceiling	N/A	N/A	
11	Internal Hydrants.	approximation of	100 mm	M
nka-	Size of Riser/Down-comer	Required	One	M
	Number of Hydrant per floor	Required Required	One	M
	Hose box.	Koquiros		1
12	Yard Hydrants.	N/A	N/A	N/
	Total number of hydrants.	N/A	N/A	N/
	Hose box.	IMA		
13	Pumping arrangements.		Maria Caracana	1
	Ground Level Discharge of main pump.	N/A	N/A	N/
	Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	> Standby Pump output.	N/A	N/A	N/A
	 Standby Pump head. Auto Starting/Manual Stopping. 	N/A	N/A	N/A
	> Pump house access.	N/A	N/A	N/A
		N/A	N/A	N/A
	Terrace Level	205 0 100 I PM	450 LPM x 2	MF
1	> Discharge of pump.	225 & 180 LPM 40 m	Provided	MR
	Head of pump.Power supply.	Required	Provided	MR
	> Auto starting of pump.	Required	Provided	MR
14		Required	a la Alemana a	
14	Underground tank capacity.	N/A	N/A	N/A
	> Draw-off connection.	N/A	N/A	N/A
	➤ Fire Service Inlet.	N/A	N/A	N/A
	> Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	5,000 Ltrs	10,000 ltr	MR
15	Exit Signage.	Required	Provided	MR
16				y
	Pressurization of lift shaft.	N/A	N/A	N/A
1	Pressurization of lift lobby.	N/A	N/A	N/A
	Communication in lift car. Fireman's switch.	N/A N/A	N/A	N/A
	Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	N/A Provided	N/A
18	Refuge Area	oquitoi	Provided	MR
	Total area			



ALL		V 3 4	ानृत महास्वय	
	• Location	N/A	N/A	N/A
19	Fire Control Room.			
	Detector system panel.	N/A	N/A	N/A
	Flow switch panel.	N/A	N/A	N/A
	PA system panel.	N/A	N/A	N/A
	Battery backup.	N/A	N/A	N/A
	Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/EH/SZ/2021/09 dated 07/01/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer

Name: Sh. Manoj Kumar Sharma Design: DO (South) Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Design: ADO (BCP)

CFO (HQ

N 12 2023

Director

ou BLP. 91

F.P. lette is put up for sing. pl

Dr- 100 Mgg/p/m

mell 23/17/3

01/01/24