
Dated: 02/01/2024

Ph:-011-23414000





No. F6/DFS/MS/2024/School/03



A Promisi Companyor Colomb

FIRE SAFETY CERTIFICATE

Certified that the Govt. Girls Senior Secondary School located at Azadpur Colony, Delhi110033 comprised of 03 blocks, Ground & first floor each only interconnected owned/
occupied by Govt. Girls Senior Secondary School was issued Fire Safety Certificated vide this
office letter no. F6/DFS/MS/2021/School/WZ/156 dated 25.02.2021. The premise was
inspected by the officer concerned of this department on 21.12.2023 in the presence of Sh. Raj
Singh Schrawat (Estate Manager) and observed that all the fire safety arrangements as
provided in the premises found in good working condition. The premises have deemed complied
with requirements of circular issued by Director of Education vide letter no 3298-3398 dated
01.03.2011 and the building/ premise is fit for occupancy class "Group B Educational" with
effect from . 22 21.224... for a period of three years, subject to compliance of the
conditions mentioned below:

Issued on . 0.2. 01.]. 2024...... at New Delhi

Copy to: -

1. The Director of Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.

The Principal, Govt. Girls Senior Secondary School located at Azadpur Colony, Delhi-110033.

Conditions for the validity of Fire Safety Certificate:

1 All the means of escape/entry/exit shall be kept free from any obstruction.

2 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3 All the staff members must know the correct method of operation of firefighting system.

The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

5 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

Name & address of the building Type of Occupancy 2.

: Govt. Girls Senior Secondary School located at Azadpur Colony, Delhi-33.

: Educational

3. Type of Case

1.

: Renewal

Composition of building 4.

: 03 blocks (Ground & First Floor Each, interconnected)

Details of previous NOC 5.

: F6/DFS/MS/2021/School/WZ/156 dated 25.02.2021

Fire Safety directives letter No 6.

: Nil

Date of inspection

: 21.12.2023

Name of the Inspecting Officers

: ADO (RN)

9. Name and designation of officers

from the building side

: Sh. Raj Singh Sehrawat (Estate Manager)

10. Year of Construction

: 1972, 2005-06, 2010-11

11. Applicant's letter No.

: Online E-mail ID dated: 17.12.2023

	Minir	num Standards on fire prevention and fire safety U/R 33	Requirement as per Rule 35 (6)	Provided at site	Remarks MR/NMR		
	Access to building						
	•	Road width	06m	06m	MR		
	2.0	Gate width	Direct Accessible	Direct Accessible	MR		
	•	Width of internal road	NA	NΛ	NA		
	Numb	er, Width, Type & Arrangement of Exits	N.				
	a. Nun	ber of staircases					
		Upper Floors	03	03	MR		
		Basements					
	b. Wic	th of staircases					
		Upper Floors	1.5 m	02 nos. of 1.50m & 01 nos. of 1.45m	MR (old case)		
		Basements	NA	NA	NA		
	c. Pro	ection of exits					
	10	Fire check door	NA	NA	NA		
	y.	Pressurization	NA	NA	NA		
	d. No	of continuous staircases to terrace	NA	NA	NA		
	e. Wi	th of Corridor	NA	NA	NA		
	f. Do	or Size	1m	1 m	MR		
3	Com	Compartmentation.					
			NA	NΛ	NΛ		
	•	a V - Calcatrical chafts	NA	NA .	NA		
	8	Fire Rating of shaft door	NA	NA	NA		
		Water Curtain	NA	NA	NA		
		Fire Dampers	NA	NA	NA		
4	Smoke Management System.						
4	Sinc		NΛ	NA	NA		
		Basements Upper floors	Required	Natural Ventilated	MR		
5		Fire Extinguishers					
_	-	Total numbers	12nos	15nos	MR		





1.7	
90000	// ·

	• Types	ABC/Co2	ABC—12, CO2—03	MR	
	ISI marking	ISI Marked	Yes	MR	
ý.	First-Aid Hose Reels.				
	Total numbers on each floor	NA	NA	NA	
	Length of hose reel hose	NA	NA	NΛ	
	Nozzle diameter	NA	NA	NΛ	
7	Automatic fire detection and alarming system.				
	Type of detectors	NA	NA	NΛ	
	Location of Main Panel	NA	NA	NΛ	
	Location of Repeater Panel	NA NA	NA	NΛ	
	Alternate source of power	NA	NA NA	NA	
	Hooters' Location	NA	NA	NA	
3	MOEFA	NA NA	NΛ	NΛ	
,	Public Address System.	NA	NA	NΛ	
	*				
0	Automatic Sprinkler System.		5.4	· · · · · · · · · · · · · · · · · · ·	
	Basement	NA NA	NA NA	NA NA	
	Upper Floor	NA	NA		
	Sprinkler above false ceiling	NA	NA	NΛ	
I	Internal Hydrants	1.48			
	Size of riser/down-comer	NA	NA	NA	
	Number of hydrants per floor Hose Box	NA NA	NA NA	NA NA	
•	SSSAC	NA	NA	NΛ	
2	Yard Hydrants.				
	Total number of hydrants	NA	NΛ	NA	
	Hose Box	NA	NA	NΛ	
3	Pumping Arrangements.				
	Ground Level				
	Discharge of main Pump	N/A	N/A	N/A	
	> Head of Main pump	N/A	N/A	N/A	
	 Number of main pumps Jockey Pump out put 	N/A	N/A	N/A	
	 Jockey Pump out put Jockey pump head 	N/A	N/A	N/A	
	> Standby Pump out put	N/A	N/A	N/A	
	> Standby Pump Head	N/A	N/A	Ν/Λ	
	 Auto Starting/ Manual stopping Pump House Access 	N/A	N/A	N/A	
	Terrace level	N/A	N/A	N/A	
	> Discharge of pump	1725.7	NOSE	New Arts	
	➤ Head of the pump	NA	N/A	NΛ	
	Power Supply	NA NA	N/A	NA NA	
	➤ Auto Starting of pump	N/A	N/A	N/A	
	_	N/A	N/A	N/A	
11	No.	AR ORDER W.	. #CM #0#0	13/73	

	Underground tank capacity Draw-off connection	NA	NA	- NA		
	Fire service inlet Access to tank Overhead Tank capacity	NA -	NA //	NA		
		NA	NA	NΛ		
		NA NA	NA NA	NΛ		
		NA	N/A	NΛ		
15	Exit Signage.	NA	NA .	NA		
16	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A .	N/A		
17	Standby power supply	N/A	N/A	N/A		
18	Refug: Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/ checked randomly and found in good

working condition, at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. F6/DFS/MS/2021/School/WZ/156 dated: 25.02,2021.

Dy. Chief Fire Officer (WZ)

Signature of the Inspecting Officer Name:- 'C.L. Meena Designation:- Asst. Div. Officer (RN)