





GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/Hospital/2023/SZ/ o 3

Dated: 0 2/01/20284

FIRE SAFETY CERTIFICATE

Certified that the Patient Attendant Block, J.P.N. Apex Trauma Centre, AIIMS, Raj Nagar, New Delhi, comprised of lower ground, upper ground plus ten upper floors, owned/occupied by All India Institute of Medical Sciences (AIIMS) was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/Hospital/2017/SZ/121 dated 31/01/2017. The said building was re-inspected by the officer concerned of this department on 22/12/2023 in the presence of Sh. Prashant Kumar (JE/Elect.) & Sh. Ashok Sharma (Fire Consultant.) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the said building/premises is fit for occupancy class "Group 'A' Residential Building" (Patient Attendant Hostel) with effect from 02/01/2023 for a period of five years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS Rules, 2010.

Issued on 02 01 2024 at New Delhi by

DIRECTOR DELHI FIRE SERVICE

Copy to: -

1. Sh. Naresh Kumar Yadav, ASO / Fire Officer, AIIMS, New Delhi-110029

2. The Chief Architect, NDMC, Sansad Marg, Palika Kendra, New Delhi-110001

Conditions for the validity of Fire Safety Certificate:

I. All the means of escape/entry/exit shall be kept free from any obstruction.

- All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- Any deviation with regard to construction, ventilation, occupancy, electric installation etc, may be got verified from concerned authorities.
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules, 2010. The from is available on www.dfs.delhigovt.nic.in
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its

		ON REPORT	Direct IDM Aney Tr	auma	
1.	Name & address of the building	ss of the building Patient Attendant Block, JPN Apex Traum			
		Centre, Raj Nagar New Delhi-110029			
2.	Type of Occupancy	Residential Building (Group 'A')			
3.	Building Comprised of	Lower Ground, Upper ground plus ten upper floors. (Lower & upper ground has Offices and Halls. 1st (1st Appel 1st Ap			
		Floor to 10th Floor 06 room & 06 dormitory (04 bed each)			
4.	Type of Case	Renewal			
5.	Details of previous NOC	F6/DFS/MS/Hospital/2017/SZ/121 dated 31/01/2017			
6.	Fire Safety directives Letter	F6/DFS/MS/BP/2013/227 dated 13/08/2013			
2001	Date of inspection	22/12/2023			
7.	Name of Inspecting Officer	ADO (SJ), Santo	osh Kumar		
8.	Name and designation of officer (s)	Sh. Prashant Ku	mar, (JE/Elect.) &		
9.	from building side	Sh. Ashok Sharma, (Fire Consultant)			
	Year of Construction	2016			
10.		Email dated 11/	10/2023		
11.	Applicant letter No.	Requirement		Remarks	
. No.	Minimum standards on fire prevention and fire safety U/R 33	Existing Fire Protection System		MR/NMI	
•	Access of building			1.0	
1.	Road width	12m	24m	MR	
	Gate width	4.5m	9m	MR MR	
	width of internal road	6m	6m	MK	
	Number, width, Type & Arrangeme	ents of exits			
2.	a. Number of staircases			\ m	
	77 - O	LG-UG: 4 nos.		MR	
	Upper floors	UG-Terr: 2nos.		NIA	
	Basements	NA	NA	NA	
	b. Width of staircases			MD	
	Upper floors	2m / 1.5m	LG-UG: 2m, 2m, 1.5m & 7.3m ramp UG-Terr: 2m each	MR	
	Basements	NA	NA NA	NA	
	c. Protection of exits		1.000		
	Fire check door	Required	Provided	MR	
	Pressurization	NA NA		NA	
	d. No of continuous staircase to terrace	02 nos.	02 nos.	MR	
	e. Width of Corridor	NA	2m	NA	
	f. Door Size	1m / 2m	lm/2m	MR	
3.	Compartmentation		Fact Allows	100	
	Fire check door	Required	Provided	MR	
	 Sealing of electrical shafts 	Required	Provided	MR	
	 Fire Rating of shaft door 	Required Provided		MR	
	Water Curtain	NA	NA NA	NA	
	Fire Dampers	NA	NA	NA	
4.	Smoke managements System			177.00	
	Basements	NA	NA	NA	
	Upper floors	Required	Provided in corridors	s MR	
5.	Fire Extinguishers		I was seen	The same	
	Total numbers	50 nos. 70 nos.		MR	
	Types	ABC/W.CO ₂	ABC, CO ₂ &	MR	
	 ISI marking 	ISI marked	Provided	MR	
6.	First-Aid Hose Reels		Page transfer	1	
	 Total numbers on each floor 	02 nos. 02 nos.		MR	
	 Length of hose reel hose 	30m 30m		MR	
			5mm		

Renewal: Patient Attendant Block, JPN Apex Trauma Centre, AlIMS, Raj Nagar, New Delhi



N-7

<i>!</i>	Automatic fire detection and alarming system					
	•	Type of detector	Smoke & Heat	Provided	MR	
	•	Location of Main Panel	Ground floor	Provided	MR	
	-	Location of Repeater Panel	Fire Control Roo	m Provided	MR	
	•	Alternate source of power	Required	Provided	MR MR	
	•	Hooters' Location	All Areas	Provided		
3.	MOEFA		Required	Provided	MR	
0	Public	Address System	Required	Provided	MR	
U	Automatic Sprinkler System					
	•	Basements	NA	NA	NA	
		Lower Ground Floor	Required	Provided	MR	
1		Sprinkler above false ceiling	NA	NA	NA	
1	Interna	l Hydrants				
	900	Size of riser/down-comer	150 mm	Provided	MR	
		Number of hydrants per floor	02 nos.	02 nos.	MR	
12	Vard L	Hose Box Hydrants	02 nos.	02 nos.	MR	
~	1 aid F		04	In	100	
		Total number of hydrants Hose Box	04 nos. 04 nos.	Provided Provided	MR	
13		ing Arrangements	11.57.0.000	THE STORY TO SECOND	MR	
	•	Ground Level	Required	nps are common for entire Provided	MR	
		Discharge of main pump	2850 LPM (Two	TEMPORAL PROPERTY OF THE PROPE	MR	
	4		90m (each)	90m (each)	MR	
	>	Number of main pumps	Two	Two	MR	
	>		180+280 LPM	180+280 LPM	MR	
	>	25.5	90m (each)	90m (each)	MR	
	>	Standby Pump out put	2850 LPM	2850 LPM	MR	
	>	and the second s	90m	90m	MR	
	>	Auto Starting/Manual stopping		Provided	MR	
	4		Required	Provided	MR	
		Terrace level		1 (2015)	27.583	
	>	Discharge of pump	NA	900 + 900 LPM	NA	
	>	Head of the pump	NA	40m (each)	NA	
	>	Power supply	NA	Provided	NA	
	>	Auto starting of pump	NA	Provided	NA	
14	Capti	ve water Storage for fire fightin	g	The Control of the Co	US-SHARES.	
		Underground tank capacity	150,000 Ltrs	Provided	MR	
	>	Draw of connection	Required	Provided	MR	
	> Access to tank		Required	Provided	MR	
			Required	Provided	MR	
			10,000 Ltrs	15,000 Ltrs	MR	
15	Exit S	ignage	Required	Provided	MR	
16.		sion of Lifts		Trovided	IVIK	
	>	Pressurization of Lift Shaft	Required	Provided	MR	
	>	The state of the state of	Required	Provided	MR	
	>	Communication in lift Car	Required	Provided	MR	
	 Fireman's Grounding Switch 		Required	Provided	MR	
	>	Lift Signage	Required	Provided	MR	
17.	Stand	by power supply	Required	Provided	MR	
18.	+	e Area	(Approximately)		MIK	
	>	Total area		Balcony provided in each room on outer periphery	NA	
	4	Location		NA	NA	

ogar, New Delhi



19.	Fire control room			_
	 Detector system panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	Required	Provided	MR
		NA	NA	NA
		Required	Provided	MR
		Required	Provided	MR
		NA	NA	NA
20.	Special Fire Protection Systems for Protection of special Risks, if any;	HT, LT & Transformer are provided with ABC & CO ₂ type fire extinguishers		MR

The fire protection systems provided in the building/premises were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the Fire Safety Certificate issued vide letter No. F6/DFS/MS/Hospital/2017/SZ/121 dated 31/01/2017, renewal under rule 37 of Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (SJ)

DO (SD)

NEM

27/12

Ch | Hugh

28/12/2022

Director M 20/17/2022

Sir, FJ Wer is profer

Signature

101/2024

Renewal: