GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

Dated:- 6

03 01 2024

No. F6/DFS/MS/School/WZ/2024/ 06

FIRE SAFETY CERTIFICATE

Colony, Mundka, Delhi-110041, is running at ground + 02 Upper Floors of a building comprised of Ground + 03 Upper Floor only owned/occupied by M. R. Bharti Sr. Sec. School was issued Fire Safety Certificate by this department Vide Letter No. F6/DFS/MS/School/2020/WZ/423 Dated 13/10/2020 (Ground + 02 Upper Floors). The said premise was re-inspected by the officer concerned of this department on 12.12.2023 in the presence of Sh. Mukesh (Owner) and found that the premises / building have deemed complied with the fire prevention and fire safety requirements in accordance with D.O.E. Cr. No. 3298-3398 dated 01.03.2011 and that the premises/building is fit for occupancy class "Educational Building" Group B with effect from 03 01 2224 for a period of three years, subject to compliance of the conditions, printed below.

Issued on 63 .01. 2.24 at New Delhi by.

Director Zel. No. 011-23414000

Copy to: -

The Director, Directorate of Education, GNCT of Delhi, Old Secretariat Delhi – 110054.

 The Principal, M.R. Bharti Model Sr. Sec. School, Kh. No. 53/15, Friends Colony, Mundka, Delhi-110041.

Following fire safety directives must be adhered to:-

- The School Management has given an undertaking that school has built up the 3rd floor for various school activities. But the number of students has decrease due to CORONA phase and it is not in use any school activity. Hence 3rd floor has been sealed / blocked for further activity. If 3rd floor of school found in any use then FSC shall be null & void.
- 2. All the means of escape shall be kept free of all type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
- Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 7. All comments / directions of licensing Department shall always be permitted and followed.
- The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 9. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in

INSPECTION REPORT

1. Name and address of the building: M.R. Bharti Sr. Sec. School Located at Kh.

No. 53/15, Friends Colony, Mundka, Delhi-

110041

Type of Occupancy : Educational, Ground + 02 Upper Floors only

3. Type of Case : Renewal

4. Details of previous NOC : F6/DFS/MS/School/2020/WZ/423 Dated 13.10.2020

5. Fire Safety directives Letter No.: D.O.E. Cr. No. 3298-3398 dated 01-03-2011

6. Date of inspection : 12.12.2023

7. Name of the Inspecting Officer : Aman Kumar Lathar, ADO (JWP)

8. Name and designation of Officer

: Sh. Mukesh (Owner) from the building side

: 2007 9. Year of Construction

1	10. Applicant's letter No.	: email dated 25.11.2023				
S No	Minimum standards on fire prevention and fire safety U/R 33	D.O.E. Circular No. 3298-3398 Dated 01.03.2011/ as per FSC dated 13.10.2020		Provided at site	Remarks MR/NMR	
1.	Access of building		, n	11.1	MR	
	Road width	06 m		rovided	MR NA	
	 Gate width 	05 m		rovided		
	 Width of internal road 	NA		NA	NA	
2.	Number, width, Type & Arrangements of exits					
-	a. Number of staircases) (D	
	Upper floors	03		03	MR	
	Basements	NA	NA		NA	
	b. Width of staircases				1.40	
	Upper floors	1.5 m		50 m x 2 85 m x 1	MR	
	Basements	NA	NA		NA	
١	c. Protection of exits					
	Fire check door	NA		NA	NA	
	Pressurization	NA		NA	NA	
	d. No of continuous staircase to terrace	03		03	MR	
	muntal OCC amider	1.5 m	P	rovided	MR	
	f. Door Size	1 m	P	rovided	MR	
	_ AN _ MICHIGAN PARTIES			NA		
4.	Compartmentation	NA		NA	NA	
	Fire check door Sealing of electrical	NA		NA	NA	
	 shafts Fire Rating of shaft door 	NA		NA	NA	
	Water Curtain	NA NA		NA	NA	
	Water Curtain Fire Dampers	NA NA		NA	NA	
	Smoke managements System					
		NA		NA	NA	
	Basements Upper floors	NA		NA	NA	
	. Fire Extinguishers					
	Total numbers	20 nos.		26 nos.	MR	
	• Types • IS marking	ABC & CO ₂ ISI marked		Provided Provided	MR MR	

	First – Aid Hose Reels				
.	m 1 1 anal Coor	02	Provided	MR	
		30 m	Provided	MR	
	Length of hose reel hose Nozzle diameter	5 mm	Provided	MR	
	Automatic fire detection and alarming s	ystem		1 274	
-	Type of detectors	NA	NA	NA	
1	Location of Main Panel	NA	NA	NA	
	Location of Repeater Panel	NA	NA	NA	
	Alternate source of power	NA	NA	NA	
	Hooters' Location	NA	NA	NA	
_		NA	NA	NA	
	MOEFA Public Address System	NA	NA	NA	
	Automatic Sprinkler System				
0.	Basements	NA	NA	NA	
	Upper Floor	NA	NA	NA	
	Sprinkler above false ceiling	NA	NA	NA	
11.	Internal Hydrants:			N/D	
1.1.	Size of riser/down- comer	100 mm	Provided	MR MR	
	Number of hydrants per floor	02	Provided	MR	
	Hose Box	02	Provided	MIK	
12.	Yard Hydrants	- 340	NIA I	NA	
	Total number of hydrants	NA	NA NA	NA NA	
	Hose Box	NA	NA	1121	
13.	Pumping Arrangements:				
	Ground Level	NA	NA	NA	
	Discharge of main pump	NA NA	NA	NA	
	➤ Head of main pump	NA NA	NA	NA	
	> Number of main pumps	NA NA	NA	NA	
	> Jockey pump out put	NA	NA	NA	
	> Jockey pump head	NA	NA	NA	
	> Standby Pump out put > Standby Pump Head	NA	NA	NA	
	> Auto Staring/Manual	NA	NA	NA	
	stopping		NA	NA	
	> Pump House Access	NA	INA	417.5	
	Terrace level	450 lpm	Provided	MR	
	Discharge of pump	40 m	Provided	MR	
	 Head of the pump Power supply 	Required	Provided	MR	
	> Auto starting of pump	Required	Provided	MR	
20.2	Storage for fire fighting:				
14.	Under ground tank capacity	NA	NA	NA	
	> Under ground tank capacity > Draw off connection	NA	NA NA	NA NA	
	> Fire service inlet	NA	NA	NA NA	
	> Access to tank	NA	NA Provided	MR	
	Overhead Tank capacity	10,000 ltrs.	Provided	MR	
15	Exit Signage	Required	Flovided		
16.	Provision of Lifts	NA	NA	NA	
	> Pressurization of Lift Shaft	NA NA	NA	, NA	
	> Pressurization of lift lobby	NA NA	NA	NA	
	Communication in lift Car	NA	NA	NA NA	
	 Fireman's Grounding Switch Lift Signage 	NA	NA	NA	
		NA	NA	NA	
17.	Standby power supply	1873			
	Refuge Area	NA	NA	NA	
18.	> Total area	1373	NA	NA	

9.	Fire control room Detector system	NA	NA	NA
I	panel	NA	NA	NA
۱۱	 ➢ Flow Switch Panel ➢ PA System Panel ➢ Battery backup ➢ Building Floor Plans 	NA	NA	NA
Ш		NA	NA	NA
		NA	NA	NA
20.	Special Fire Protection Systems for Protection of special Risks, if any; Fire protection systems	NA	NA	NA

functional at the time of inspection.

Note:- The school management has given an undertaken against earlier shortcoming issued vide letter no. F6/DFS/MS/School/WZ/2023/50 dated 06/11/2023 by this department that the school has built up the 3rd floor for various school activities. But the number of students has decrease due to CORONA phase and it is not in use any school activity. Hence 3rd floor has been sealed / blocked for further activity. If 3rd floor of school found in any use then FSC shall be null & void.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety requirements as per D.O.E. Circular no. 3298-3398 dated 01.03.2011, vide letter issued Certificate Safety renewal of Fire F6/DFS/MS/School/2020/WZ/423 Dated 13.10.2020 is recommended.

Accordingly DFA is put up for approval please.

ADO (JWP)