

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELIII- 110001

ग्रिटी आजादी न अमृत महोत्सव

No. F6/DFS/MS/GH/SZ/2024/05

Dated: 03 01 2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Mayank Guest House located at 2A, Nangli Razapur East Nizamuddin, New Delhi-13, was granted Fire Safety Certificated (FSC) by this department vide letter no. F6/DFS/MS/GH/2021/SZ/17 dated 11.01.2021 for Ground + Two upper floors. The building/premises was re-inspected by Assistant Divisional Officer (M. Road) from this department on 01.01.2023 in presence of Mr. Bhupender Rajpoot (Manager) and found that the building now comprised of Ground + 04 upper floors: Ground floor- reception + 02 guest rooms, 1st floor - 02 guest rooms, 2nd floor- 02 guest rooms, 3rd floor - staff room, 4th floor/Terrace - 01 store room found closed. The building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. The owner has submitted an affidavit on 02.01.2024 not use any floor above third floor for any purpose in accordance with Gazette Notification dated 27.05.2019. Accordingly, the premises is fit for occupancy of "Residential Sub Division-A-1" for total 06 Guest rooms (Ground floor- reception + 02 guest rooms, 1st floor - 02 guest rooms, 2nd floor- 02 guest rooms) and valid upto 31.03.2027 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on 03 01 2024 at New Delhi by

Director
Delhi Fire Service

Reference: MHA Portal Online application no. 2023122019764 dated 20.12.2023.

Conditions for the validity of Fire Safety Certificate

1. This FSC is valid for Ground + Two upper floors only.

2. All the means of escape/entry/exit shall be kept free from any obstruction.

- All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

5. The trained fire fighting staff should be available round the clock.

- 6. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 7. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub Rule (I) of Rule 37] along with a copy of this Certificate, six month prior to its expiry. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

ı	Name	& -	ddress of the Latte		ON REPORT			
	Name & address of the building			M	Vs Mayank Gues	t House located	at 2A. Nane	
	Building is compain 1 6			K	M/s Mayank Guest House located at 2A, Nan Razapur East Nizamuddin, New Delhi-13.			
	Building is comprised of			G	round + 04 upper	r floors		
- 1				G	Ground floor- reception + 02 guest rooms 1 st floor - 02 guest rooms 2 nd floor- 02 guest rooms 3 rd floor - staff room			
- 1				1.				
- 1				2"				
				3"				
				4	4th floor/Terrace - 01 store room found closed			
3	Type of occupancy				Residential Group A-1			
4	Type of case			R	Renewal/addition of 1 store room at terrace floor			
5	Details of Previous FSC				F6/DFS/MS/GH/2021/SZ/17 dated 11.01.2021			
6	Fire Safety directive letter no.			_	Nil			
7	Date of inspection			0	01.01.2024			
8	Name of the inspecting officers			JOS.	Order Publish Districts	la ADO (M. Road	D	
9			the designation of officer	_	Rajesh Kumar Shukla ADO (M. Road) Mr. Bhupender Rajpoot (Manager) 2002 & 2018 MHA online application no. 2023122019764 date 20.12.2023			
			building side	- 1				
10			construction	20				
11	_		it's letter no.	977				
- বংলা			erromentation of the					
S.I	M	inin	um Standards on fire	100	equirement as	Provided at	Remarks	
0			ntion and fire safety		er Rule 35 (6)	Site	MR/NMR	
	re	qui	rements U/R 33	1150				
1	Access to building							
	A		Road width		Required	6.0 mtrs	MR	
	В	1	Gate width		NA	NA	NA	
	C	١,	Width of internal road		NA	NA	NA	
2	Number, Width, Type and Arrange				ent of Exits			
	A		Number of staircases					
		8	Upper floor		Required	2 nos.	MR	
	- 1	ī	Basement		NA	NA	NA	
	В		Width of staircases					
1	-	1	Upper floor		0.90 mtrs	1.03 mtrs	MR	
		1	Basement		NA	NA	NA	
	C	: 1	Protection of exits					
		\rightarrow	Fire check door		NA	NA	NA	
		-	Pressurization		NA	NA	NA	
	D	1	No. of continuous staircases	to	Required	01 no.	MR	
		t	егтасе					
	F	,	Width of corridor		NA	NA	NA	
	F		Door size		1.0 mtrs	1.0 mtrs (final exit)	MR	
3	Compartmentation					381	ll l	
3	A Fire check door			NA	NA	NA		
		Sealing of electrical shafts			NA	NA	NA	
	1				NA	NA	NA	
		550	Water curtain		NA	NA	NA	
		Fire dampers			NA	NA	NA	
4	The state of the s					1314	NA	
337		A	asement		NA	NA NA	NA	
1			Ipper floor		NA	NA	IVA	

	Fire Extinguisher A Total numbers			05 nos.	06 nos.	MR		
	1,01,70	AMERICAN		CO ₂ & ABC	CO ₂ & ABC	MR		
		Types		17/4		MR		
ě	C ISI marking			Required	ISI marked	IVIK		
6	Fir	st-Aid	l-Hose Reels			1		
31	A Total numbers of each floor			NA	01 no.	NA		
	В	Leng	th of hose reel hose	NA	30 mtrs.	NA		
	C Nozzle diameter			NA	5 mm	NA		
7	Automatic Fire Detection And Alarming System (required as per clause 7.31.v UBBL 2016).							
	A		oe of detectors	CO detectors	Provided	MR		
	В		cation of main panel	At ground floor	Provided	MR		
	C	Lo	cation of repeater panel	NA	NA	NA		
	D		ernate source of power	NA	NA	NA		
	E		oters	Audible in entire building	Provided	MR		
8	M	OEF	A	Required	Provided	MR		
9	Pu	blic A	Address System.	NA	NA	NA		
10	A	itoms	atic Sprinkler System.					
	A	Base	ement	NA	NA	NA		
	В	Upp	er floor	NA	NA	NA		
	C	(6.6)		NA	NA	NA		
11	Internal Hydrants							
.5.5	A		of riser/down-comer	NA	NA	NA		
	В	War word or	nber of hydrants per floor	NA	NA	NA		
	C	-	se box	NA	NA	NA		
12			lydrants.					
	A		al number of hydrants	NA	NA	NA		
	B		se box	NA	NA	NA		
13	1 250	550	ng Arrangements.					
13	A		ound Level			Tari		
	A	a	Discharge of main Pump	NA	NA	NA		
		ь	Head of Main Pump	NA	NA	NA		
		c	Number of main pumps	NA	NA	NA		
		d	Jockey pump out put	NA	NA	NA		
		e	Jockey pump head	NA	NA	NA		
		f	Standby pump out put	NA	NA	NA NA		
		g	Standby pump Head	NA NA	NA NA	NA NA		
1		h	Auto Starting /Manual	NA	INA	i		
			stopping scress	NA	NA	NA		
1	-	i	Pump house access			1		
	F		Discharge of pump	NA	450 LPM	NA		
		a	Head of the Pump	NA	40 mtrs.	NA		
		Ь	Power supply	NA	Provided	NA NA		
		d	Auto starting of pump Guest House located at 2A, Nangli	NA	Provided	INA		

N/16

M/s Mayank Guest House located at 2A, Nangli Razapur East Nizamuddin, New Delhi-13.

4	Captive Water Storage for Fire Fighting.							
	A Underground tank capacity	NA	NA	NA				
	B Draw-off connection	NA	NA	NA				
	C Fire service inlet	NA	NA	NA				
	D Access to tank	NA	NA	NA				
	E Overhead tank capacity	NA	5,000 ltrs	NA				
15	Exit Signage.	Required	Provided	MR				
16	Provision of Lifts.							
	A Pressurization of lift shaft	NA	NA	NA				
	B Pressurization of lift lobby	NA	NA	NA				
	C Communication in lift car	NA	NA	NA				
	D Firemen's grounding switch	NA	NA	NA				
	E Lift signage	NA	NA	NA				
17	Standby Power Supply	Required	Provided	MR				
18	Refuge Area.							
	A Total area	NA	NA	NA				
	B Location	NA	NA	NA				
19	Fire Control Room							
	A Detector system panel	NA	NA	NA				
	B Flow switch panel	NA	NA	NA				
	C PA system panel	NA	NA	NA				
	D Battery backup	NA	NA	NA				
	E Building floor plans	NA	NA	NA				
20	Special Fire Protection Systems For Protection Of Special Risks, If Any:	NA	NA	NA				

Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

Note:- There is mentioned of 3rd floor in the building at N/1. However the same has not been mentioned in inspection reports/FSC in subsequent notingr. The Guest house is running at Ground + Two uppers floors of the building which is comprised of Ground + 04 upper floors. However one store room at 4th /terrace floor was also seen in the building and same was found closed by the management. The owner has submitted an affidavit on 02.01.2024 not use any floor above third floor for any purpose in accordance with Gazette Notification dated 27.05.2019 placed at C-50 on file.

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

If agreed to the note above & in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/GH/2021/SZ/17 dated 11.01.2021 is recommended to be renewed under Rule 37 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (M. Road)

00 (50) My 04/1/24

Oirector May 24

Soyme

Masor

Majordes