GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/EH/NDZ/2024/ 08

Dated : 05./01-2024

FIRE SAFETY CERTIFICATE

Certified that the M/S KTG Hotel and Resort, Pvt. Ltd, located at C-11 mezzanine floor, Connaught Place, New Delhi in a building comprised of ground and mezzanine floor and restaurant running at mezzanine floor only was earlier granted FSC by this department vide letter No.F6/DFS/MS/EH/NDZ/2021/08 dated 06/01/21. Now, the premises was re-inspected by the officer concerned of this department on 29/12/23 in the presence of Manager and found that the said premises has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Assembly Building Group D for restaurant at mezzanine floor only and valid up to 31.03.2026 from the date of issue in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 05-01-2024 at New Delhi by.

Delhi Fire Service

Copy to:-

1. The Chief Architect, NDMC, Palika Kendra, New Delhi.

2. The Joint Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID No. 2020122209136 dated 19.12.23.

3. The Manager, M/s KTG hotel and resort Pvt. Ltd C-11 Mezzanine floor, Connaught Place, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. This FSC is valid for restaurant only.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned

5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any. 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi

Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency. 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

9. Any flammable material for interior decoration is strictly prohibited.

INSPECTION REPORT

1. Name & address of the

Building

M/S KTG Hotel & Resort Pvt. Ltd at C-11 Mezzanine floor, Connaught Place, New

Delhi, Gr.+ mez.

2. Type of occupancy:-

Assembly Building Group-D

Restaurant running at mezzanine floor only Renewal

3. Type of case:-

4. Details of previous FSC:-

No. F6/DFS/MS/EH/NDZ/2021/08 dated 06/01/21 N/A

5. Fire safety directives No.-6. Date of inspection:-

29/12/23

7. Name of the inspecting officer:-

Sh. Ravinder Singh (ADO/CC)

8. Name & designation of officer

from the building side:-

Manager

9. Year of construction:-

Old Heritage Bldg.

10. Applicant's letter No:-

Id no. 2020122209136 dated 19.12.23.

10. Applicant's letter No:-		Old case (renewal		
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building		00	MR
	1) Road width	06m	09 mtr.	MR
	2) Gate width	N/A	Directly accessible from main road	A PAOLIS SES
		N/A	N/A	N/A
	3)Width of internal road	engement of Ex	its	
2.	Number, Width Type & Arr	angement of Da	/	
	A. Number of staircases	02 Nos.	02 Nos.	MR
	1. Upper floors	N/A	N/A	N/A
	2. Basements	IVA		
3.	B. Width of staircase	1.25m & 1.0m	1.25m & 1.0 m	MR
	1. Upper floors(mez.)	N/A	N/A	N/A
	2. Basements	N/A	N/A	N/A
	C. Protection of exits		N/A	N/A
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	01	MR
	D. No. of continuous staircase to terrace	01	(李朝	N/A
	E. Width of corridor	N/A	N/A	
	F. Door size	2.0 m& 1.0 m	2.0 m& 1.0 m	MR
	Compartmentation	NT/A		
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
	Smoke Management System	Taria		
5.	1) Basements	N/A	N/A	N/A
	2) Upper floors	12 ACPH	Natural	MR
	Fire Extinguishers			

		N/24	10 Nos.	MR	
	1) Total numbers	ABC & CO2	ABC & CO2	MR	
	2) Types	Required	Provided	MR	
	3) ISI marking	Required	1000-00 C		
6.	First-Aid Hose Reel	01	01 /	MR	
-	1) Total number of each	UI.	177		
	floor	30 mtr.	30 mtr.	MR	
	2) Length of hose reel hose	05 mm	05 mm	MR	
	3) Nozzle diameter 05 mm 05 mm Automatic Fire Detection & Alarming System				
7.	Automatic Fire Detection &	Alarming Syst	N/A	N/A	
	1) Type of detectors	N/A	N/A	N/A	
	2) Location of main panel	N/A	N/A	N/A	
	3) Location of repeater panel	N/A	N/A	N/A	
	4) Alternate source of power	N/A	N/A	N/A	
	5) Hooter's Location	N/A	- William Control	MR	
8.	MOEFA	Required	Provided	N/A	
9.	Public Address System	N/A	N/A	IN/A	
10.	Automatic Sprinkler System		37/4	N/A	
10.	1) Basement	N/A	N/A	N/A	
	2) Upper floors	N/A	Provided		
	3) Sprinkler above false	N/A	Provided /	N/A	
	ceiling				
11.	Internal Hydrants	100mm	100mm	MR	
	1) Size of riser/down-comer	01	01	MR	
	2) Number of hydrants per	UI .	V.		
	floor	01	01	MR	
	3) Hose box	UI.			
12.	Yard Hydrants	N/A	N/A	N/A	
	1) Total number of hydrants	N/A	N/A	N/A	
12	2) Hose box	IVA			
13.	Pumping Arrangement				
	Ground level Discharge of main	N/A	N/A	N/A	
	pump	27/4	27/4	77/4	
	b) Head of main pump	N/A	N/A	IN/A	
	c) Number of main pump	N/A	N/A	N/A	
	d) Jockey pump out put	N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A	
	f) Stand by pump output	N/A	N/A	N/A	
	g) Stand by pump head	N/A	N/A	N/A	
	h) Auto starting/Manual	N/A	N/A	N/A	
	stopping		2,722		
	2) Terrace level				
	a) Discharge of pump	450 LPM	450 LPM	MR	
	b) Head of pump	30 mtr.	30 mtr.	MIR	
	c) Power supply	Required	Provided Provided	MR	
	d) Auto starting of pump	Required	Provided .	MR	
4.	Captive Water Storage for Fir	71.1.1		TATE	

· e

		, , ,		
ař.	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	Required	Provided	MR
	d) Over head tank capacity		20,000 ltr. /	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	•		
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System Risk, if any:	N/A		

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved, we may renew the FSC issued vide letter no. F6/DFS/MS/EH/NDZ/2021/08 dated 06/01/21, under rule 35(6) of the Delhi Fire Service rules 2010. Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name :- Ravinder Singh

Designation :- ADO (CC)