## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELIII- 110001



No.F6/DFS/MS/School/NDZ/2024/ 18

Dated: | 0 / 0 | /2024

## **FIRE SAFETY CERTIFICATE**

Certified that the Greenway International School located at A- Block, Vivek Vihar, Delhi110095, comprised of basement plus ground plus one upper floor, owned/occupied by
Greenway International School was issued Fire Safety Certificate vide letter No.
F6/DFS/MS/School/2020/NDZ/559 dated 17/12/2020. The School building was re-inspected by the
officer concerned of this department on 03/01/2024 in presence of Mrs. Shruti (Principal) and
observed that all the fire prevention and fire safety arrangements provided in the premises found in
good working condition. The premises have therefore deemed complied with the Fire Prevention and
Fire Safety requirements in accordance with Circular No. F16/Estate/CC/Fire Safety/2011/3298 to
3398 dated 01.03.2011 issued by Director of Education and that the building is fit for occupancy
class "Educational" (Group-B) with effect from 10 / 0 / 2024 for a period of three years in
accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to
compliance of the conditions under rule 38 of the DFS rule 2010. Subject to conditions printed
below.

Issued on 10 01 2024 at New Delhi by.

DIRECTOR DELHI FIRE SERVICE

## Copy to:-

- The Director of Education, MCD Udyog Sadan, Plot no. 419, FIE, Patparganj Industrial Area, , Delhi-110092.
- 2. The Principal, Greenway International School, A-Block, Vivek Vihar, Delhi-110095.

## Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

			1	NSPE	CTION REPORT				
1	Name & address of the building Greenway International School located at					at A			
2	Building is comprised as			Block, Vivek Vihar, Delhi-110095.					
3	Building is comprised of		Basement, ground plus first floor.						
4	Type of occupancy			Educational Buil	lding				
5	Type of case			Renewal					
	Details of previous FSC			F6/DFS/MS/School/2020/NDZ/559 dated 17/12/2020.					
6	Fire safety directives letter no.			F16/Estate/CC/Fire Safety/2011/3298-3398 dated 01.03.2011.					
7	Date of inspection			03.01.2024.					
8	Name of the inspecting officers				Meena ADO (L.N)				
9	Name of the designation of officer from the building side			Mrs. Shruti (Principal)					
10	Ye	ar of construction 2002				3			
11	Applicant's letter no. Outdoor dairy no.11320 dated 28/				o.11320 dated 28/12	2/2023			
S.N	_		num standard of	fire	01.03.2011	Provided at	Re	Remarks	
0	ALTERNATION AND ADDRESS OF		ntion and fire safety		Circular requirement	site	MR	/NMR	
1	Access to Building:								
T.	A Road width				6.0 mtrs.	6.0 mtrs. MR		MR	
	B Gate width				N/A	N/A	N/A N/A		
	C Width of internal road				N/A	N/A N/A		N/A	
2	Number, Width, Type and Arrangement of Exits:								
_=:	A Number of staircases								
		-	Upper floor		01 no.	02 nos.	•	MR	
	-	С	Basement		02 no.	02 nos.		MR	
	В	10.40	lidth of staircases						
	Б	a	Upper floor		1.50 mtrs 1.45 mtrs,&		).80mtrs MR		
		ь	Basement	1.25 r	ntrs & 0.75 mtrs	1.30 mtrs & 0.93	mtrs	MR	
	C		rotection of exits	11.00					
	_	-	Fire check door		N/A	N/A		N/A	
		10000	Pressurization		N/A	N/A		N/A	
	D	N	lo. of continuous aircases to terrace		01 no.	01 no.		MR	
	E	V	Vidth of corridor		1.50 mtrs.	1.50 mtrs.		MR	
	F Door size		1.0 mtrs.	1.0 mtrs.		MR			
3	Compartmentation:				CITI-				
	A Fire check door			NA		NA NA			
	B Sealing of electrical shafts		N/A			N/A			
	C Fire rating of shaft door		N/A			N/A			
	D Water curtain				N/A	N/A N/A N/A N/A			
	E Fire dampers			NASSY.	N/A N/A N/		IN/A		
4	_	_	e Management Syste	m:	I 20 / 1	D 21.1		MD	
	A Basement				30 a/c per hour		-	MR N/A	
	B Upper floor		N/A N/A		1	IN/A			

5.	Fire Extinguisher:							
	A	Total numbers	08 nos.	08 nos.	MR			
	B	Types	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	MR			
	C	ISI marking	ISI Marked	Provided	MR			
6	Fin	First-Aid-Hose Reel:						
	A	Total numbers of each floor	01 no.	Provided	MR			
	В	Length of hose reel hose	30 m	Provided	MR			
	C	Nozzle diameter	05 mm	Provided	MR			
7	_	Automatic Fire Detection and Alarming System:						
	A	Type of detectors	N/A	N/A	N/A			
	B	Location of main panel	N/A	N/A	N/A			
	C	Location of repeater panel	N/A	N/A	N/A			
	D	Alternate source of power	N/A	N/A	N/A			
	E	Hooters	N/A	N/A	N/A			
8	-	OEFA:	N/A	N/A	N/A			
9	-		N/A	Provided	MR			
		Tubic Address System.						
10	Au	tomatic Sprinkler System:  Basement	Required	Provided	MR			
			N/A	N/A	N/A			
	B	Upper floor		N/A	N/A			
	C	Sprinkler above false ceiling	N/A	IN/A	IN/A			
11	Internal Hydrants:		27/4	NT/A	N/A			
	A	Size of riser/down-comer	N/A N/A	N/A N/A	N/A			
	B	Number of hydrants per floor		N/A	N/A			
	C	Hose box	N/A	N/A	IV/A			
12		Yard Hydrants:						
		Total number of hydrants	N/A	N/A	N/A			
202	В	Hose box	N/A	N/A	N/A			
13	Pumping Arrangements:							
1	Ground level							
	A	Discharge of main pump	N/A	N/A	N/A			
	В	Head of main pump	N/A	N/A	N/A			
Į	C	Number of main pumps	N/A	N/A	N/A			
	D	Jockey pump out put	N/A	N/A	N/A			
	E	Jockey pump head	N/A	N/A	N/A			
	F	Standby pump out put	N/A	N/A	N/A			
	G	Standby pump head	N/A	N/A	N/A			
	H	Auto starting /manual	N/A	N/A	N/A			
		stopping			2000 CS			
2	I	Pump house access	N/A	N/A	N/A			
	Terrace Level							
-	A	Discharge of pump	450 LPM	Provided	MR			
H	B C	Head of the pump	40 m	Provided	MR			
ŀ	_	Power supply	Required	Provided	MR			
	D	Auto starting of pump	Required	Provided	MR			

Greenway International School located at A- Block, Vivek Vihar, Delhi.

4	Captive Water Storage for Fire Fighting:							
	A	Underground tank capacity	N/A	N/A	N/A			
Ì	В	Draw-off connection	N/A	N/A	N/A			
ŀ	C	Fire service inlet	N/A	N/A	N/A			
ł	D	Access to tank	N/A	N/A	N/A			
ł	E	12.00 pt 10.00 pt 10.	10,000 Ltr	10,000 Ltr	MR			
15		Overhead tank capacity	Required	Provided	MR			
-	Exit Signage: Required Treview							
16	Provision of Lifts:		I N/A	N/A	N/A			
	A	Pressurization of lift shaft	N/A	N/A	N/A			
	В	Pressurization of lift lobby	N/A	N/A	N/A			
T)	C	Communication in lift car	N/A	N/A	N/A			
	D	Firemen's grounding switch	N/A	N/A	N/A			
	E	Lift signage	N/A	N/A	N/A			
17	Sta	ndby Power Supply:	IN/A					
18	Re	fuge Area:		N/A	N/A			
	A	Total area	N/A	N/A	N/A			
	В		N/A	IVA				
19		e Control Room:		N/A	N/A			
-	A	Detector system panel	N/A	N/A N/A	N/A			
	B	Flow switch panel	N/A	N/A	N/A			
	C		N/A	N/A	N/A			
	D	The state of the s	N/A	N/A N/A	N/A			
	F	Building floor plans	N/A	N/A N/A	N/A			
20	Sp	ecial Fire Protection systems for otection of special Risks, if any:	N/A	IN/A	15//			

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education Circular no F16/Estate/CC/Fire Safety/2011/3298-3398 dated 01.03.2011, the FSC issued vide letter no. F6/DFS/MS/School/2020/NDZ/559 dated 17/12/2020 is recommended to be renewed.

> Signature of the Inspecting Officer Name: - Yashwant Singh Meena

Designation:- ADO (L.N)