

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS: DELHI FIRE SERVICE, NEW DELHI: 110001**

No. F6/DFS/MS/EH/MN/2024/ 12

Dated: 09/01/2024

**FIRE SAFETY CERTIFICATE**

Certified that the M/s. Nandos (A unit of Nandos Karnataka Restaurant Pvt. Ltd. Shop No. SH/2F/12, Second Floor, Pacific Mall, Khayla, New Delhi 110027 is running at 2<sup>nd</sup> floor in a Pacific Mall in a building comprised of Two Basements, Ground & four upper floors plus Projection room was issued FSC vide Letter No. F.6/DFS/MS/WZ/Mall/2023/349 dated 21/07/2023. The premises was inspected by the officer concerned of this department on 02/01/2024 in the presence of Sh. Amit Bhayana (Director Operation) and found that the said building have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the premises is fit for occupancy class "Assembly" Group D with effect from 09/01/2024 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010. Condition mentioned below.

Issued on ..09/01/2024.. at New Delhi by.

  
(Atul Garg)  
Director

**Copy to:**

1. The Owner/occupier Nandos (A unit of Nandos Karnataka Restaurant Pvt. Ltd. Shop No. SH/2F/12, Second Floor, Pacific Mall, Khayla, New Delhi 110027.
2. The Joint Commissioner of Police, Licensing Unit, 1<sup>st</sup> floor, Police Station, Defence Colony, New Delhi. ([adlcp.lic-dl@nic.in](mailto:adlcp.lic-dl@nic.in))
3. The Dy. Health Officer, SDMC, West Zone, Vishal Enclave, Rajouri Garden, New Delhi 110027. ([dhowest\\_zone@gmail.com](mailto:dhowest_zone@gmail.com))

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
6. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.



## INSPECTION REPORT

1. Name & address of the building	M/s. Nandos (A unit of Nandos Karnataka Restaurant Pvt. Ltd. Shop No. SH/2F/12, Second Floor, Pacific Mall, Khayla, New Delhi 110027.
2. Type of Occupancy	Eating House /Assembly Occupancy
3. Type of Case	New
4. Details of previous NOC	Nil
5. Fire Safety directives letter No	Nil
6. Date of inspection	02/01/2024
7. Name of the Inspecting Officers	Sarabjeet Singh (ADO MN)
8. Name and designation of officers from the building side	Sh. Amit Bhayana (Director Operation)
9. Year of Construction	2011 (As per MHA Portal)
10. Applicant's letter No.	Online ID 2023122019754 dated 26/12/2023

The said restaurant is running at second floor in Pacific Mall in a building comprised of two basement, ground & four upper floors & projection room was issued FSC vide letter no. F.6/DFS/MS/WZ/Mall/2023/349 dated 21/07/2023.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	BBL /NBC Requirement	Provided at site	Remarks MR/NMR
1	<b>Access to building</b>			
	• Road width	12 mtrs	Provided	MR
	• Gate width	5 mtr	Provided	MR
	• Width of internal road	6 mts	Provided	MR
2	<b>Number, Width, Type &amp; Arrangement of Exits common with the mall</b>			
	a. Number of staircases			
	• Upper Floors	2	Provided by mall	MR
	• Basements	NA	NA	NA
	b. Width of staircases			
	• Upper Floors	1.5 mtr	Provided by mall	MR
	• Basements	NA	NA	NA
	c. Protection of exits			
	• Fire check door	NA	NA	NA
	• Pressurization	NA	NA	NA
	e. No. of continuous staircases to terrace	NA	NA	NA
	f. Width of Corridor	Required	Provided	MR
	g. Door Size	1.5 m X 2	Provided	MR
3	<b>Compartmentation.</b>			
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4	<b>Smoke Management System.</b>			
	• Basements	NA	NA	NA
	• Upper floors	Required	Provided	MR
5	<b>Fire Extinguishers</b>			
	• Total numbers	02 Nos.	Provided	MR
	• Types	CO <sub>2</sub> , ABC type	Provided	MR
	• IS marking	ISI marked	Provided	MR



Common with the mall				
6	<b>First-Aid Hose Reels.</b>	01	Provided	MR
	• Total numbers on each floor	30m	Provided	MR
	• Length of hose reel hose	5mm	Provided	MR
	• Nozzle diameter			
7	<b>Automatic fire detection and alarming system.</b>	Smoke	Provided	MR
	• Type of detectors	Required	Provided	MR
	• Location of Main Panel	NA	NA	NA
	• Location of Repeater Panel	Required	Provided	MR
	• Alternate source of power	Required	Provided	MR
	• Hooters' Location	Required	Provided	MR
8	<b>MOEFA</b>	NA	NA	NA
9	<b>Public Address System.</b>			
10	<b>Automatic Sprinkler System.</b>			
	• Basement	NA	Provided	NA
	• Upper Floor	Required	Provided	MR
	• Sprinkler above false ceiling	NA	NA	NA
11	<b>Internal Hydrants</b>	Common with the mall		
	• Size of riser/down-comer	150 mm	Provided	MR
	• Number of hydrants per floor	Required	Provided	MR
	• Hose Box	Required	Provided	MR
12	<b>Yard Hydrants.</b>			
	• Total number of hydrants	NA	NA	NA
	• Hose Box	NA	NA	NA
13	<b>Pumping Arrangements.</b>	Common with the mall		
	• Ground Level			
	➤ Discharge of main Pump	NA	Common with the mall	NA
	➤ Head of Main pump	NA	Common with the mall	NA
	➤ Number of main pumps	NA	Common with the mall	NA
	➤ Jockey Pump out put	NA	Common with the mall	NA
	➤ Jockey pump head	NA	Common with the mall	NA
	➤ Standby Pump out put	NA	Common with the mall	NA
	➤ Standby Pump Head	NA	Common with the mall	NA
	➤ Auto Starting/ Manual stopping	NA	Common with the mall	NA
	➤ Pump House Access	NA	Common with the mall	NA
	• Terrace level			
	➤ Discharge of pump	900 lpm	Common with the mall	MR
	➤ Head of the pump	40 m	Common with the mall	MR
	➤ Power Supply	Required	Common with the mall	MR
	➤ Auto Starting of pump	Required	Common with the mall	MR
14	<b>Captive Water Storage for fire fighting.</b>	Common with the mall		
	• Underground tank capacity	NA	2,00,000 litres	NA
	➤ Draw-off connection	NA	Provided	NA
	➤ Fire service inlet	Required	Provided	MR
	➤ Access to tank	NA	Provided	NA
	• Overhead Tank capacity	20,000 litres	30, 000 Litres	MR
15	<b>Exit Signage.</b>	Required	Provided	MR

16 Provision of Lifts.				
	• Pressurization of Lift Shaft	NA	NA	NA
	• Pressurization of Lift lobby	NA	NA	NA
	• Communication In lift Car	NA	NA	NA
	• Fireman's Grounding Switch	NA	NA	NA
	• Lift Signage	NA	NA	NA
17	Standby power supply	Required	Provided	MR
18 Refuge Area.				
	➤ Total Area	NA	NA	NA
	➤ Location	NA	NA	NA
19 Fire Control Room				
	• Detector System Panel	NA	NA	NA
	• Flow Switch Panel	NA	NA	NA
	• PA System Panel	NA	NA	NA
	• Batter backup	NA	NA	NA
	• Building Floor Plans	NA	NA	NA
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	Provided in Kitchen Hood	NA

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

1 ADO/MN  
03/01/24

*[Signature]*  
03/01/2024  
Signature of the Inspecting Officer  
Name: Sarabjeet Singh  
Designation: ADO (MN)

*[Signature]*  
DFO (MN)  
*[Signature]*

~~CFO - leave  
Director  
8/1/24~~

FT PS

*[Signature]*  
AD/MN

Sir, F.T is put up for your kind personal & sig. pls  
*[Signature]*  
Director  
*[Signature]*