## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110001

No.F6/DFS/MS/School/2024/SZ/20

Dated: 11/01/224

## FIRE SAFETY CERTIFICATE

Certified that the Nav Jeewan Academy, C-Block, Jeewan Park, Pankha Road, New Delhi-110059, comprised of ground plus three upper floors(half portion fourth floor sealed), owned/occupied by Nav Jeewan Academy have complied with the fire prevention and fire safety requirements in accordance with the Rules 33 of the Delhi Fire Service Rules 2010 and verified by the officer concerned of this department on 27/12/2023 in the presence of Sh. R.K. Sharma (Manager) and found that the school building is fit for occupancy class B 'Educational Building' for with effect from .1.1 224 for a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under

Director

Delhi Fire Service

%p.

Copy to:-

 The Principal, Nav Jeewan Academy, C-Block, Jeewan Park, Pankha Road, New Delhi-110059.

2. The Director of Education, Govt of NCT of Delhi, Old Secretariat, New Delhi-54.

## Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- The trained staff should be available round the clock.
- Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director
  in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months
  prior to its expiry.

1. Name & address of the building

: Nav Jeewan Academy, C-Block, Jeewan Park, Pankha

Road, New Delhi-110059.

2. Building is comprised of 3. Type of Occupancy

:  $G+3 & 4^{th}$  floor half portion constructed which is sealed).

4. Type of Case

: Educational

5. Details of Previous FSC letter

: New Case

6. Fire Safety direction letter No

: Nil

7. Date of Inspection

: NBC Part-IV

: 27/12/2023

8. Name of the Inspecting officers 9. Name and designation of Officer:

: ADO R.K. Yadav

From the building side

10. Year of Construction

: Sh. R.K.Sharma (Manager) : 2003

11. Applicant's letter No.

: Nil dated 11/12/2023

N 1	Minimum Standards on fire prevention and fire safety U/R33	Requirement	Provided at Site	Remarks MR/NMR				
	Access to building							
	Road width     Gate width	06 m.	Provided	MR				
	Width of internal road	N/A	N/A	N/A				
2		N/A	N/A	N/A				
	Number, Width, Type and Arrangement of Exits							
	a. Number of Staircases							
	Upper Floor	02 Nos.	02 Nos.	MR				
	Basement	N/A	N/A	N/A				
	B. Width of Staircases							
	Upper Floor	1.50 m each	1.80 m each	MR				
	Basement	N/A	N/A	N/A				
	c. Protection of exits							
	Fire check door	N/A	N/A	N/A				
	Pressurization	N/A	N/A	N/A				
	d. No. of continuous staircases	02 No.	02 No.	MR				
	to terrace e. Width of Corridor f. Door Size	1.5 m.	1.50 m.	MR				
		1.20 m	1.20 m	MR				
3	Compartmentation.							
	Fire check door	N/A	N/A	N/A				
	Sealing of electrical shafts	N/A	N/A	N/A				
	Fire rating of shaft door	N/A	N/A	N/A				
	Water curtain	N/A	N/A	N/A				
	Fire Dampers	N/A	N/A	N/A				
4	Smoke Management System.							
	Basement	N/A	N/A	N/A				
	Upper floor	Required	Natural Ventilation	MR				
5.	Fire Extinguishers							
	Total numbers	12 nos.	Provided	MR				
	• Types	ABC /CO <sub>2</sub>	ABC /CO <sub>2</sub>	MR				
	IS marking	IS I marked	ISI marked	MR				
	• 15 marking	15 I marked	151 Illai KCu	IVIK				

6	First-aid-Hose Reels.							
	Total numbers of each floor	01 Nos.	Provided	MR				
	Length of hose reel hose	30 m	Provided	MR				
	Nozzle diameter	05mm Provided		MR				
7	Automatic fire detection and alarming system.							
	Type of detectors	N/A	N/A	N/A				
	<ul> <li>Location of main panel</li> </ul>	N/A	N/A	N/A				
	<ul> <li>Location of repeater panel</li> </ul>	N/A	N/A	N/A				
	Alternate source of power	N/A	N/A	N/A N/A				
	Hooter's location	N/A	N/A					
9	MOEFA	N/A	N/A	N/A				
POINT.	Public address System.	N/A	N/A	N/A				
10	Automatic Sprinkler System.							
	Basement	N/A	N/A	N/A				
	upper floor	N/A	N/A	N/A				
	sprinkler above false ceiling	N/A	N/A	N/A				
11	Internal Hydrants							
	size of riser/down-comer	N/A	Provided	MR				
	Number of hydrants per	N/A	Provided					
	floor		Tiovided	MR				
	Hose Box	N/A	Provided	MD				
12	Yard Hydrants.							
	Total number of hydrants	N/A	N/A	31/4				
	Hose Box	N/A	N/A N/A	N/A				
13	Pumping Arrangements.	INEX	N/A	N/A				
	Ground Level							
	> Discharge of main	N/A	3774					
	Pump	IN/A	N/A	N/A				
	Head of Main Pump	N/A	N/A	N/A				
	Number of main pumps	N/A	N/A	N/A				
	Jockey pump out put	N/A	N/A	N/A				
	Jockey pump head	N/A	N/A	N/A				
	Standby pump out put	N/A	N/A					
	Standby pump Head	N/A	N/A	N/A				
	➤ Auto Starting /Manual	N/A	N/A	N/A				
	stopping		IN/A	N/A				
	➢ Pump House Access	N/A	N/A	N// 4				
	Terrace Level	IVA	N/A	N/A				
	Discharge of pump	900 LPM	000 I D) (	1.75				
	➤ Head of the Pump	40 M	900 LPM	MR				
	> Power supply		Provided	MR				
	➤ Auto Starting of pump	Required	Provided	MR				
14	Canting Water St.	Required	Provided	MR				
-	Captive Water Storage for Fire Fighting.							
	<ul> <li>Underground tank capacity</li> </ul>	N/A	N/A	N/A				
	> Draw-off connection	N/A	N1/A					
	> Fire service inlet		N/A	N/A				
	> Access to tank	N/A	N/A	N/A				
	And the second s	N/A	N/A	N/A				
	Overhead Tank capacity	10,000 Ltr.	10,000 Ltrs	MR				
15	Exit Signage.	Required	Provided	MR				





6	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication in lift car	N/A	N/A	N/A		
	Firemen's grounding switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
17	Standby power supply	N/A	N/A	N/A		
18	Refuge Area.					
	Total area	N/A	N/A	N/A		
	• Location	N/A	N/A	N/A		
19	Fire Control Room					
.,	Detector system panel	N/A	N/A	N/A		
_	Flow switch panel	N/A	N/A	N/A		
_	The state of the s	N/A	N/A	N/A		
	PA system panel	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building Floor Plans		N/A	N/A		
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	IV/A			

The fire protection systems provided in the building were tested/checked at the time of inspection.

inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety as required under the Rule 35 of the Delhi Fire Service Rules 2010 it is recommended to grant Fire Safety Certificate.

Signature of the Inspecting Officer Name- R.K. Yadav

Designation- A.D.O(JKP)

Dorseta My 2 A

ET Letter to put up for sognation

DIRECTOR / 1/1/21