

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE **NEW DELHI- 110001**

No.F.6/DFS/MS/College/SZ/2024/01

Dated: 19 01 22

FIRE SAFETY CERTIFICATE

Certified that the Delhi Teachers Training College, 340, Deenpur, Bus Stop, Najafgarh, New Delhi-110043, comprised of ground floor plus three upper floors was issued a FSC by this department vide letter No. F.6/DFS/MS/College/2020/SZ/279 dated 28.07.2020. The building was re-inspected by the officer concerned of this department on 09.01.2024 in the presence of Sh. S.K. Mishra (Principal) and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 19 01 2024 at New Delhi.

Delhi Fire Service

Copy to:-

- 1. The Principal, Delhi Teachers Training College, 340, Deenpur Bus Stand Najafgarh, New Delhi- 110043.
- 2. The Director, G.G.S Indraprastha University, Sector- 16, Dwarka, New Delhi

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the Fire Service Rules 2010, form is available on of Delhi first schedule www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry

N2

INSPECTION REPORT

1. Name & address of the building : Delhi Teachers Training College, 340, Deenpur, Bus Stop, Najafgarh,

New Delhi-110043

2. Building comprised of : Ground floor plus three upper floors.

3. Type of Occupancy : Educational 4. Type of Case : Renewal

5. Details of Previous NOC : F.6/DFS/MS/College/2020/SZ/279 dated 28.07.2020

6. Fire Safety directives letter No : N/A
7. Date of inspection : 09.01.2024

8. Name of Inspecting Officer : A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side : Sh. S.K. Mishra(Principal)

10. Year of Construction : Before 2015

11. Applicant's letter No. : DTTC-1687(ii)/2023 dated 21.12.2023

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR			
1.	Access to building						
	Road width Gate width Width of internal road	Accessible 06 m 4.5 m N/A	Provided Provided N/A	MR MR N/A			
2.	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases Upper Floors	02 No.'s	02 No.	MR			
	Basements Width of staircases	N/A	N/A	N/A			
	Upper Floor Basements	1.50 m& 1.0 m	1.50& 1.20 m	MR			
	c. Protection of exits • Fire check door	N/A	N/A	N/A			
	Pressurization	N/A	N/A	N/A N/A			
	d. No. of continuous staircases to	N/A	N/A				
	terrace	Required	Provided	MR			
	e. Width of Corridor	1.50 m	Provided	MR			
	f. Door Size	1.0 m	1.0/1.30 m	MR			
3.	Compartmentation	21/4	N/A	N/A			
	Fire check door	N/A	N/A	N/A			
	 Sealing of electrical shafts Fire Rating of shaft door 	N/A		N/A			
	Water Curtain	N/A	N/A				
	Fire Dampers	N/A	N/A N/A	N/A N/A			
4.	Smoke Management System	N/A	IN/A	N/A			
4.	CAN CONTRACTOR OF THE CONTRACT	N/A	N/A	N/A			
	Basements	Required	Natural ventilation	M/R			
	Upper floors	Required	provided	(Note that the same to be same to			
5.	Fire Extinguishers						
	Total numbers	08 no's	Provided	MR			
	• Types	ABC/CO ₂ type	Provided	MR			
	IS marking	ISI marked	Provided	MR			

		Ω			
6.	First-Aid Hose Reels		4.00		
	mad la seah Goor	One	Provided	10	
	Total numbers on each floor	30 mtrs	Provided		
	 Length of hose reel hose Nozzle diameter 	5 mm	Provided	MR	
7	Automatic fire detection and alarming system	m	T 27/4	I N/A	
7.		N/A	N/A	N/A	
	Type of detectors Location of Main Panel	N/A	N/A	1,1	
	Location of Repeater Panel	N/A	N/A	N/A	
	Alternate source of power	N/A	N/A	N/A	
	Hooters' Location	N/A	N/A	N/A	
	year minether a present of the system traces and	N/A	N/A	N/A	
8.	MOEFA System	N/A	N/A	N/A	
9.	Public Address System Automatic Sprinkler System			N/A	
10.	Basement	N/A	N/A	N/A	
	Ground Floor	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A	
11.	Internal Hydrants			N1/A	
11,	Size of riser/down-comer	N/A	N/A	N/A	
	Number of hydrants per floor	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
12.	Yard Hydrants			200	
	Total number of hydrants	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
13.	Pumping Arrangements				
	Ground Level			21/4	
	 Discharge of main Pump 	N/A	N/A	N/A	
	➤ Head of Main pump	N/A	N/A	N/A	
	> Number of main pumps	N/A	N/A	N/A	
	Jockey Pump out putJockey pump head	N/A	N/A	N/A	
	Standby Pump out put	N/A	N/A	N/A	
	Standby Pump Head	N/A	N/A	N/A	
	➤ Auto Starting/Manual Stopping	N/A	N/A	N/A	
		0.51.1078	N/A	N/A	
		N/A N/A	N/A	N/A	
	Pump House Access	IVA			
	Terrace level	450 LPM	Provided	MR	
	Discharge of pump	450 LPM	Provided	MR	
	Head of the pumpPower Supply	Required	Provided	MR	
	➤ Auto Starting of pump	Required	Provided	MR	
				-	
14.	Captive Water Storage for fire fighting	N/A	N/A	N/A	
	 Underground tank capacity Draw-off connection 	N/A N/A	N/A	N/A	
	> Fire service inlet			N/A	
	> Access to tank	N/A	N/A N/A	N/A N/A	
	Overhead Tank capacity	N/A	STATE OF		
	•	10,000 ltrs	Provided	MR MR	
15.	Exit Signage.	Required	Provided	MK	
16.	Provision of Lifts. No Lift				
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	
	Communication In lift Car	N/A	N/A	N/A	
	 Fireman's Grounding Switch 	N/A	N/A	N/A	
	a LiA Cianaca	PERSONAL PROPERTY OF THE PERSON OF THE PERSO			
	Lift Signage	N/A	N/A	N/A	

	Total Area	N/A	N/A	N/A
X	Location	N/A	N/A	N/A
Fire	Control Room			N/A
_	Detector System Panel	N/A	N/A	
1	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Battery backup Building Floor Plans	N/A	N/A	N/A
		N/A	N/A	N/A
1				

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no F.6/DFS/MS/College/2020/SZ/279 dated 28.07.2020, renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Offi

Name:-R.K.Yadav

Designation:-Asstt. Divisional Officer

Divisional Officer (South West)

16 of Front

Director

Acuf XI

FT Letter to part up for rogni please

Picer

18 [1] 2004