

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE

NEW DELHI- 110001

No.F6/DFS/MS/School/2024/SZ/ 47

Dated: 19 01 2024

FIRE SAFETY CERTIFICATE

Certified that the Jyoti Public School, G-2/69,70 & 71, Sai Enclave, Mohan garden, New Delhi-110059, comprised of ground plus two upper floors, owned/occupied by Jyoti Public School have complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules 2010 and verified by the officer concerned of this department on 05/01/2024 in the presence of Sh. Ravi Kumar (Manager) of the school and that the school building is fit for occupancy class B 'Educational Building' for with effect from 1.9.01. 2.224 for a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on. 19/01/2024 at New Delhi by

Director Delhi Fire Service

Copy to:-

 The Principal, Jyoti Public School, G-2/69,70 & 71, Sai Enclave, Mohan garden, New Delhi-110059.

Director of Education, GNCT of NCT of Delhi, Old Secretariat, Delhi.

Following fire safety directives must be adhered to:-

1. All the means of escape shall be kept free of all type of obstruction all the time.

 All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.

 All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

 Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.

 This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

Jyoti Public School, G-2/69,70 & 71, Sai Enclave, Mohan garden, New 1. Name & address of the building :

Delhi-110059.

1. Building comprised of G+2 upper floors 3. Type of Occupancy Educational

4. Type of Case New 5. Details of Previous NOC Nil 6. Fire Safety directives letter No Nil

05/01/2024 5 A.D.O. R.K.Yadav 7. Date of inspection 8. Name of Inspecting Officer

9. Name and designation of officers

: Sh. Ravi Kumar (Manager) From the building side

11. No.	Applicant's letter No. : Nil dated 21/12/ Minimum Standards on fire prevention and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR				
	Access to building							
1:	Road width Gate width Width of internal road	06 m N/A N/A	4.5 m N/A N/A	MR old accepted N/A N/A				
		ite						
2.	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases		03 no.'s	MR				
	Upper Floors	02 no.	N/A	N/A				
	Basements	N/A	N/A					
	b. Width of staircases Upper Floor	1.5 m &.75 m	1.50 m, 1.20 & 1.0 m	MR				
	Basements	N/A	N/A	N/A				
	c. Protection of exits	1077						
	Fire check door	N/A	N/A	N/A				
	Pressurization	N/A	N/A	N/A				
	d. No. of continuous staircases to	01 no.	01 no.'s	MR				
	terrace	1.5 M	1.5 M	MR				
	e. Width of Corridor f. Door Size	1.0 m	.90/ 1.0 m	MR				
3.	Compartmentation							
3.		N/A	N/A	N/A				
	Fire check door	N/A	N/A	N/A				
	 Sealing of electrical shafts Fire Rating of shaft door 	N/A	N/A	N/A				
	Water Curtain	N/A	N/A	N/A				
	Fire Dampers	N/A	N/A	N/A				
		13/24						
4.	Smoke Management System	N/A	N/A	N/A				
	Basements	1,073	300.003	2.50				
	Upper floors	Required	Natural Ventilation	MR				
5.	Fire Extinguishers							
		04 No's	Provided	MF				
	Total numbers Types	ABC/CO ₂	Provided	Mi				

	First-Aid Hose Reels	1 No.	Provided	MR
-+	Total numbers on each floor	30 m	Provided	MR
	 Length of hose reel hose Nozzle diameter 	05 mm	Provided	MR
	Automatic fire detection and alarming system		NI/A T	N/A
	Automatic fire detection and annual	********	N/A	N/A
	Type of detectors Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A N/A	N/A	
	Hooters' Location	N/A	N/A	N/A
	VII	N/A	N/A	N/A
.	MOEFA	N/A	N/A	N/A
	Public Address System			
10.	Automatic Sprinkler System	N/A	N/A	N/A
	Basement	N/A	N/A	N/A
	 Ground Floor Sprinkler above false ceiling 	N/A	N/A	N/A
		/ \$ /W.5		
11.	Internal Hydrants	N/A	N/A	N/A
	Size of riser/down-comer Chadrents per floor	N/A	N/A	N/A
	 Number of hydrants per floor Hose Box 	N/A	N/A	N/A
		1000		
12.	Yard Hydrants	N/A	N/A	N/A
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	10.37.5.2		
13.	Pumping Arrangements			
	Ground Level Ground Level Ground Level	N/A	N/A	N/A
	 Discharge of main Pump Head of Main pump 	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	Jockey pump headStandby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	> Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	92 SEE A *********************************	• • • • • • • • • • • • • • • • • • • •		
	> Pump House Access	450 LPM	Provided	MR
	 Terrace level Discharge of pump 	40 M	Provided	MR
	> Head of the pump	Required	Provided	MR
	> Power Supply	Required	Provided	MR
	> Auto Starting of pump	Kequired	1.07123	
	S. S. Gabting			
14.	Captive Water Storage for fire fighting	N/A	N/A	N/A
	 Underground tank capacity Draw-off connection Fire service inlet 	N/A	N/A	N/A
		N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
1	 Overhead Tank capacity 	10,000 Ltrs	Provided	MR
		Required	Provided	MR
15.	Exit Signage.	Required	micottomentiation	

				(No Lift)					
5.	Provision of Lifts.	N/A	N/A	N/A					
	Pressurization of Lift Shaft Pressurization of Lift lobby	N/A	N/A	N/A					
	Pressurization of Lift lobby Communication In lift Car	N/A	N/A	N/A					
	 Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A					
		N/A	N/A	N/A					
24		N/A	N/A	N/A					
7.	VIII III	andby power supply							
18.	Refuge Area.	N/A	N/A	N/A					
	> Total Area	N/A	N/A	N/A					
	> Location	N/A	IN/A	374005254					
19.	Fire Control Room	N/A							
12.61	Detector System Panel	N/A	N/A N/A	N/A					
	Flow Switch Panel	N/A N/A	N/A	N/A					
	PA System Panel Page to selver	N/A	N/A	N/A					
	Battery backup Building Floor Plans	N/A	N/A	N/A					
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A					

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings communicated vide letter No. F.6/DFS/MS/School/2023/SZ/423 (A) dated 21/09/2023 have been complied.

Keeping in view the substantial compliance of the minimum standards of fire prevention and fire safety measures under Rule 35 of the Delhi Fire Service Rules 2010 it is recommended to grant Fire Safety Certificate.

Signature of the Inspecting Officer

Name

:-R.K.Yadav

Designation:-ADO(JKP)

DO (South West)

10/1/24

(FO (52)

10 tol 3024

Anys KN