

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/Hospital/2024/SZ/61

Dated: 30/.01./2024

## FIRE SAFETY CERTIFICATE

Certified that the Rose walk Healthcare Pvt Ltd located at N-88, Panchsheel Park, New Delhi 110017 comprised of Basements, Ground plus three upper floors owner/occupied by Rose walk Healthcare Pvt Ltd was issued FSC by this department vide letter No. F6/DFS/MS/2020/SZ/390 dated 29/09/2020. The premise was re-inspected by the officer concerned of this department on 18.01.2024 in the presence of Mr. Kuldeep Sharma and found deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy Group C "Institutional (Hospital)" with effect 30/01/2024 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued 30 01 /2024 at New Delhi by

DIRECTOR

**DELHI FIRE SERVICE** 

Copy to: -

of m

- 1. The Authorized Signatory, Rose walk Healthcare Pvt Ltd at N-88, Panchsheel Park, New Delhi 110017
- 2. The Executive Engineer (Bldg) MCD, Aurobindo Marg Green Park, New Delhi 110016

## Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting system.

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. The basement shall be used as per the provisions of UBBL /NBC Part- IV.

- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL- 2016), if any.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.
- 8. Temporary Structure at terrace found sealed



	INSPECTION	ON REPORT	2017/2015/10-1		
1	Name & Address of the Building	Rose walk Healthcare Pvt Ltd at N-88, Panchsheel Park, New Delhi 110017			
2	Type of Occupancy	Institutional building, "Group-C" (Hospital)			
3	Building Comprised of	Basement Ground + 03 upper floors			
4	Type of Case	Renewal			
5	Details of Previous NOC	F6/DFS/MS/2020/SZ/390 dated 29/09/2020			
6	Fire Safety Directives Letter No	Nil			
7	Date of Inspection	18/01/2024			
8	Name of the Inspecting Officers	DO (South)			
9	Name & Designation of Officers from the building side	Mr. Kuldeep Sharma			
10	Year of construction	2023			
11	Applicant letter No.	Outdoor diary no 10956 dated 18/12/2023			
No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	requirements	Provided at Site	Remarks MR/NMI	
1	Access to Building.	*			
İ	Road width	06 mtr	45 mtr	MR	
	Gate width	4.5 mtr	4.5 mtr	MR	
	Width of internal road	-NA-	NA	-NA-	
2	Number, width, type & arrangement of exits.				
ne m. m.	a) Number of Staircase	3,000	CALLEY Y		
	> Upper floors.	02 Nos	Provided	MR	
	> Basement floor.	02 Nos	Provided	MR	
56	b) Width of Staircase	0 . 0 . 60	2	3.00	
70.7 71.1 140.2	> Upper floors	2 mtr & 1.50mtr	2 mtr & 1.50mtr	MR MR	
	> Basement floor	2 mtr & 1.50mtr	2 mtr & 1.50mtr	1. MK	
	c) Protection of exits	Dawier I	D 11-1	1 Am	
	➤ Fire check door	Required	Provided	MR	
	> Pressurization	-NA-	-NA-	-NA-	
100 H	d) No. of continuous staircase to terrace	Required	Provided	MR	
	e) Width of corridor	2.4 mtr	Provided	MR	
	f) Door size	2m/1.25m & 1m	2m/1.25m & 1m	MR	
3	Compartmentation.	Control to the Au-	The street district	1 22	
	Fire check door.	Required	Provided	MR	
	<ul> <li>Sealing of electrical shafts.</li> </ul>	Required	Provided	MR	
	Fire rating of shaft door.	-NA-	-NA-	-NA-	
	Water curtain	-NA-	-NA-	-NA-	
	Fire dampers.	-NA-	-NA-	-NA-	
4.	Smoke Management system.		Kath Stephens	1.61	
	Basement	12 ACPH	Provided	MR	
	Upper floors	12 ACPH	Provided	MR	
5.	Fire Extinguishers.	aridot (bit im	Parameter B.		
	Total numbers	Required	30 Nos	MR	
in.	Types	ISI marked	ABC & Co2	MR	
	ISI Marking	Required	Provided	MR	
6.	First Aid Hose Reels.		the printing		
<u> </u>	Total numbers on each floor.	01 Nos at each	Provided	MR	
7-	Length of hose-reel hose	30m	Provided	MR	
10	Nozzle Diameter	5mm	Provided	MR	
7	The state of the s				
	Type of detectors     Location of Main Panel	Required	Smoke / Heat	MR	
	a Location of Main Panel				

	T	-NA-	-NA-	-NA
	Location of Repeater Panel	Required	Provided	MR
	Alternate source of power	Required	All Areas	MR
•	Hooter's location		Provided	MR
8.	MOEFA	Required -NA-	-NA-	-NA-
9. 10.	Public Address System	-IVA-	31 845	
10.	Automatic Sprinkler System     Basement	Required	Provided	MR
		-NA-	-NA-	-NA-
	Upper floors     Sprinkler shows false spiling	-NA-	-NA-	-NA-
11.	Sprinkler above false ceiling     Internal Hydrants.	7 13 20 0	A THE PARTY OF THE SERVICE	
11.	Size of Riser/Down-comer	100 mm	Provided	MR
	Number of Hydrant per floor	01 Nos	Provided	MR
	Hose box.	01 Nos	Provided	MR
12.	Yard Hydrants.	OTTOS		
	Total number of hydrants.	03 Nos	Provided	MR
	Hose box.	03 Nos	Provided	MR
	70000000000000000000000000000000000000	03 1408	Tioridea	1 1 1 2 2 2 2
13.	Pumping arrangements.		- Albertania	
	Ground Level	I COO T DV C	Provided	MR
	Discharge of main pump.	1620 LPM	Provided	MR
	➤ Head of main pump.	65 mtr		MR
	Number of main pumps.	01 No	Provided	
	➤ Jockey Pump output.	180 LPM	Provided	MR
	➤ Jockey Pump head.	70 mtr	Provided	MR
	Standby Pump output.	1620 LPM	Provided	MR
	➤ Standby Pump head.	65 mtr	Provided	MR
	Auto Starting/Manual Stopping.	Required	Provided	MR
	Pump house access.	Required	Provided	MR
	Terrace Level			
	Discharge of pump.	-NA-	-NA-	-NA-
	➤ Head of pump.	-NA-	-NA-	-NA-
	➤ Power supply.	-NA-	-NA-	-NA-
	> Auto starting of pump.	-NA-	-NA-	-NA-
14.	Captive water storage for fire fighting.	1.00.000.7.	Provided	MR
	Underground tank capacity.	1,00,000 Ltrs Required	Provided	MR
	> Draw-off connection.	Required	Provided	MR
	<ul> <li>Fire Service Inlet.</li> <li>Access to tank.</li> </ul>	Required	Provided	MR
	Overhead tank capacity.	10,000 Ltrs	Provided	MR
15.	Exit Signage.	Required	Provided Provided	MR
16.	Provision of Lifts.		Terlander x	
10.	Pressurization of lift shaft.	Required	Provided	MR
	Pressurization of lift lobby.	Required	Provided	MR
	Communication in lift car.	Required	Provided	MR
	Fireman's switch.	Required	Provided	MR
	Lift signage.	Required	Required	MR
17.	Standby Power Supply	Required	Provided (DG Set)	MR
18.	Refuge Area		NY 4	NIA
-/	Total area	-NA-	-NA-	-NA-
	Location	-NA-	-NA-	-NA-
19.	Fire Control Room.		- 1 2 - 1	274
	Detector system panel.	-NA-	-NA-	-NA-
	Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel.	-NA-	-NA-	-NA-

त्सव 9

नादी <sub>का</sub> समृत महोत्सव Battery backup. -NA--NA--NA-Building floor plan. -NA--NA--NA-Special Fire Protection System for the Required LT, HT & MR Protection of special Risk, if any. Transformers provided with Co2 flooding

Note: Temporary Structure at terrace level found sealed (Photo enclosed)

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued &

communicated by this department vide letter of even no 4458 dated 11/12/2023.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/2020/SZ/390 dated 29/09/2020, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspection Office Name: Sh. Manoj Sharma

Design: DO (South)

CFO (HO)