

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001



No F 6 / DFS / MS /Motel/ 2024 / WZ / 60

FIRE SAFETY CERTIFICATE

Dated 30/01/2024

Certified that the M/s Sydney Grand Hotel and Resort & Just Chill Water and Fun Park, Village Singhola, Main G.T.K. Road, Delhi-110040 comprised of Basement (Storage), Ground floor (Restaurant and 15 Guest Rooms) and First Floor (13 Guest Rooms) owned/ occupied by M/s Sydney Grand Hotel and Resort and Just Chill Water and Fun Park was issued fire safety certificate vide letter no. F6/DFS/MS/Motel/2021/WZ/86 dated 02/02/2021 & Corrigendum letter No. F6/DFS/MS/2021/WZ/552 dated 08/03/2021. The building was re-inspected by the officer concerned of this department on 22.01.2024 in the presence of Sh. Om Singh and found that all the fire prevention and fire safety arrangements as provided in the building in good working condition. The building have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy under Mixed ('Residential/ Motel' & 'Assembly/ Water and Fun Park') with effect from . 30 . 21.20.24... Valid up to 31/03/2027 in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on .. So. . ol. 2024 at New Delhi by

(Attal Garg) Director

Ph. 011-23414000

ole a

Copy to:-

- M/s Sydney Grand Hotel and Resort & Just Chill Water and Fun Park, Village Singhola, G.T. Karnal Road, Delhi-40.
- MHA Portal ID No. 2024011000296 dated 10/01/2024.

Conditions for the validity of Fire Safety Certificate:

- All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- The trained fire fighting staff should be available round the clock.
- Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>www.dfs.Delhigovt.nic.in</u>
- All the means of escape shall be kept free of any obstruction all the time to evacuate the
 occupant, in a safe manner, in the event of emergency.

INSPECTION REPORT

1. Name & address of the building :

M/s Sydney Grand Hotel and Resort & Just Chill Water and fun park, at

Village Singhola, Main G.T.K. Road, Delhi-40.

2. Type of Occupancy

: Mixed ('Residential/Motel' & 'Assembly/Water and fun park')

: Basement, Ground Floor and First Floor.

Building Comprised

: Renewal

Type of Case

Deta is of previous NOC

: F6/DFS/MS/Motel/2021/WZ/86 dated 02/02/2021

Fire Safety directives letter No

: F 6/DFS/MS/BP/2007/383 dated 07/02/2007

Date of inspection

: 22.01.2024

Name of the Inspecting Officers

: R.K. Sinha, ADO/BW

9. Name and designation of officers

from the building side

: Sh. Om Singh

9. Year of Construction

: 2007

10. Applicant's letter No.

: MHA ID No. 2024011000296 dated 10/01/2024

	Minimum Standards on fire prevention a fire safety U/R 33	NBC/ BBL Requirement	Provided at site	Remarks MR/NMR			
1	Access to building						
	Road width	09m	09m	MR			
	Gate width Width of internal road	05m	05m	MR			
	Note that the second se	NA NA	NA	NA			
Number, Width, Type & Arrangement of Exits							
	a. Number of staircases	No. of					
	Upper Floors	03	Provided	MR			
	Basements	03	Provided	MR			
	b. Width of staircases			13,			
	Upper Floors Basements	1.25 m	Provided	MR			
		1.25 m	Provided	MR			
	c. Protection of exits						
	Fire check door	Required	Provided	MR			
	Pressurization	NA	NA	NA.			
	d. No. of continuous staircases to terrace	Required	Provided	MR			
	e. Width of Corridor	Required	Provided	MR			
	f. Door Size	1.0m	1.0m	MR			
Compartmentation.							
	Fire check door	Required	Provided	MR			
	Sealing of electrical shafts	Required	Provided	MR			
	• Fire Rating of shaft door	Required	Provided	MR			
	Water Curtain Fire Dampers	Required	Provided	MR			
4		Required	Provided	MR			
	Smoke Management System.		1				
	Basements	Required		, D			
	Upper floors		Provided	MR			
		Required	Provided	MR			

11/	
46	
	46

	N-46					
	Total numbers	14 nos	Provided ABC	MR		
	 Types 	ABC & Co2	2450,30	MR		
	ISI marking	Yes	Yes	I WIK		
	First-Aid Hose Reels.					
-	Total numbers on each floor	01	Provided	MR		
	Length of hose reel hose	30m	30m	MR		
	Nozzle diameter	5mm	5mm	MR		
			MANAGE TO SERVICE TO S			
	Automatic fire detection and alarming system		Provided	MR		
	Type of detectors	Smoke/Heat	Provided	MR		
	Location of Main Panel	GF	NA	NA		
		NA	WANGE	MR		
	Location of Repeater Panel	Required	Provided			
	Alternate source of power	Required	Provided	MR		
	Hooters' Location		Provided	MR		
3	MOEFA	Required Required	Provided	MR		
)	Public Address System.	Requires	2020/X/9140			
0	Automatic Sprinkler System.		Provided	MR		
	Basement	Required	Provided	MR		
	Upper Floor	Required	W-189/W-1997	1000		
	Sprinkler above false ceiling	Required	Provided	MR		
1	Internal Hydrants					
	Size of riser/down-comer	100 mm	Provided	MR		
	 Number of hydrants per floor 	02	Provided	MR		
	Hose Box	02	Provided	MR		
12	Yard Hydrants.					
	Total number of hydrants	06	Provided	MR		
	Hose Box	06	Provided	MR		
13	Pumping Arrangements.					
	Ground Level Discharge of main Popper	1620 lpm	Provided	MR		
	 ➢ Discharge of main Pump ➢ Head of Main pump 	40m	Provided	MR		
	> Number of main pumps	3	Provided	MR		
	Jockey Pump out put	180 lpm	Provided	MR		
	> Jockey pump head	40 m	Provided	MR		
	Standby Pump out put	1620 lpm	Provided	MR		
	> Standby Pump Head	40 m	Provided	MR		
	> Auto Starting/ Manual stopping	SISSESS.	2010974374278344			
	> Pump House Access	Required	Provided	MR		
	Terrace level Discharge of pump	0001	000 1	N/D		
	Head of the pump	900 lpm	900 lpm	MR		
	> Power Supply	40m	40m	MR		
	> Auto Starting of pump	Required	Provided	MR		
	2	Required	Provided	MR		
4	Captive Water Storage for fire fighting.					
	Underground tank capacity	1,00,000 ltr.	Provided	MR		
	A-Sec. 1947 - December 201 On the \$1000 - 1100 - 1	1,00,000 14.	11011404	HATTE		

_

1		1	10-47		
1	13	inlet	NA	NA	NA.
到		Fire service inlet Access to tank	NA	NA	NA
$\backslash \widehat{\ \ } \backslash$		Overhead Tank capacity	10,000 ltrs	Provided	MR
كر			Required	Provided	MR
1	12	ignage.			-
	16 Provision of Lifts.				
1	0		N/A	N/A	N/A
1	•	Pressurization of Lift Shaft Pressurization of Lift lobby	N/A	N/A	N/A
1	•	Communication In lift Car	NA	NA	NA
		Fireman's Grounding Switch	NA	NA	NA
1	1.	Lift Signage	NA	NA	NA
		Elit organization	Required	125 KVA	MR
17	Standby	power supply	Roden		
18	Refuge Area.				N/A
			N/A	N/A	N/A
	52	Total Area	N/A	N/A	N/A
	350 157	Location			
19	Fire Con	trol Room		NA	NA
		Detector System Panel	NA		NA
	1		NA	NA	
		Flow Switch Panel PA System Panel	NA	NA	NA
		Batter backup	NA	NA	NA
		Building Floor Plans	NA NA	NA	NA
			The second secon	NA	NA
1/1	-	Protection Systems for of special Risks, if any:	NA		

The fire protection systems provided in the building were tested/ checked and found

Keeping in view of deemed compliance of the minimum standards on fire prevention and functional at the time of inspection. fire safety required under the rules it is recommended to renew the Fire Safety Certificate issued vide letter no. F6/DFS/MS/Motel/2021/WZ/86 dated 02/02/2021 under rule 37 of the Delhi Fire 800 3W 127

Service Rules, 2010.

Signature of the inspecting officer

Name: Rajeev Kumar Sinha

Designation: ADO/BW