

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2024/GH/ 15

Dated 29/01/2024

FIRE SAFETY CERTIFICATE

Certified that M/s Globus Suites located at A-82, Gujrawala Town, Part-I, Main G.T. Karnal Road, Delhi-110009 comprised of basement, ground & 03 upper floors but guest house running at first floor, second floor & third floor only owned/occupied by M/s Globus Suite was issued fire safety certificate vide letter no. F6/DFS/MS/2021/WZ/GH/42 dated 27.01.2021. The premises was inspected by the officer concerned of Fire Service on 16.1.2024 in the presence of Sh. Parmeet Singh Anand and observed that all the fire prevention & fire safety arrangements as provided in the premises found in good working condition The premises have therefore, deemed complied with the requirement under rule 33 of Delhi Fire Service Rules, 2010 and the building is fit for occupancy Class A-1 Residential (Rooming & Lodging) for first, second & third floor with 28 guest rooms only with effect from 24-01-20-24- for a period of valid up to 31.03.2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on .29 01 2-24... at New Delhi by

Director

Ph: 011-23414000

Copy to:-

1. The Owner, M/s Globus Suite located at A-82, Gujrawala Town, Part-I, Main G.T. Karnal Road, Delhi-110009.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non-functional fire safety measure shall be at the responsibility of the management.

3. The trained firefighting staff should be available round the clock.

4. Any deviation with regard to the construction etc. shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is WWW.dfs.Delhigovt.nic.in
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

INSPECTION REPORT

Name & address of the building

: Globus Suites at A-82, Gujrawala Town, Part-1, G.T.K Road, Delhi-110009.

2. Type of Occupancy

: Residential (Lodging house)

3. Composition of building

: Basement, Ground & 03 upper floors but guest house running at 1^{st} , 2^{nd} & 3^{rd}

Floor with 28 guest rooms only, basement & ground floor other property

4. Type of Case

: Renewal

5. Details of previous NOC

: F6/DFS/MS/2021/WZ/G11/42 dated: 29.01.2021

6. Fire Safety directives letter No

: Nil

7. Date of inspection

: 16.01.2024

8. Name of the Inspecting Officers

: ADO (RN)

9. Name and designation of officers

from the building side

: Sh. Parmeet Singh Anand

10. Year of Construction

: 2009

	Minimum Standards on fire prevention and fire safety U/R 33	UBBL/NBC Part- IV Requirements	Provided at site	Remarks MR/NMI		
	Access to building					
	Road width	06m	Provided	MR		
	Gate width	4.5m	Directly Accessible	MR		
	Width of internal road	NA	NA	NΛ		
	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	• Upper Floors	02	02	MR		
	Easements	NA	NA NA	NA		
	b. Width of staircases	The Table				
	Upper Floors	1.50m	02 nos. of 1.50m	MR		
	• Easements	NA	NA	NA		
	c. Protection of exits					
	Fire check door	Required	Provided	MR		
7	Pressurization	NA	NA	NΛ		
	d. No. of continuous staircases to terrace	02	02	MR		
	e. Width of Corridor	Required	Provided	MR		
	f. Door Size	01m	01m	MR		
	Compartmentation.					
	Fre check door	NA	NA	NA		
	Sealing of electrical shafts	NA	NA	NA		
	Fire Rating of shaft door	NΛ	NA	NΛ		
	Water Curtain	NA	NA	NΛ		
	Fire Dampers	NA	NA	NΛ		
	Smoke Management System.					

	Basements	NA NA	NA				
	Upper floors	Required	Provided	2-			
-	Fire Extinguishers						
_		06nos	08nos	MR			
	Total numbers Trans	ABC & WCo2	ABC - 8	MR			
	Types ISI marking	Yes	Yes	MR			
-	First-Aid Hose Reels.						
		01	01	MR			
	Total numbers on each floor		30m	MR			
	Length of hose reel hose	30m		MR			
	Nozzle diameter	5mm	5mm				
	Automatic fire detection and alarming system.						
	Type of detectors	Smoke/Heat	Smoke/Heat (carbon monoxide)	MR			
	Location of Main Panel	(carbon monoxide) Required	Provided	MR			
	Location of Repeater Panel	NA	NA	NΛ			
	Alternate source of power	NA NA	NA	NA			
	Ilooters' Location	NA NA	NA	NA			
	MOEFA	Required	Provided	MR			
	Public Address System.	NA	NA	NA			
	Automatic Sprinkler System.						
	8	NA	NA.	NA			
	Basement	NA NA	NA	NΛ			
	Upper Floor			NA			
	Sprinkler above false ceiling	NΛ	NA	100			
	Internal Hydrants						
Ì	Size of riser/down-comer	100mm	100mm	MR			
	 Number of hydrants per floor 	01	01	MR			
	Hose Box	01	01	MR			
	Yard Hydrants.						
Ī	 Total number of hydrants 	NΛ	NA	NA			
1	Hose Box	NA	NA	NA			
+	Pumping Arrangements.						
1	Ground Level						
	> Discharge of main Pump	N/A	N/A	N/A			
	> Head of Main pump			(EOSISSE)			
	➤ Number of main pumps	N/A	N/A	N/A			
	➤ Jockey Pump out put	N/A	N/A	N/A			
	 Jockey pump head 	N/A	N/A	N/A			
	➤ Standby Pump out put	N/A	N/A	N/A			
	 Standby Pump Head 	N/A	N/A	N/A			
	> Auto Starting/ Manual stopping	N/A	N/A	N/A			
	➤ Pump House Access	N/A	N/A	N/A			
	Terrace level						
	Discharge of pump	450 LPM	450 LPM	MR			
		40m	40n	MR			

				· · · · · · · · · · · · · · · · · · ·				
T		> Power Supply	Required	Provided	MR			
		Auto Starting of pump	Required	Provided	MR			
4	Captive	tive Water Storage for firefighting.						
-		Underground tank capacity	NA	NA	NΛ			
	>	Draw-off connection	NΛ	NA	NA			
- 1	>	Fire service inlet	NΛ	NA	NΛ			
1	>	Access to tank	NΛ	NA	NΛ			
		Overhead Tank capacity	10,000 LTR	10,000 LTR	MR			
15	Exit Sig	nage.	Required	Provided	MR			
16	Provision of Lifts. 1.no Passenger lift							
	75.55.50 40.5	Pressurization of Lift Shaft	N/A	N/A	N/A			
		Pressurization of Lift lobby	N/A	N/A	N/A			
	•	Communication In lift Car	N/A	N/A	N/A			
		Fireman's Grounding Switch	Required	Provided	MR			
	•	Lift Signage	Required	Provided	MR			
17	Standh	y power supply	Required	Provided	MR			
18	Refuge Area.							
10	lemsessa.	14 - 1	N/A	N/A	N/A			
	^	Total Area Location	N/A	N/A	N/A			
19	Fire Control Room							
(27		Detector System Panel	N/A	· N/A	N/A			
			N/A	N/A	N/A			
		Flow Switch Panel	N/A	N/A	N/A			
		PA System Panel	N/A	N/A	N/A			
		Batter backup	N/A	N/A	N/A			
		Building Floor Plans			N/A			
20	Specia	l Fire Protection Systems for tion of special Risks, if any:	NΛ	NA	NΛ			

The fire protection systems provided in the building were tested/ checked and found in working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate issued vide this department letter of even no. F6/DFS/MS/2021/WZ/GH/42 dated 27.01.2021 under rule 37 of the Delhi

Fire Service Rules 2010.

Signature of the Inspecting Officer Name: - C.L. Meena

Designation: Asst. Div. Officer (RN)